

Dr. R. Stephen Green, Superintendent/CEO

Dr. Michael A. Erwin, Board Chair Mr. Marshall D. Orson, Vice Chair Mr. Diijon DaCosta Mrs. Allyson Gevertz Mr. Stan O. Jester Dr. Joyce Morley Mrs. Vickie B. Turner

July 25, 2019

Via Email to: John Heneghan < John@JKHeneghan.com>

Re: Open Records Request

Dear Mr. Heneghan:

The DeKalb County School District ("School District") has received your request, dated July 22, 2019, made pursuant to the Georgia Open Records Act, O.C.G.A. § 50-18-70, et seq. (the "Act"). You have requested the following records related to open work orders in schools in the Dunwoody Cluster:

This request includes, but is not limited to, all documents, notes, correspondence and memoranda evidencing the scope of the repair needed, and all communication and correspondence in whatever tangible medium between the DeKalb School System employees and /or contractors employed to repair and certify that such work orders were completed properly.

In accordance with O.C.G.A. § 50-18-71(b)(1)(A) and § 50-18-71(c)(1), the School District estimates it will take at least six business days and cost \$310.50 to produce the requested documents. In accordance with O.C.G.A. § 50-18-71(d), the School District will defer production of these records until you agree to pay the estimated cost shown below:

| Task | Cost | Units | Qty. | Cost |
|--|---------|-------|------|-----------|
| Produce all documents related to 27 open work orders | | | | |
| in schools in the Dunwoody Cluster | \$34.50 | Hours | 9 | \$ 310.50 |
| Total Estimated Cost | | | | \$ 310.50 |

Payment is due upon receipt of the records. Please advise or mail a copy of this invoice, along with a check or money order for the total estimated cost of \$ 310.50 made payable to:


DeKalb County Board of Education Attn: Audrey Qualls Office of Legal Affairs 1701 Mountain Industrial Blvd. Stone Mountain, GA. 30083 If we can provide further assistance, please contact our office.

Sincerely,

Audrey Qualls

Audrey Qualls





Report Criteria

Shop is **ELECTRICAL**, **FIRE SAFETY** or **GROUNDS**

last time we received mulch was September 2015.

Type is equal to Corrective

Department is ES - Austin Elementary Facility, ES - Chesnut Elementary Facility, ES - Dunwoody Elementary Facility, ES - Hightower Elementary Facility, ES - Kingsley Elementary Facility, ES - Vanderlyn Elementary Facility, HS - Dunwoody High Facility or MS - Peachtree Charter Middle Facility


| Work Order # | Reason | Asset ID | Parent Location | Shop Name | Requested | | | |
|---|---|----------------|-----------------------|----------------|--------------------------|--|--|--|
| (Site No | t Specified) | | | | | | | |
| (Site | Not Specified) > ES - Austin Elementary Facility | | | | | | | |
| 88693 | Lights Out needs a ballast U shaped bulb near the art room | AUSTIN ES - 1 | Elementary Schools | ELECTRICAL | 4/9/2019 8:35:00 AM | | | |
| 90735 | Lights Out needs ballast in the third grade hall in boys bathroom | AUSTIN ES - 1 | Elementary Schools | ELECTRICAL | 4/30/2019 9:10:00 AM | | | |
| 92107 | Lights Out over teachers desk needs a Ballast in room 126 | AUSTIN ES - 1 | Elementary Schools | ELECTRICAL | 5/6/2019 6:12:00 AM | | | |
| 98434 | Light Out in main hallway 2nd light from the head custodian office | AUSTIN ES - 1 | Elementary Schools | ELECTRICAL | 7/10/2019 11:30:00 AM | | | |
| 98524 | Miscellaneous need a ballast cover for a U Shaped fixure | AUSTIN ES - 1 | Elementary Schools | ELECTRICAL | 7/11/2019 1:29:00 PM | | | |
| 98803 | Miscellaneous Broken light switch in outside storage area. | AUSTIN ES - 1 | Elementary Schools | ELECTRICAL | 7/16/2019 9:14:00 AM | | | |
| ES - Aus | ES - Austin Elementary Facility - 6 Total: | | | | | | | |
| (Site Not Specified) > ES - Chesnut Elementary Facility | | | | | | | | |
| 59927 | Teachers parking lot light is out and we will need the bucket truck and trace the power problem. | CHESNUT ES - 1 | Elementary Schools | ELECTRICAL | 7/18/2018 8:31:00 AM | | | |
| 98686 | Main fire alarm panel battery needs changing | CHESNUT ES - 1 | Elementary Schools | FIRE SAFETY | 7/15/2019 8:23:00 AM | | | |
| ES - Che | esnut Elementary Facility - 2 Total: | | | | | | | |
| (Site | Not Specified) > ES - Dunwoody Elementary Facility | | | | | | | |
| 85652 | Deliver Material. Our playground is becoming more and more dangerous and unsafe for our students. The entire playground area needs mulch under and around the equipment. Some areas within are just exposed dirt no cushion for the little ones, in case of a fall. A work order request was placed last fall but no mulched was supplied or delivered. The | | Elementary Schools | GROUNDS | 3/13/2019 9:56:00 AM | | | |


| Work Order # | Reason | Asset ID | Parent Location | Shop Name | Requested | | | | | |
|---|--|---|--|----------------|--------------------------|--|--|--|--|--|
| 93289 | Miscellaneous. Deliver Material. Rubber playground mulch badly needed. This is another request for playground mulch. In reference to work order numbers 85652 which was closed recently without fulfillment, #45230, and many other requests. Our entire play equipment area needs this mulch in order to help protect our students in case of a fall. Please address. | DUNWOODY ES - GROUNDS - 1 | Dunwoody ES - 1 (Winward) | GROUNDS | 5/21/2019 10:19:00 AM | | | | | |
| 93699 | Lights Out in parking lot. 3 pole lights observed. Repair will require aerial (bucket) truck. | DUNWOODY ES - GROUNDS - 1 | Dunwoody ES - 1 (Winward) | ELECTRICAL | 5/28/2019 6:44:00 AM | | | | | |
| ES - Du | ES - Dunwoody Elementary Facility - 3 Total: | | | | | | | | | |
| (Site Not Specified) > ES - Hightower Elementary Facility | | | | | | | | | | |
| 89393 | Lights Out: A ballast is out in room 16. | HIGHTOWER ES - 1 | Elementary Schools | ELECTRICAL | 4/15/2019 5:36:00 PM | | | | | |
| 96262 | Lights Out: A LED light in the hallway by the cafeteria is out. It has water in it. | HIGHTOWER ES-HALLWAY | Hightower ES - 1 (Winward) | ELECTRICAL | 6/19/2019 3:42:00 PM | | | | | |
| ES - Hig | htower Elementary Facility - 2 Total: | | | | | | | | | |
| (Site | Not Specified) > ES - Kingsley Elementary Facility | | | | | | | | | |
| 86400 | Miscellaneous/ Our Administrators are requesting 6 Reserve signs in or staff parking lot. | KINGSLEY ES - 1 | Elementary Schools | GROUNDS | 3/22/2019 7:27:00 AM | | | | | |
| 98333 | Miscellaneous/ We need a TV taken down from one of our Special Ed classroom (108) | KINGSLEY ES - 1 | Elementary Schools | ELECTRICAL | 7/9/2019 9:43:00 AM | | | | | |
| 98804 | Lights Out/ Room 108 need 3 ballast replaced please | KINGSLEY ES - 1 | Elementary Schools | ELECTRICAL | 7/16/2019 9:18:00 AM | | | | | |
| 98854 | Lights Out/Our security lights are not working-per Fire Marshall | KINGSLEY ES - 1 | Elementary Schools | ELECTRICAL | 7/16/2019 2:08:00 PM | | | | | |
| 98855 | Exit Signs/ need to be hanged. | KINGSLEY ES - 1 | Elementary Schools | ELECTRICAL | 7/16/2019 2:12:00 PM | | | | | |
| ES - Kir | ngsley Elementary Facility - 5 Total: | | | | | | | | | |
| (Site | Not Specified) > ES - Vanderlyn Elementary Facility | | | | | | | | | |
| 92401 | The pole light in our back parking lot by the kitchen is out.92198 | VANDERLYN ES - 1 | Elementary Schools | ELECTRICAL | 5/9/2019 8:56:00 AM | | | | | |
| 95364 | We need a ballast replaced in the boy's bathroom in the gym. | VANDERLYN ES - 1 | Elementary Schools | ELECTRICAL | 6/6/2019 6:55:00 AM | | | | | |
| 96769 | We need the ballast replaced in a T-8 light fixture in the teacher work room. | VANDERLYN ES - 1 | Elementary Schools | ELECTRICAL | 6/27/2019 9:33:00 AM | | | | | |
| ES - Va | nderlyn Elementary Facility - 3 Total: | | | | | | | | | |
| (Site | Not Specified) > HS - Dunwoody High Facility | | | | | | | | | |
| 98734 | Standing Water Drain is stopped up behind the sheds at the end of the football field and is now almost into the buildings | DUNWOODY HS - 1 | High Schools | GROUNDS | 7/15/2019 1:48:00 PM | | | | | |
| 98978 | Need light bulbs for front hall. | DUNWOODY HS - 1 | High Schools | ELECTRICAL | 7/17/2019 3:08:49 PM | | | | | |
| 99055 | Miscellaneous need intention pond cleared out all trees cut down and grass cut. | DUNWOODY HS - 1 | High Schools | GROUNDS | 7/18/2019 10:33:00 AM | | | | | |
| HS - Du | nwoody High Facility - 3 Total: | | | | | | | | | |
| (Site | Not Specified) > MS - Peachtree Charter Middle Facility | | | | | | | | | |
| 85508 | Miscellaneous INeed Repair on the Gate out by The pods in The Back of the Trailers | PEACHTREE CHARTER MS - 1- GROUNDS | Peachtree Charter MS - 1 (Winward) | GROUNDS | 3/12/2019 10:43:00 AM | | | | | |
| 86942 | Lights Out Pole Lights out in the parking lot i have Six Light out i do Need repair onThem asap | PEACHTREE CHARTER MS - 1 | Middle Schools | ELECTRICAL | 3/25/2019 10:16:00 AM | | | | | |
| 96803 | Miscellaneous the Lights are not Working on the timer they are staying on in the School all day and night i need a electrician to Come out to Repair them | PEACHTREE CHARTER MS - 1 | Middle Schools | ELECTRICAL | 6/27/2019 3:35:00 PM | | | | | |
| 98372 | Reinstall concrete portion of pillar that has fallen in. | PEACHTREE CHARTER MS - 1 | Middle Schools | GROUNDS | 7/9/2019 4:04:07 PM | | | | | |
| 98747 | Alarm Systems: front lobby inside alarm panel and, outside gym lobby card access pad is n't working as well. Both needs fixing. Thank you! "very urgent" | PEACHTREE CHARTER MS - 1 | Middle Schools | FIRE SAFETY | 7/15/2019 3:15:00 PM | | | | | |
| 98828 | Requesting gate installation for both, back parking lot and, bus lane area too. | PEACHTREE CHARTER MS - 1 | Middle Schools | GROUNDS | 7/16/2019 12:24:00 PM | | | | | |
| 98832 | Having trouble in the fire alarm system. It needs to be rebooted. "Urgent" Thanks again! | PEACHTREE CHARTER MS - 1 | Middle Schools | FIRE SAFETY | 7/16/2019 12:32:00 PM | | | | | |
| | | | | | | | | | | |


| Work Order # | Reason | Asset ID | Parent Location | Shop Name | Requested |
|-----------------|---|---------------------------------------|--|------------------|--------------------------|
| 98882 | Kitchen Dish Machine has no power. No power/bad booster heater. Electrician for repairs. Thanks | PEACHTREE CHARTER MS-MAIN LEVEL | Peachtree Charter MS - 1 (Winward) | ELECTRICAL | 7/17/2019 6:10:51 AM |
| 99064 | when, entering on campus,the round about circle. The base of the light pole is leaning over. Also, a Do Not Enter sign leaning as well. | PEACHTREE CHARTER MS - 1 | Middle Schools | ELECTRICAL | 7/18/2019 11:08:00 AM |


MS - Peachtree Charter Middle Facility - 9 Total:


(Site Not Specified) - 33 Total:













































































Audrey Qualls (Legal Affairs) From:

John Heneghan
RE: Open Records request from DeKalb School System and request Code Compliance Inspections from Dunwoody via DeKalb Fire Marshal Subject:

Thursday, July 25, 2019 6:26:17 PM hunsady, July 25, 2019 6:26:17 PM Junwoody Cluster Work Orders -7-22-2019.pdf Junwoody Cluster Work Order History-7-22-2019.pdf Junwoody Cluster Work Orders ORA Response .pdf Attachments

Dear Mr. Heneghan,

Please find attached the open work orders requested in your email below. In regards to your further request for "all documents, notes, correspondence and memoranda evidencing the scope of the repair needed, and all communication and correspondence in whatever tangible medium between the DeKalb School System employees and /or contractors employed to repair and certify that such work orders were completed properly", please see the attached ORA Response.

If we can provide further assistance, please contact our office.

Thank you.

Audrey Qualls | Legal Records Specialist II

Office of Legal Affairs | DeKalb County School District

1701 Mountain Industrial Blvd | Stone Mountain, GA 30083-1027

Tel: 678.676.0203 | Fax: 678.676.0234 | audrey_k_qualls@dekalbschoolsga.org

From: Daniel Drake (DEPT OF FACILITIES & OPERATION)

Sent: Monday, July 22, 2019 6:20 AM To: Audrey Qualls (Legal Affairs)

Cc: Maria Marquez (DEPT OF FACILITIES & OPERATION)

Subject: Fwd: Open Records request from DeKalb School System and request Code Compliance Inspections from Dunwoody via DeKalb Fire Marshal

Audrey,

Please see ORR

-Dan

Mr. Daniel E Drake, PE Interim Chief Operations Officer (COO) DeKalb County School District 1780 Montreal Rd Tucker, Georgia 30084 678-676-1332 (telephone) 678-676-1469 (fax) daniel drake@dekalbschoolsga.org

From: John Heneghan < John@JKHeneghan.com>

Sent: Monday, July 22, 2019 12:16:51 AM

To: Sherry Johnson (Region I); Daniel Drake (DEPT OF FACILITIES & OPERATION); Richard Boyd (DEPT OF FACILITIES & OPERATION); ikcox@dekalbcountyga.gov; aburden@dekalbcountyga.gov; 'Richard McLeod'; 'Compliance'

Cc: 'John Heneghan'; Stan Jester (School Board Members); 'Jester, Nancy'; 'Council Members'; Eric Linton; dekalbfmo@dekalbcountyga.gov; Ann Culbreath (Austin Elementary); Veronica Williams (Chesnut Elementary); Priscilla Cole (Dunwoody High); Jennifer Sanders (Dunwoody Elementary School); Sheila Price (Hightower Elementary School); Melanie Pearch (Kingsley Elementary); Donnie Davis (Peachtree Middle)

Subject: Open Records request from DeKalb School System and request Code Compliance Inspections from Dunwoody via DeKalb Fire Marshal

Dear Ms. Johnson, Mr. Drake & Mr. Bovd.

I was reviewing the open work orders in DeKalb County Schools in which Dunwoody Residents regularly attend (minus the magnets and specials) and noted 27 work orders on the "Open Work Order spreadsheet dated July 16th" that was found on the <u>DeKalb County Facilities Maintenance website</u> that I believe could be violations of fire safety code.

I have copied down below the 27 work orders that I am interested in reviewing and pursuant to the Georgia Open Records Law (O.C.G.A § 50-18-70 et seq.) (the "Law"), you are hereby requested to provide in an electronic format via email or electronic transfer to all interested parties on this email the documents requested. This request for electronic documents includes the best known email addresses of the DeKalb County Fire Marshal, City of Dunwoody Code Compliance representatives and the Principals at each of the schools so that these important safety items can be corrected and reviewed prior to the first day of school. If electronic documents cannot be sent via email or electronic transfer, I request that they be made physically available for review and copying all files, records and other documents in the school systems possession that refer, reflect or relate to these 27 work orders. This request includes, but is not limited to, all documents, notes, correspondence and memoranda evidencing the scope of the repair needed, and all communication and correspondence in whatever tangible medium between the DeKalb School System employees and /or contractors employed to repair and certify that such work orders were completed properly. If this request is denied in whole or in part, I ask that you cite in writing the specific statutory exemption upon which you have relied, as required by law. I also ask that you release all separate portions of otherwise exempt material. Please waive any costs associated with this request, or first inform me of such costs as required by Georgia law. As you know, the Law requires a response by you within three business days of your receipt of this letter and provides sanctions for non-compliance. Should you have any questions, please do not hesitate to contact me at 678-491-8228 or John.Heneghan@dunwoodyga.gov

I understand that these are ongoing repair items that may not yet be repaired but due to the responsibilities of the City of Dunwoody sharing the responsibility of Fire Code compliance I would hope to track the documentation of these specific work orders to completion so that the Fire Marshal and the City can be assured that the proper repairs are made. Thanks

John Heneghan

Dunwoody City Council
4624 Buckley Court
Dunwoody, GA 30338
John.Heneghan@Dunwoodyga.gov

Dear DeKalb Fire Marshal Joseph Cox and Dunwoody Community Development Director Richard McLeod;

Per the above open records request to the DeKalb School System for work orders that I believe may violate fire code, I would like both the DeKalb Fire Marshal and the City of Dunwoody to thoroughly review the work order documents that return from the request; both the issues raised and eventually the repair documentation to assure compliance. These 27 items were just a small snapshot of the attached full list that shows many more requests that include HVAC issues, broken equipment & trash compactors, roof leaks and pest control. As the City of Dunwoody only has a small amount of oversight on Fire Safety on DeKalb School System property as per an MOU that the DeKalb Fire Marshal has inspection oversight, I would hope that the DeKalb Fire Marshal does a complete review of these issues and work performed to assure that it is all up to code and inspected. I would also hope that the files on the work order completely identify the proper qualified inspector for each trade that confirms each repair is up to building code.

As per the MOU, if the City of Dunwoody has joint responsibility for fire safety; it is the duty of the City to assure compliance therefore I am asking that this matter be given the full attention it deserves and our schools be fully inspected by the DeKalb County Fire Marshal assuring the community that the safety of the children is not compromised.

Please note that I am fully aware that Hightower is physically located outside the City of Dunwoody boundaries, but that being said Dunwoody's children attend this school and I am therefore concerned and want verification of safety from DeKalb.

Thanks

John

| Work Order | Department Name | Shop Name | Problem Name | ZoneName | Requested | Target |
|------------|--|-------------------|------------------|----------|------------|-----------|
| # | | | | | | Date |
| 70762 | CO - DeKalb County Schools System Wide | FIRE SAFETY | | | 1/10/2018 | |
| 98525 | ES - Austin Elementary Facility | HAZARDOUS | Bad Odor | Region 1 | 11/7/2019 | |
| 98822 | ES - Austin Elementary Facility | | Bad Odor | Region 1 | 16/07/2019 | |
| 92107 | ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 6/5/2019 | 5/11/2019 |
| 88693 | ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 9/4/2019 | |
| 98434 | ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 10/7/2019 | |
| 90735 | ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 30/04/2019 | 5/5/2019 |
| 98524 | ES - Austin Elementary Facility | ELECTRICAL | Miscellaneous | Region 1 | 11/7/2019 | |
| 98803 | ES - Austin Elementary Facility | ELECTRICAL | Miscellaneous | Region 1 | 16/07/2019 | |
| 98686 | ES - Chesnut Elementary Facility | FIRE SAFETY | Fire Alarm | Region 1 | 15/07/2019 | |
| 59927 | ES - Chesnut Elementary Facility | ELECTRICAL | | Region 1 | 18/07/2018 | |
| 93699 | ES - Dunwoody Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 28/05/2019 | 6/2/2019 |
| 89393 | ES - Hightower Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 15/04/2019 | |
| 96262 | ES - Hightower Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 19/06/2019 | |
| 88385 | ES - Hightower Elementary Facility | HAZARDOUS | | Region 1 | 2/4/2019 | 4/2/2019 |
| 98804 | ES - Kingsley Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 16/07/2019 | |
| 98333 | ES - Kingsley Elementary Facility | ELECTRICAL | Miscellaneous | Region 1 | 9/7/2019 | |
| 95364 | ES - Vanderlyn Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 6/6/2019 | 6/11/2019 |
| 92401 | ES - Vanderlyn Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 9/5/2019 | |
| 96769 | ES - Vanderlyn Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 27/06/2019 | 7/12/2019 |
| 98400 | HS - Dunwoody High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 1 | 10/7/2019 | |
| 98734 | HS - Dunwoody High Facility | GROUNDS | Standing Water | Region 1 | 15/07/2019 | |
| 98287 | HS - Dunwoody High Facility | FIRE SAFETY | | Region 1 | 9/7/2019 | |
| 98747 | MS - Peachtree Charter Middle Facility | FIRE SAFETY | Alarm Systems | Region 1 | 15/07/2019 | |
| 98832 | MS - Peachtree Charter Middle Facility | | Fire Alarm | Region 1 | 16/07/2019 | |
| 86942 | MS - Peachtree Charter Middle Facility | ELECTRICAL | Lights Out | Region 1 | 25/03/2019 | |
| 96803 | MS - Peachtree Charter Middle Facility | ELECTRICAL | Miscellaneous | Region 1 | 27/06/2019 | 7/2/2019 |

INTERGOVERNMENTAL AGREEMENT FOR THE PROVISION OF FIRE RESCUE SERVICES BETWEEN DEKALB COUNTY, GEORGIA and THE CITY OF DUNWOODY, GEORGIA

THIS INTERGOVERNMENTAL AGREEMENT, is entered into by and between DeKalb County, Georgia ("County") and the City of Dunwoody, Georgia ("City").

WHEREAS, DeKalb County, Georgia is a constitutionally created political subdivision of the State of Georgia; and

WHEREAS, the City of Dunwoody is a municipality created by the 2008 Georgia General Assembly pursuant to Senate Bill 82 (hereinafter referred to as "SB 82"); and

WHEREAS, SB 82 provides that the city of Dunwoody begins operations December 1, 2008 and Section 6.03(c) requires the County to "...provide within the territorial limits of the City all government services and functions which DeKalb County provided in 2008; and

WHEREAS, the residents of Dunwoody have paid the same taxes as paid by residents of unincorporated DeKalb County for 2008 and the payment of those county taxes entitles the City and its residents to be provided with the 2008 county governmental services and functions until December 31, 2008 without any further compensation from the City or its residents to the County; and

WHEREAS, this intergovernmental agreement therefore only becomes effective on the date that the City will begin paying for services as set forth in this Agreement; and

WHEREAS, the County and City desire to enter into an Intergovernmental Agreement for the County to provide fire rescue services within the boundaries of Dunwoody for a period of one year beginning January 1, 2009; and

WHEREAS, the County and the City further desire to establish the cost of fire rescue services to be provided by the County to the City pursuant to this Agreement; and

WHEREAS, the County and the City desire to maintain a mutually beneficial, efficient and cooperative relationship that will promote the interests of the citizens of both jurisdictions.

NOW THEREFORE, in consideration of the following mutual obligations, the County and City agree as follows:

ARTICLE 1 PURPOSE AND INTENT

The purpose of this Agreement is to provide fire rescue services within the City.

ARTICLE 2 DEFINITIONS

For the purposes of the Agreement, the following terms shall be defined as:

- 2.1 "Fire Chief" means the director of the DeKalb County Fire and Rescue department or designee.
- 2.2 "Fire Code" means (1) those applicable provisions of state law related to fire rescue services, including the state fire safety rules, the International Fire Code and (2) those applicable provisions of the Code of Dekalb County, Georgia related to fire rescue services including but not limited to chapter 12 of the Code of Dekalb County, Georgia and (3) those applicable provisions of the Ordinances of the City of Dunwoody, Georgia that may be enacted during the term of this Agreement related to fire rescue services.
- 2.2 "Fire prevention tax district" means the area of land in DeKalb County, Georgia that has been designated as the fire prevention tax district in which the County imposes and collects from the taxpayers in the district a separate fire tax for the purpose of defraying the cost of the County fire rescue services provided to the taxpayers in the district.
- 2.3 "Fire Rescue Services" means fire suppression, community risk reduction, fire protection, disaster mitigation, rescue, hazardous material response and emergency medical service transports service provided by County Fire and Rescue Department personnel.

ARTICLE 3 TERM OF AGREEMENT

The term of the Agreement is for one year, commencing January 1, 2009 at 0000 hours and concluding at 2400 hours on December 31, 2009. This Agreement shall automatically renew without further action by the City or County on January 1st of each succeeding year for an additional one (1) year for a total lifetime Agreement of fifty (50) years, unless previously terminated in accordance with the termination provisions of this Agreement. At the conclusion of this term, the City will be solely responsible for providing all fire rescue services within its boundaries, unless extended by mutual Agreement by both governing bodies. The parties agree that, as of that date, the County's obligation (pursuant to O.C.G.A. 36-31-8 and Section 6.03 of SB 82) to provide the services covered by this Agreement shall terminate, and that this provision constitutes the agreement for the assumption of these services by the City as contemplated by O.C.G.A. 36-31-8 and Section 6.03 of SB 82.

ARTICLE 4 COMPENSATION AND CONSIDERATION

- 4.1 For the fire rescue services to be rendered during the term of this Agreement, the City agrees that the County shall remain entitled to impose and collect the fire prevention district tax annually in the same manner and at the same rate that such tax is imposed and collected within the portion of the DeKalb fire prevention tax district that is located in unincorporated DeKalb County. The City agrees to remain within the DeKalb fire prevention tax district and nothing in this Agreement shall preclude the County's right to continue to collect DeKalb fire prevention district taxes from the residents of the City for all fire rescue services originating within the City of Dunwoody.
- 4.2 The City agrees that County remains entitled to impose, collect and retain all ambulance transport fees. Fees charged shall be equal to those imposed upon residents of unincorporated DeKalb County, whether in effect at the time of this agreement or approved by the DeKalb County Governing Authority at some future date. Nothing in this Agreement shall preclude the County's right to continue to collect such fees for ambulance transport calls originating from within the City of Dunwoody.

ARTICLE 5 FIRE CHIEF

The Fire Chief will direct and manage the daily fire rescue operations in the City and supervise the delivery of fire rescue services contracted for in this Agreement.

ARTICLE 6 SERVICES

- 6.1 During the term of this Agreement, the County shall provide the same fire rescue services to the City as are provided in unincorporated area of DeKalb County. Such fire rescue services shall equal or exceed the fire rescue services provided by the County in 2008 within the area that comprises the City. The County shall provide fire rescue services on a continual 24-hour per day basis. The County and the City intend to enter into mutual aid agreements, which shall govern the parties in case of emergencies requiring assistance from neighboring fire departments.
- 6.2 Response times in the City shall remain consistent with those response times in unincorporated DeKalb County. County-wide response reports will be provided by the Fire Chief if requested by the City Manager.
- 6.3 All emergency incidents within the City shall operate under the National Response Plan (NRP) utilizing the National Incident Management System (NIMS). During the term of this agreement, the City agrees that it will not adopt any ordinance that in any way amends, repeals or replaces the applicable fire rescue provisions of the Code of DeKalb County, Georgia, including but not limited to chapter 12 of the Code of DeKalb County, Georgia and any amendments thereto without the written consent of the Fire Chief. Such consent shall not be unreasonably withheld.

ARTICLE 7 EQUIPMENT

The County agrees to provide DeKalb County fire and rescue personnel assigned to work within the City with all necessary equipment and motor vehicles in connection with this Agreement in order to perform the agreed upon fire rescue services, in accordance with DeKalb County Fire and Rescue department policies and procedures. The County agrees to maintain said equipment and vehicles and to provide replacements as necessary during the term of the Agreement. All DeKalb County Fire and Rescue Officers assigned hereunder shall wear the uniform and insignia as issued and ordered by the DeKalb County Fire and Rescue Department.

ARTICLE 8 AUTHORITY TO ENFORCE THE LAW IN DUNWOODY

- 8.1 The Fire Chief shall designate the fire rescue officers to take an oath administered by an official authorized by the City of Dunwoody to administer oaths, as prescribed by O.C.G.A. §§ 45-3-1 and 45-3-10.1 prior to undertaking fire rescue duties pursuant to this Agreement to enforce the fire code.
- 8.2 Every fire and rescue officer of the County assigned to the City shall still be deemed to be a sworn officer of the County while performing the services, duties and responsibilities hereunder and is vested with the "police powers" of the County that are necessary to provide the fire rescue services within the scope of this Agreement.
- 8.3 The Fire Chief shall be and hereby is vested with the additional power to enforce the fire code, to make arrests or issue citations incident to the enforcement of the fire code, and to perform other tasks as are reasonable and necessary in the exercise of their powers. This vesting of additional powers to enforce the fire code is made for the sole and limited purpose of giving official and lawful status to the performance of fire rescue services provided by fire and rescue officers within the City of Dunwoody.
- 8.4 Fire and Rescue officers shall enforce the fire code and shall appear in the Municipal Court of the City of Dunwoody as necessary to prosecute cases made therein. The City further agrees to provide, at its own expense, citation books containing the printed Municipal Court information to the fire rescue officers working within the City.

ARTICLE 9 EMPLOYMENT STATUS

All County Fire and Rescue Department personnel operating in the City, as well as any other County personnel operating under this Agreement are and will continue to be employees of the County for all purposes, including but not limited to duties and responsibilities, employee benefits, grievance, payroll, pension, promotion, annual or sick leave, standards of performance, training, workers compensation and disciplinary functions. All County Fire and Rescue Department personnel operating in the City as well as any other sworn personnel assigned under this Agreement are and will continue to be part of the DeKalb County Fire and Rescue

Department command structure. Fire and rescue personnel are under the supervision of the DeKalb County Fire Chief.

ARTICLE 10 FIRE INSPECTION AND PREVENTION

- 10.1 The County shall also provide "fire inspection and prevention services" which include, but are not limited to, the following:
 - a. review of all interior finished, new structures, additions and renovation of all commercial buildings and multi-family buildings, whether existing or to be constructed in the City;
 - b. Reviewing plans for both new construction and renovations of existing structures;
 - c. Final inspections for all commercial and multi-family buildings;
 - d. Inspections for business licenses or change of occupancy;
 - e. Inspections required for setting occupancy loads;
 - f. Enforcement of fire lane and handicap parking regulations; and
 - g. Enforcement of the fire code.
- 10.2 The County shall be entitled to collect the plan review, permit and inspection fees in connection with commercial and multi-family buildings constructed or renovated in the City if such structures or plans are reviewed or inspected by the Fire and Rescue Department. Fees charged shall be equal to those imposed upon residents of unincorporated DeKalb County for similar permits, inspections and plan reviews, whether in effect at the time of this agreement or as approved by the DeKalb County Governing Authority at some future date.
- 10.3 Construction plans and accompanying documents for all buildings subject to the provisions of this Agreement shall be submitted to the Fire Chief. Interior finish work and minor building additions may make use of the Fire and Rescue department "walk through" process.
- 10.4 Following completion of final inspection of commercial and multi-family buildings by the Fire Chief:
 - a. The City shall not issue any Certificate of Occupancy without the express written approval of the Fire Chief.
 - b. The City shall issue the Certificate of Occupancy when the City is satisfied that the project has complied with all City requirements.
 - c. The City shall be responsible for notifying utilities companies in connection with the issuance of Certificates of Occupancy.
 - d. The issuance of the Certificate of Occupancy by the City shall in no way obligate the City to make any plan review or inspections of the building, and it is specifically agreed that the City shall have the right to rely upon the plan review and inspections performed by the Fire Chief.
- 10.5 Retaining walls, tents, signs, greenhouses, satellite dishes, Christmas tree lots, emission inspections stations, and similar projects or structures shall not be subject to the

provisions of this Agreement, and the City shall continue to issue permits and/or approvals for such projects.

- 10.6 Both the City personnel and the County Fire and Rescue officers are authorized to issue citations for violations of the fire code.
- 10.7 The City shall be responsible for inspections of all erosion control and site work on all projects within the City.
- 10.8 The City shall be responsible for enforcement of building code requirements and shall issue all citations necessary to prosecute any building code violations in the Municipal Court of Dunwoody.

ARTICLE 11 RECORDKEEPING AND REPORTING

The County Fire and Rescue Department is the central repository for all departmental records and makes available public records as defined by the Georgia Open Records Act, O.C.G.A. 50-18-70, *et seq.* During the term of this Agreement, the County will continue to maintain all reports relating to Fire and Rescue Department activity within the City. Except as limited by any provision of state or federal law, the City may request, review and access data and County records at a mutually agreed upon time to ensure compliance with this Agreement.

ARTICLE 12 CITY – COUNTY RELATIONS

The DeKalb County Fire Chief will notify the City Manager in the event of a significant fire rescue emergency situation within the City. The DeKalb County Fire Chief and City Manager shall designate what they consider "significant" by a memorandum. The County shall be the sole provider of services within the city that require sworn fire rescue personnel during the term of this Agreement.

ARTICLE 13 TRANSITION

The County and City agree that 90 days prior to the end date of this Agreement, the City Manager and Executive Assistant will meet and confer to effect a smooth transition.

ARTICLE 14 TERMINATION AND REMEDIES

14.1 The City may terminate this Agreement with or without cause by giving one hundred and eighty (180) days prior written notice to the County. If the City intends to terminate this Agreement for cause, the City must notify the County in writing, specifying the cause, extent and effective date of the termination. The County shall have thirty three (33) days after the date of the written notice from the City to cure the stated cause for termination.

- 14.2 On December 1, 2011 at 2400 hours, the parties agree that the County's obligation pursuant to O.C.G.A. 36-31-8 and Section 6.03 of SB 82 to provide the government functions and services described in this Agreement shall terminate as contemplated by O.C.G.A. 36-31-8 and Section 6.03 of SB 82.
- 14.3 Beginning December 2, 2011 at 0000 hours, the County may terminate this Agreement with or without cause by giving one hundred and eighty (180) days prior written notice to the City. If the County intends to terminate this Agreement for cause, the County must notify the City in writing, specifying the cause, extent and effective date of termination. The City shall have thirty three (33) days after the date of the written notice from the County to cure the stated cause for termination.
- 14.4 The parties reserve all available remedies afforded by law to enforce any term of condition of this Agreement.

ARTICLE 15 NOTICES

All required notices shall be given by first class mail, except that any notice of termination shall be mailed via U.S. Mail, return receipt requested. The parties agree to give each other non binding duplicate facsimile notice. Notices shall be addressed to the parties at the following addresses:

If to the County:

Richard Stogner, Executive Assistant 1300 Commerce Drive 6th Floor Decatur, Georgia 30030 404-371-2883, Office number 404-371-2116, Facsimile number

With a copy to:

William J. Linkous, III County Attorney 1300 Commerce Drive, 5th Floor Decatur, Georgia 30030 404-371-3011, Office number 404-371-3024, Facsimile number

If to the City:

City of Dunwoody

________, Georgia

Office number:

Facsimile number:

With a copy to:

Brian Anderson, City Attorney (Insert address, phone number and facsimile number)

ARTICLE 16 EXTENSION OF AGREEMENT

This Agreement may be extended at any time during the term by mutual written consent of both parties so long as such consent is approved by official action of the City Council and approved by official action of the County governing authority.

ARTICLE 17 NON-ASSIGNABILITY

Neither party shall assign any of the obligations or benefits of this Agreement.

ARTICLE 18 ENTIRE AGREEMENT

The parties acknowledge, one to the other, that the terms of this Agreement constitute the entire understanding and Agreement of the parties regarding the subject matter of the Agreement. This Agreement constitutes the entire understanding and agreement between the Parties concerning the subject matter of this Agreement, and supersedes all prior oral or written agreements or understandings. No representation oral or written not incorporated in this Agreement shall be binding upon the City or the County. All parties must sign any subsequent changes in the Agreement.

ARTICLE 19 SEVERABILITY, VENUE AND ENFORCEABILITY

If a court of competent jurisdiction renders any provision of this Agreement (or portion of a provision) to be invalid or otherwise unenforceable, that provision or portion of the provision will be severed and the remainder of this Agreement will continue in full force and effect as if the invalid provision or portion of the provision were not part of this Agreement. No action taken pursuant to this Agreement should be deemed to constitute a waiver of compliance with any representation, warranty, covenant or agreement contained in this Agreement and will not operate or be construed as a waiver of any subsequent breach, whether of a similar or dissimilar nature. This Agreement is governed by the laws of the state of Georgia without regard to conflicts of law principles thereof. Should any party institute suit concerning this Agreement, venue shall be in the Superior Court of DeKalb County, Georgia. Should any provision of this Agreement require judicial interpretation, it is agreed that the court interpreting or construing the same shall not apply a presumption that the terms hereof shall be more strictly construed against one party by reason of the rule of construction that a document is to be construed more strictly against the party who itself or through its agent prepared the same, it being agreed that the agents of all parties have participated in the preparation hereof.

ARTICLE 20 BINDING EFFECT

This Agreement shall inure to the benefit of, and be binding upon, the respective parties' successors.

ARTICLE 21 INDEMNITY

- 21.1 It is the intent of the parties to be covered under the auspices of any applicable immunity granted by law. Only to the extent permitted by law, shall the City defend, indemnify and hold harmless the County and its officers, employees, or agents from any and all liability, losses or damages, including attorneys' fees and costs of defense, which the County or its officers, employees, or agents may incur as a result of any claim, demand, suit, or cause of action or proceeding of any kind or nature arising out of, relating to, or resulting from the negligent performance of this Agreement by the City, its employees, officers and agents. The County shall promptly notify the City of each claim, cooperate with the City in the defense and resolution of each claim and not settle or otherwise dispose of the claim without the City's participation.
- 21.2 It is the intent of the parties to be covered under the auspices of any applicable immunity granted by law. Only to the extent permitted by law, shall the County defend, indemnify and hold harmless the City and its officers, employees, or agents from any and all liability, losses or damages, including attorneys' fees and costs of defense, which the City or its officers, employees, or agents may incur as a result of any claim, demand, suit, or cause of action or proceeding of any kind or nature arising out of, relating to, or resulting from the negligent performance of this Agreement by the County, its employees, officers, and agents. The City shall promptly notify the County of each claim, cooperate with the County in the defense and resolution of each claim and not settle or otherwise dispose of the claim without the County participation.
- 21.3 The indemnification provisions of this Agreement shall survive termination of this Agreement for any claims that may be filed after the termination date of the Agreement provided the claims are based upon actions that occurred during the term of this Agreement.

ARTICLE 22 COUNTERPARTS

This Agreement may be executed in several counterparts, each of which shall be an original, and all of which shall constitute but one and the same instrument.

IN WITNESS WHEREOF, the City and County have executed this Agreement through their duly authorized officers.

SIGNATURES APPEAR ON THE FOLLOWING PAGES

DEKALB COUNTY, GEORGIA

| By: | | (SEAL) | |
|--|-------------------------|------------------------|------|
| - | Vernon Jones | | |
| | Chief Executive Officer | | |
| | DeKalb County, Georgia | | |
| ATTI | EST: | | |
| | | | |
| | ael Bell | _ | |
| | fficio Clerk of the | | |
| | d of Commissioners of | | |
| DeKa | alb County, Georgia | | |
| APPF | ROVED AS TO FORM: | APPROVED AS TO SUBSTAN | ICE: |
| —————————————————————————————————————— | am J. Linkous, III | Richard Stogner | |
| | tv Attornev | Executive Assistant | |

SIGNATURES APPEAR ON THE FOLLOWING PAGE

CITY OF DUNWOODY, GEORGIA

| Ken Wright Mayor | Municipal Clerk | (SEAL) | | | |
|---------------------------------|----------------------------------|--------|--|--|--|
| Approved as to Form: | Approved as to Substance: | | | | |
| Brian Anderson City Attorney | Warren Hutmacher City Manager | | | | |



41 Perimeter Center East, Suite 250 Dunwoody, Georgia 30346 P (678) 382-6700 F (678) 382-6701 dunwoodyga.gov

<u>MEMORANDUM</u>

To: Mayor and City Council

From: Bill Riley, Assistant City Attorney

Date: May 8, 2017

Subject: Memorandum of Understanding Between the City of

Dunwoody and DeKalb County Board of Education

ITEM DESCRIPTION

Memorandum of Understanding Between the City of Dunwoody and DeKalb County Board of Education.

BACKGROUND

The following Memorandum of Understanding outlines the procedure for issuance of City of Dunwoody Certificates of Occupancy for DeKalb County Board of Education buildings.

Pursuant to our Intergovernmental Agreement with DeKalb County, the DeKalb County Fire Department will review, inspect and certify fire code compliance.

Pursuant to case law, the City will review, inspect and certify land disturbance compliance.

Pursuant to the City of Dunwoody / DeKalb County Board of Education Memorandum of Understanding, a registered engineer, retained by the Board, will design, inspect and certify all other aspects of construction permitting compliance.

The City will issue Certificates of Occupancy based on successful completion of the above actions.

RECOMMENDED ACTION

The City Attorney's Office recommends approval of the Memorandum of Understanding between the City of Dunwoody and DeKalb County Board of Education.

MEMORANDUM OF UNDERSTANDING

by and between

DEKALB COUNTY SCHOOL DISTRICT

and

CITY OF DUNWOODY, GEORGIA

FOR BUILDING PLAN REVIEW AND INSPECTION OF DEKALB COUNTY, GEORGIA SCHOOL DISTRICT'S CAPITAL AND FACILITIES IMPROVEMENT PROJECTS WITHIN THE CITY BOUNDARIES

The parties to this Memorandum of Understanding (MOU) are interested in serving the needs of the citizens of DeKalb County, Georgia and the City of Dunwoody, Georgia by providing efficient plan review and inspection services for all DeKalb County School District's Capital and Facilities Improvement Projects located within the City of Dunwoody, including but not limited to, new schools, building additions, facilities modifications, portable classroom installations, and facility maintenance improvements. By signing this MOU, both DeKalb County School District ("DCSD") and the City of Dunwoody, Georgia ("City") agree to the following:

1.

The City shall have the responsibility for site plan reviews and/or issuance of land disturbance permits. DCSD shall have the responsibility for building plan review and construction inspection authority for all capital and facilities improvement projects related to new schools, building additions, and other capital improvements, including but not limited to new facilities, facilities modifications, portable classroom installations and other facility maintenance improvements.

2.

DCSD shall engage the services of an authorized engineering and inspection services firm ("AE"; with credentials for construction inspection services) to perform building plan review and inspections for the above referenced projects, for compliance with State and County and applicable municipal codes, ordinances, and procedures, Georgia Department of Education requirements, and for conformance with technically sound engineering principles. It is understood that the AE shall direct and supervise technical support staff responsible for performing building plan review and inspection services for DCSD.

3.

The AE shall review the plans for compliance with applicable architectural, structural, electrical, heating, ventilation, air conditioning, plumbing, and energy codes and ordinances adopted by the state of Georgia, Georgia Department of Education and any other applicable codes or ordinances.

4

The DeKalb County Fire Marshal's Office ("Fire Marshal"), pursuant to the Intergovernmental Agreement for the Provision of First Rescue Services dated December 10, 2008 between the City and DeKalb County ("Fire IGA") shall conduct fire safety inspections and duties as provided in O.C.G.A § 25-2-12 *et seq.* Where applicable, DCSD will submit site plans to DeKalb County Fire Marshal and the City. The City will review site plans (where applicable) and when compliant, issue Land Disturbance Permits.

5.

The AE shall signify approval of plans for each project, by professionally stamping, signing, and dating these drawings prior to commencement of construction. DCSD shall submit a copy of the approved plans, signed and dated to the City.

6.

DCSD or its designee shall perform inspections as outlined in Paragraphs 2 and 3 and 4 above for conformance with the approved plans.

7.

The Fire Marshal, pursuant to the Fire Services IGA, shall to be responsible for periodic Fire Marshal inspections and any enforcement action where necessary. The City shall be responsible for periodic erosion control inspections and any enforcement action where necessary, including any erosion control measures for capital and facilities improvement projects and portable classroom installations constructed by DCSD.

8.

The inspections certifying compliance with the approved plans shall be accumulated/assembled and at the end of the project or as requested by City, shall be submitted to the City for City's review. The City will issue Certificate of Occupancy upon compliance.

9.

Upon request of DCSD and the satisfactory inspection of a DCSD facility by the Fire Marshal for compliance with State and local fire codes, the Fire Marshal shall be responsible for issuing a permit or other certificate to the effect that said building(s) is (are) in fire code compliance.

10.

This MOU shall continue in effect from its effective date, shall continue in effect for a term of five years (5) years, provided that the contract shall terminate absolutely every year as required by O.C.G.A. § 20-2-506, but shall automatically renew unless either party notifies the other in writing of its intent to terminate said MOU with at least 30 days' notice.

11.

This MOU constitutes the entire agreement between the parties as to all matters contained herein. All subsequent changes in this MOU must be in writing and signed by both parties.

IN WITNESS HEREOF, the City and DCSD have executed this Agreement through their duly authorized officers.

| | Approved: |
|---------------------------|--------------------------|
| | Denis L. Shortal, Mayor |
| | Approved as to Content: |
| | Eric Linton City Manager |
| ATTEST: | Approved as to Form: |
| Sharon Lowery, City Clerk | Office of City Attorney |

| Work Order # Department Name | Shop Name | Problem Name | ZoneName | Requested | Target Date |
|---|-----------------------------|-------------------|----------|------------|-------------|
| 98470 AF - Adams Stadium | GROUNDS | | Region 1 | 10/7/2019 | |
| 95262 AS - Doravile Admin | CARPENTRY | Miscellaneous | Region 1 | 4/6/2019 | 6/9/2019 |
| 96618 AS - Doravile Admin | CARPENTRY | Move Items | Region 1 | 25/06/2019 | |
| 71628 AS - Margaret Harris Complex | ROOF | Roof Leak | Region 1 | 11/10/2018 | |
| 72762 AS - Margaret Harris Complex | ROOF | Ceilings | Region 1 | 26/10/2018 | |
| 88724 AS - Margaret Harris Complex | ELECTRICAL | Lights Out | Region 1 | 9/4/2019 | |
| 89956 AS - Margaret Harris Complex | ROOF | Roof Leak | Region 1 | 22/04/2019 | |
| 93825 AS - Margaret Harris Complex | ELECTRICAL | Miscellaneous | Region 1 | 29/05/2019 | 6/3/2019 |
| 95538 AS - Margaret Harris Complex | ROOF | Roof Leak | Region 1 | 10/6/2019 | |
| 82698 EO - Warren Technical Chamblee | ELECTRICAL | Lights Out | Region 1 | 11/2/2019 | |
| 91117 EO - Warren Technical Chamblee | CARPENTRY | Floors | Region 1 | 1/5/2019 | 5/6/2019 |
| 98311 EO - Warren Technical Chamblee | HVAC | Miscellaneous | Region 1 | 9/7/2019 | |
| 98358 EO - Warren Technical Chamblee | PEST CONTROL | Pest | Region 1 | 9/7/2019 | |
| 85524 ES - Ashford Park Elementary Facility | GROUNDS | Miscellaneous | Region 1 | 12/3/2019 | |
| 85834 ES - Ashford Park Elementary Facility | ROOF | Water Leak | Region 1 | 15/03/2019 | |
| 89728 ES - Ashford Park Elementary Facility | ROOF | Water Leak | Region 1 | 19/04/2019 | |
| 92939 ES - Ashford Park Elementary Facility | ROOF | Water Leak | Region 1 | 16/05/2019 | |
| 93445 ES - Ashford Park Elementary Facility | WASTE MANAGEMENT | Recycling | Region 1 | 22/05/2019 | |
| 93732 ES - Ashford Park Elementary Facility | LOCKSMITH | Locks / Keys | Region 1 | 28/05/2019 | 6/2/2019 |
| 95581 ES - Ashford Park Elementary Facility | ROOF | Ceilings | Region 1 | 10/6/2019 | |
| 95582 ES - Ashford Park Elementary Facility | ROOF | Roof Leak | Region 1 | 10/6/2019 | |
| 95587 ES - Ashford Park Elementary Facility | ROOF | Roof Leak | Region 1 | 10/6/2019 | |
| 95589 ES - Ashford Park Elementary Facility | HVAC | Miscellaneous | Region 1 | 10/6/2019 | |
| 95590 ES - Ashford Park Elementary Facility | CARPENTRY | Floors | Region 1 | 10/6/2019 | |
| 95592 ES - Ashford Park Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 10/6/2019 | |
| 96320 ES - Ashford Park Elementary Facility | ROOF | Roof Leak | Region 1 | 20/06/2019 | |
| 98256 ES - Ashford Park Elementary Facility | HVAC | Room Too Hot | Region 1 | 8/7/2019 | |
| 98373 ES - Ashford Park Elementary Facility | ROOF | Ceilings | Region 1 | 9/7/2019 | |
| 98545 ES - Ashford Park Elementary Facility | PLUMBING | Water Leak | Region 1 | 11/7/2019 | |
| 98761 ES - Ashford Park Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 1 | 15/07/2019 | |
| 98762 ES - Ashford Park Elementary Facility | WASTE MANAGEMENT | Recycling | Region 1 | 15/07/2019 | |
| 62794 ES - Austin Elementary Facility | PAINTING / PRESSURE WASHING | | Region 1 | 6/8/2018 | 8/6/2018 |
| 82772 ES - Austin Elementary Facility | MECHANICAL EQUIPMENT | Miscellaneous | Region 1 | 12/2/2019 | |
| 88693 ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 9/4/2019 | |
| 89524 ES - Austin Elementary Facility | HVAC | | Region 1 | 17/04/2019 | |
| 90735 ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 30/04/2019 | 5/5/2019 |
| 92107 ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 6/5/2019 | 5/11/2019 |
| 94097 ES - Austin Elementary Facility | CARPENTRY | Doors | Region 1 | 31/05/2019 | |
| 95131 ES - Austin Elementary Facility | VENDOR | Miscellaneous | Region 1 | 3/6/2019 | 6/8/2019 |
| | | | | | |

| 95254 ES - Austin Elementary Facility | CARPENTRY | Doors | Region 1 | 4/6/2019 | 6/9/2019 |
|--|-----------------------------|------------------|----------|------------|-----------|
| 96708 ES - Austin Elementary Facility | CARPENTRY | Floors | Region 1 | 26/06/2019 | |
| 96755 ES - Austin Elementary Facility | PEST CONTROL | Pest | Region 1 | 27/06/2019 | 7/12/2019 |
| 98293 ES - Austin Elementary Facility | ROOF | Roof Leak | Region 1 | 9/7/2019 | |
| 98434 ES - Austin Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 10/7/2019 | |
| 98524 ES - Austin Elementary Facility | ELECTRICAL | Miscellaneous | Region 1 | 11/7/2019 | |
| 98525 ES - Austin Elementary Facility | HAZARDOUS | Bad Odor | Region 1 | 11/7/2019 | |
| 98733 ES - Austin Elementary Facility | HVAC | Room Too Hot | Region 1 | 15/07/2019 | |
| 98803 ES - Austin Elementary Facility | ELECTRICAL | Miscellaneous | Region 1 | 16/07/2019 | |
| 98822 ES - Austin Elementary Facility | | Bad Odor | Region 1 | 16/07/2019 | |
| 98823 ES - Austin Elementary Facility | | Roof Leak | Region 1 | 16/07/2019 | |
| 79068 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 4/1/2019 | |
| 80806 ES - Cary Reynolds Elementary Facility | PAINTING / PRESSURE WASHING | | Region 1 | 24/01/2019 | |
| 83317 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 21/02/2019 | |
| 84938 ES - Cary Reynolds Elementary Facility | CARPENTRY | Floors | Region 1 | 5/3/2019 | |
| 85043 ES - Cary Reynolds Elementary Facility | HVAC | Roof Leak | Region 1 | 6/3/2019 | |
| 85901 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 18/03/2019 | |
| 86009 ES - Cary Reynolds Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 1 | 19/03/2019 | |
| 87330 ES - Cary Reynolds Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 1 | 29/03/2019 | |
| 88757 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 9/4/2019 | |
| 89134 ES - Cary Reynolds Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 1 | 12/4/2019 | |
| 89347 ES - Cary Reynolds Elementary Facility | HVAC | Roof Leak | Region 1 | 15/04/2019 | |
| 89723 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 19/04/2019 | |
| 89726 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 19/04/2019 | |
| 90433 ES - Cary Reynolds Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 26/04/2019 | 5/1/2019 |
| 93518 ES - Cary Reynolds Elementary Facility | KITCHEN EQUIPMENT | Stove / Oven | Region 1 | 24/05/2019 | |
| 95713 ES - Cary Reynolds Elementary Facility | FIRE SAFETY | Fire Alarm | Region 1 | 11/6/2019 | |
| 96026 ES - Cary Reynolds Elementary Facility | CARPENTRY | Floors | Region 1 | 17/06/2019 | |
| 96027 ES - Cary Reynolds Elementary Facility | CARPENTRY | Floors | Region 1 | 17/06/2019 | |
| 96506 ES - Cary Reynolds Elementary Facility | CARPENTRY | Doors | Region 1 | 24/06/2019 | |
| 98203 ES - Cary Reynolds Elementary Facility | HVAC | | Region 1 | 8/7/2019 | |
| 98213 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 8/7/2019 | |
| 98745 ES - Cary Reynolds Elementary Facility | ROOF | Roof Leak | Region 1 | 15/07/2019 | |
| 59927 ES - Chesnut Elementary Facility | ELECTRICAL | | Region 1 | 18/07/2018 | |
| 93323 ES - Chesnut Elementary Facility | GLAZING | Broken Equipment | Region 1 | 21/05/2019 | |
| 98274 ES - Chesnut Elementary Facility | CARPENTRY | Doors | Region 1 | 8/7/2019 | |
| 98686 ES - Chesnut Elementary Facility | FIRE SAFETY | Fire Alarm | Region 1 | 15/07/2019 | |
| 72272 ES - Dresden Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 1 | 19/10/2018 | |
| 76287 ES - Dresden Elementary Facility | KITCHEN EQUIPMENT | Doors | Region 1 | 30/11/2018 | 12/1/2018 |
| 79271 ES - Dresden Elementary Facility | WAREHOUSE | Supplies Needed | Region 1 | 8/1/2019 | |
| 79271 ES - Dresden Elementary Facility | WAREHOUSE | Supplies Needed | Region 1 | 8/1/2019 | |

| 89417 ES - Dresden Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 1 | 16/04/2019 | |
|--|-----------------------------|-------------------|----------|------------|-----------|
| 89639 ES - Dresden Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 1 | 18/04/2019 | |
| 98446 ES - Dresden Elementary Facility | HVAC | Water Leak | Region 1 | 10/7/2019 | |
| 83110 ES - Dunwoody Elementary Facility | ROOF | Roof Leak | Region 1 | 19/02/2019 | |
| 85652 ES - Dunwoody Elementary Facility | GROUNDS | Deliver Material | Region 1 | 13/03/2019 | |
| 85654 ES - Dunwoody Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 1 | 13/03/2019 | |
| 92519 ES - Dunwoody Elementary Facility | HVAC | Room Too Hot | Region 1 | 10/5/2019 | |
| 93256 ES - Dunwoody Elementary Facility | KITCHEN EQUIPMENT | Stove / Oven | Region 1 | 21/05/2019 | |
| 93259 ES - Dunwoody Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 1 | 21/05/2019 | |
| 93289 ES - Dunwoody Elementary Facility | GROUNDS | Miscellaneous | Region 1 | 21/05/2019 | |
| 93699 ES - Dunwoody Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 28/05/2019 | 6/2/2019 |
| 93773 ES - Dunwoody Elementary Facility | HVAC | Room Too Hot | Region 1 | 28/05/2019 | 6/2/2019 |
| 94054 ES - Dunwoody Elementary Facility | VENDOR | | Region 1 | 31/05/2019 | 6/5/2019 |
| 98675 ES - Dunwoody Elementary Facility | PEST CONTROL | Pest | Region 1 | 15/07/2019 | -,-, |
| 98723 ES - Dunwoody Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 1 | 15/07/2019 | |
| 98728 ES - Dunwoody Elementary Facility | HVAC | Room Too Hot | Region 1 | 15/07/2019 | |
| 57586 ES - Hightower Elementary Facility | ROOF | | Region 1 | 14/06/2018 | |
| 64040 ES - Hightower Elementary Facility | ROOF | Roof Leak | Region 1 | 15/08/2018 | |
| 64932 ES - Hightower Elementary Facility | ROOF | Roof Leak | Region 1 | 23/08/2018 | |
| 69608 ES - Hightower Elementary Facility | ROOF | Roof Leak | Region 1 | 26/09/2018 | |
| 82439 ES - Hightower Elementary Facility | HVAC | Roof Leak | Region 1 | 6/2/2019 | |
| 87290 ES - Hightower Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 1 | 28/03/2019 | |
| 88385 ES - Hightower Elementary Facility | HAZARDOUS | · · | Region 1 | 2/4/2019 | 4/2/2019 |
| 89393 ES - Hightower Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 15/04/2019 | |
| 93300 ES - Hightower Elementary Facility | GLAZING | Broken Equipment | Region 1 | 21/05/2019 | |
| 96261 ES - Hightower Elementary Facility | CARPENTRY | Floors | Region 1 | 19/06/2019 | |
| 96262 ES - Hightower Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 19/06/2019 | |
| 96482 ES - Hightower Elementary Facility | HVAC | Room Too Hot | Region 1 | 24/06/2019 | |
| 98407 ES - Hightower Elementary Facility | HVAC | | Region 1 | 10/7/2019 | |
| 98408 ES - Hightower Elementary Facility | HVAC | | Region 1 | 10/7/2019 | |
| 83095 ES - Huntley Hills Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 19/02/2019 | |
| 85399 ES - Huntley Hills Elementary Facility | ELECTRICAL | | Region 1 | 11/3/2019 | 3/11/2019 |
| 89353 ES - Huntley Hills Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 15/04/2019 | |
| 90058 ES - Huntley Hills Elementary Facility | ENERGY MANAGEMENT | | Region 1 | 22/04/2019 | |
| 92895 ES - Huntley Hills Elementary Facility | HVAC | | Region 1 | 15/05/2019 | |
| 93186 ES - Huntley Hills Elementary Facility | HVAC | Room Too Hot | Region 1 | 20/05/2019 | |
| 94058 ES - Huntley Hills Elementary Facility | VENDOR | | Region 1 | 31/05/2019 | 6/5/2019 |
| 95144 ES - Huntley Hills Elementary Facility | CARPENTRY | Miscellaneous | Region 1 | 3/6/2019 | 6/8/2019 |
| 95707 ES - Huntley Hills Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 1 | 11/6/2019 | |
| 96016 ES - Huntley Hills Elementary Facility | GROUNDS | Miscellaneous | Region 1 | 17/06/2019 | |
| | | | - | | |

| 96034 ES - Huntley Hills Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 1 | 17/06/2019 | |
|---|-------------------|-------------------|----------|------------|-----------|
| 96266 ES - Huntley Hills Elementary Facility | PEST CONTROL | Pest | Region 1 | 19/06/2019 | |
| 96527 ES - Huntley Hills Elementary Facility | ELECTRICAL | Broken Equipment | Region 1 | 24/06/2019 | 7/12/2019 |
| 96534 ES - Huntley Hills Elementary Facility | HVAC | Room Too Hot | Region 1 | 24/06/2019 | 7/12/2019 |
| 96577 ES - Huntley Hills Elementary Facility | GROUNDS | Miscellaneous | Region 1 | 25/06/2019 | 7/12/2019 |
| 98666 ES - Huntley Hills Elementary Facility | HVAC | Room Too Hot | Region 1 | 15/07/2019 | |
| 85486 ES - John Robert Lewis Elementary Facility | HVAC | Miscellaneous | Region 1 | 12/3/2019 | |
| 89337 ES - John Robert Lewis Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 1 | 15/04/2019 | |
| 90261 ES - John Robert Lewis Elementary Facility | WASTE MANAGEMENT | Miscellaneous | Region 1 | 24/04/2019 | |
| 90704 ES - John Robert Lewis Elementary Facility | WASTE MANAGEMENT | Recycling | Region 1 | 30/04/2019 | 5/5/2019 |
| 90705 ES - John Robert Lewis Elementary Facility | WASTE MANAGEMENT | Miscellaneous | Region 1 | 30/04/2019 | 5/5/2019 |
| 92284 ES - John Robert Lewis Elementary Facility | WAREHOUSE | Compactor / Trash | Region 1 | 7/5/2019 | 5/12/2019 |
| 95273 ES - John Robert Lewis Elementary Facility | PEST CONTROL | Pest | Region 1 | 4/6/2019 | 6/9/2019 |
| 95600 ES - John Robert Lewis Elementary Facility | GROUNDS | | Region 1 | 10/6/2019 | |
| 98673 ES - John Robert Lewis Elementary Facility | FIRE SAFETY | | Region 1 | 15/07/2019 | |
| 74807 ES - Kingsley Elementary Facility | CARPENTRY | Miscellaneous | Region 1 | 8/11/2018 | |
| 86400 ES - Kingsley Elementary Facility | GROUNDS | Miscellaneous | Region 1 | 22/03/2019 | |
| 89035 ES - Kingsley Elementary Facility | HOUSEKEEPING | Miscellaneous | Region 1 | 11/4/2019 | |
| 92411 ES - Kingsley Elementary Facility | HVAC | Miscellaneous | Region 1 | 9/5/2019 | |
| 95343 ES - Kingsley Elementary Facility | EQUIPMENT REPAIR | Miscellaneous | Region 1 | 5/6/2019 | |
| 98332 ES - Kingsley Elementary Facility | CARPENTRY | Floors | Region 1 | 9/7/2019 | |
| 98333 ES - Kingsley Elementary Facility | ELECTRICAL | Miscellaneous | Region 1 | 9/7/2019 | |
| 98804 ES - Kingsley Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 16/07/2019 | |
| 98805 ES - Kingsley Elementary Facility | PLUMBING | Faucet Dripping | Region 1 | 16/07/2019 | |
| 85439 ES - Kittredge Magnet at Nancy Creek Facility | ELECTRICAL | Lights Out | Region 1 | 11/3/2019 | 3/12/2019 |
| 86078 ES - Kittredge Magnet at Nancy Creek Facility | ELECTRICAL | Lights Out | Region 1 | 19/03/2019 | |
| 93510 ES - Kittredge Magnet at Nancy Creek Facility | ELECTRICAL | Lights Out | Region 1 | 23/05/2019 | |
| 97887 ES - Kittredge Magnet at Nancy Creek Facility | CARPENTRY | Floors | Region 1 | 1/7/2019 | 7/6/2019 |
| 97889 ES - Kittredge Magnet at Nancy Creek Facility | HVAC | Room Too Cold | Region 1 | 1/7/2019 | |
| 97890 ES - Kittredge Magnet at Nancy Creek Facility | HVAC | Broken Equipment | Region 1 | 1/7/2019 | 7/6/2019 |
| 97893 ES - Kittredge Magnet at Nancy Creek Facility | CARPENTRY | Broken Equipment | Region 1 | 1/7/2019 | 7/6/2019 |
| 97895 ES - Kittredge Magnet at Nancy Creek Facility | HVAC | Locks / Keys | Region 1 | 1/7/2019 | 7/6/2019 |
| 97896 ES - Kittredge Magnet at Nancy Creek Facility | CARPENTRY | Broken Equipment | Region 1 | 1/7/2019 | 7/6/2019 |
| 98253 ES - Kittredge Magnet at Nancy Creek Facility | ELECTRICAL | Lights Out | Region 1 | 8/7/2019 | |
| 98825 ES - Kittredge Magnet at Nancy Creek Facility | | Broken Equipment | Region 1 | 16/07/2019 | |
| 63382 ES - Montclair Elementary Facility | ROOF | Roof Leak | Region 1 | 9/8/2018 | |
| 74601 ES - Montclair Elementary Facility | ROOF | Ceilings | Region 1 | 6/11/2018 | |
| 74896 ES - Montclair Elementary Facility | ROOF | Water Leak | Region 1 | 9/11/2018 | |
| 75105 ES - Montclair Elementary Facility | ROOF | Ceilings | Region 1 | 12/11/2018 | |
| 75148 ES - Montclair Elementary Facility | ROOF | Ceilings | Region 1 | 13/11/2018 | |
| | | | | | |

| 75151 ES - Montclair Elementary Facility | ROOF | Ceilings | Region 1 | 13/11/2018 | |
|---|-----------------------------|------------------|----------|------------|-----------|
| 83837 ES - Montclair Elementary Facility | ROOF | Ceilings | Region 1 | 28/02/2019 | 3/1/2019 |
| 85211 ES - Montclair Elementary Facility | ROOF | Roof Leak | Region 1 | 7/3/2019 | |
| 90613 ES - Montclair Elementary Facility | ROOF | Ceilings | Region 1 | 29/04/2019 | 5/4/2019 |
| 95996 ES - Montclair Elementary Facility | HVAC | | Region 1 | 17/06/2019 | |
| 96196 ES - Montclair Elementary Facility | PAINTING / PRESSURE WASHING | Miscellaneous | Region 1 | 19/06/2019 | |
| 96666 ES - Montclair Elementary Facility | CARPENTRY | Doors | Region 1 | 26/06/2019 | 7/12/2019 |
| 98341 ES - Montclair Elementary Facility | GROUNDS | | Region 1 | 9/7/2019 | |
| 98449 ES - Montclair Elementary Facility | PLUMBING | Standing Water | Region 1 | 10/7/2019 | |
| 98802 ES - Montclair Elementary Facility | PEST CONTROL | Pest | Region 1 | 16/07/2019 | |
| 98806 ES - Montclair Elementary Facility | PEST CONTROL | Pest | Region 1 | 16/07/2019 | |
| 79157 ES - Montgomery Elementary Facility | ROOF | Roof Leak | Region 1 | 7/1/2019 | |
| 80799 ES - Montgomery Elementary Facility | ROOF | Roof Leak | Region 1 | 24/01/2019 | |
| 90404 ES - Montgomery Elementary Facility | ROOF | Roof Leak | Region 1 | 26/04/2019 | 5/1/2019 |
| 92846 ES - Montgomery Elementary Facility | CARPENTRY | | Region 1 | 15/05/2019 | |
| 93310 ES - Montgomery Elementary Facility | CARPENTRY | Miscellaneous | Region 1 | 21/05/2019 | |
| 98338 ES - Montgomery Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 9/7/2019 | |
| 98498 ES - Montgomery Elementary Facility | KITCHEN EQUIPMENT | • | Region 1 | 11/7/2019 | 7/12/2019 |
| 88897 ES - Oakcliff Elementary Facility | CARPENTRY | Miscellaneous | Region 1 | 10/4/2019 | |
| 90003 ES - Oakcliff Elementary Facility | WAREHOUSE | Miscellaneous | Region 1 | 22/04/2019 | |
| 91829 ES - Oakcliff Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 2/5/2019 | 5/7/2019 |
| 96701 ES - Oakcliff Elementary Facility | ELECTRICAL | Broken Equipment | Region 1 | 26/06/2019 | 7/1/2019 |
| 98726 ES - Oakcliff Elementary Facility | GROUNDS | Debris | Region 1 | 15/07/2019 | |
| 98752 ES - Oakcliff Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 1 | 15/07/2019 | |
| 98753 ES - Oakcliff Elementary Facility | PEST CONTROL | Pest | Region 1 | 15/07/2019 | |
| 92401 ES - Vanderlyn Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 9/5/2019 | |
| 95364 ES - Vanderlyn Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 6/6/2019 | 6/11/2019 |
| 96166 ES - Vanderlyn Elementary Facility | ROOF | Miscellaneous | Region 1 | 19/06/2019 | |
| 96769 ES - Vanderlyn Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 27/06/2019 | 7/12/2019 |
| 98386 ES - Vanderlyn Elementary Facility | ROOF | Structure | Region 1 | 9/7/2019 | |
| 98527 ES - Vanderlyn Elementary Facility | HVAC | Room Too Hot | Region 1 | 11/7/2019 | |
| 80295 ES - Woodward Elementary Facility | GLAZING | Broken Window | Region 1 | 18/01/2019 | |
| 89701 ES - Woodward Elementary Facility | GROUNDS | Debris | Region 1 | 19/04/2019 | |
| 95642 ES - Woodward Elementary Facility | GROUNDS | Miscellaneous | Region 1 | 10/6/2019 | |
| 96021 ES - Woodward Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 1 | 17/06/2019 | |
| 96097 ES - Woodward Elementary Facility | ELECTRICAL | Lights Out | Region 1 | 18/06/2019 | |
| 96753 ES - Woodward Elementary Facility | GROUNDS | J | Region 1 | 27/06/2019 | 7/2/2019 |
| 98326 ES - Woodward Elementary Facility | CARPENTRY | Floors | Region 1 | 9/7/2019 | |
| 98330 ES - Woodward Elementary Facility | HVAC | Miscellaneous | Region 1 | 9/7/2019 | |
| 98340 ES - Woodward Elementary Facility | FIRE SAFETY | Fire Alarm | Region 1 | 9/7/2019 | |
| • | | | • | | |

| 98342 ES - Woodward Elementary Facility | HVAC | Water Leak | Region 1 | 9/7/2019 | |
|---|-----------------------------|----------------------|----------|------------|-----------|
| 98682 ES - Woodward Elementary Facility | PAINTING / PRESSURE WASHING | | Region 1 | 15/07/2019 | |
| 98820 ES - Woodward Elementary Facility | | Miscellaneous | Region 1 | 16/07/2019 | |
| 78958 HS - Chamblee Charter High Facility | ELECTRICAL | Broken Equipment | Region 1 | 3/1/2019 | |
| 90172 HS - Chamblee Charter High Facility | GROUNDS | Broken Equipment | Region 1 | 23/04/2019 | |
| 92353 HS - Chamblee Charter High Facility | GROUNDS | | Region 1 | 8/5/2019 | |
| 93959 HS - Chamblee Charter High Facility | ELECTRICAL | Broken Equipment | Region 1 | 30/05/2019 | 6/4/2019 |
| 96644 HS - Chamblee Charter High Facility | HVAC | Miscellaneous | Region 1 | 25/06/2019 | 7/12/2019 |
| 98009 HS - Chamblee Charter High Facility | HVAC | Room Too Hot | Region 1 | 3/7/2019 | 7/8/2019 |
| 98012 HS - Chamblee Charter High Facility | HVAC | Room Too Hot | Region 1 | 3/7/2019 | 7/10/2019 |
| 98058 HS - Chamblee Charter High Facility | FIRE SAFETY | Alarm Systems | Region 1 | 5/7/2019 | 7/10/2019 |
| 98199 HS - Chamblee Charter High Facility | HVAC | | Region 1 | 8/7/2019 | |
| 98770 HS - Chamblee Charter High Facility | HVAC | Room Too Hot | Region 1 | 15/07/2019 | |
| 57371 HS - Cross Keys High Facility | ROOF | | Region 1 | 12/6/2018 | |
| 75346 HS - Cross Keys High Facility | ROOF | Roof Leak | Region 1 | 14/11/2018 | |
| 84947 HS - Cross Keys High Facility | LOCKSMITH | Locks / Keys | Region 1 | 5/3/2019 | |
| 85905 HS - Cross Keys High Facility | CARPENTRY | Miscellaneous | Region 1 | 18/03/2019 | |
| 89617 HS - Cross Keys High Facility | ROOF | Roof Leak | Region 1 | 18/04/2019 | |
| 93743 HS - Cross Keys High Facility | GROUNDS | Miscellaneous | Region 1 | 28/05/2019 | 6/2/2019 |
| 93872 HS - Cross Keys High Facility | CARPENTRY | | Region 1 | 29/05/2019 | |
| 93952 HS - Cross Keys High Facility | CARPENTRY | Miscellaneous | Region 1 | 30/05/2019 | 6/4/2019 |
| 94089 HS - Cross Keys High Facility | GLAZING | Broken Window | Region 1 | 31/05/2019 | |
| 95540 HS - Cross Keys High Facility | FIRE SAFETY | | Region 1 | 10/6/2019 | |
| 95611 HS - Cross Keys High Facility | CARPENTRY | Miscellaneous | Region 1 | 10/6/2019 | |
| 96154 HS - Cross Keys High Facility | GROUNDS | Miscellaneous | Region 1 | 18/06/2019 | |
| 96224 HS - Cross Keys High Facility | ELECTRICAL | No Power | Region 1 | 19/06/2019 | |
| 96271 HS - Cross Keys High Facility | CARPENTRY | Miscellaneous | Region 1 | 19/06/2019 | |
| 96727 HS - Cross Keys High Facility | HVAC | Room Too Hot | Region 1 | 26/06/2019 | 7/1/2019 |
| 96729 HS - Cross Keys High Facility | HVAC | Room Too Hot | Region 1 | 26/06/2019 | 7/12/2019 |
| 98217 HS - Cross Keys High Facility | FIRE SAFETY | Alarm Systems | Region 1 | 8/7/2019 | |
| 98218 HS - Cross Keys High Facility | FIRE SAFETY | Alarm Systems | Region 1 | 8/7/2019 | |
| 98775 HS - Cross Keys High Facility | FIRE SAFETY | Alarm Systems | Region 1 | 16/07/2019 | |
| 98776 HS - Cross Keys High Facility | FIRE SAFETY | Alarm Systems | Region 1 | 16/07/2019 | |
| 58125 HS - Dunwoody High Facility | CARPENTRY | | Region 1 | 26/06/2018 | |
| 83887 HS - Dunwoody High Facility | CARPENTRY | Floors | Region 1 | 28/02/2019 | |
| 88403 HS - Dunwoody High Facility | EQUIPMENT REPAIR | Broken Equipment | Region 1 | 2/4/2019 | |
| 93158 HS - Dunwoody High Facility | CARPENTRY | Miscellaneous | Region 1 | 20/05/2019 | |
| 93194 HS - Dunwoody High Facility | CARPENTRY | Floors | Region 1 | 20/05/2019 | |
| 95308 HS - Dunwoody High Facility | CARPENTRY | Floors | Region 1 | 5/6/2019 | 6/10/2019 |
| 96129 HS - Dunwoody High Facility | CARPENTRY | Cove Base | Region 1 | 18/06/2019 | |
| | | | | | |

| | OCTAC LIC. D L. LIVL F IV | CARRENTRY | NAC II | D 4 | 27/06/2010 | 7/2/2010 |
|--------|--|-----------------------------|----------------------|----------|------------|-----------|
| | 96746 HS - Dunwoody High Facility | CARPENTRY | Miscellaneous | Region 1 | 27/06/2019 | 7/2/2019 |
| | 98287 HS - Dunwoody High Facility | FIRE SAFETY | 5 | Region 1 | 9/7/2019 | |
| | 98400 HS - Dunwoody High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 1 | 10/7/2019 | |
| | 98664 HS - Dunwoody High Facility | HVAC | Room Too Hot | Region 1 | 15/07/2019 | |
| | 98734 HS - Dunwoody High Facility | GROUNDS | Standing Water | Region 1 | 15/07/2019 | |
| | 41365 MS - Chamblee Middle Facility | ROOF | | Region 1 | 12/1/2018 | |
| | 60567 MS - Chamblee Middle Facility | CARPENTRY | | Region 1 | 26/07/2018 | |
| | 83130 MS - Chamblee Middle Facility | ELECTRICAL | Lights Out | Region 1 | 19/02/2019 | |
| | 83395 MS - Chamblee Middle Facility | ROOF | Roof Leak | Region 1 | 21/02/2019 | |
| | 93202 MS - Chamblee Middle Facility | HVAC | Room Too Hot | Region 1 | 20/05/2019 | |
| | 96726 MS - Chamblee Middle Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 1 | 26/06/2019 | 7/1/2019 |
| | 98552 MS - Chamblee Middle Facility | PLUMBING | | Region 1 | 12/7/2019 | |
| | 59517 MS - Peachtree Charter Middle Facility | CARPENTRY | | Region 1 | 12/7/2018 | |
| | 61026 MS - Peachtree Charter Middle Facility | CARPENTRY | | Region 1 | 31/07/2018 | |
| | 61027 MS - Peachtree Charter Middle Facility | CARPENTRY | | Region 1 | 31/07/2018 | |
| | 85373 MS - Peachtree Charter Middle Facility | HVAC | Miscellaneous | Region 1 | 11/3/2019 | 3/12/2019 |
| | 85508 MS - Peachtree Charter Middle Facility | GROUNDS | Miscellaneous | Region 1 | 12/3/2019 | |
| | 86942 MS - Peachtree Charter Middle Facility | ELECTRICAL | Lights Out | Region 1 | 25/03/2019 | |
| | 87269 MS - Peachtree Charter Middle Facility | PAINTING / PRESSURE WASHING | Miscellaneous | Region 1 | 28/03/2019 | |
| | 89481 MS - Peachtree Charter Middle Facility | GLAZING | Broken Window | Region 1 | 16/04/2019 | |
| | 90093 MS - Peachtree Charter Middle Facility | CARPENTRY | Structure | Region 1 | 23/04/2019 | |
| | 90245 MS - Peachtree Charter Middle Facility | CARPENTRY | Miscellaneous | Region 1 | 24/04/2019 | |
| | 90341 MS - Peachtree Charter Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 1 | 25/04/2019 | |
| | 95821 MS - Peachtree Charter Middle Facility | ROOF | Roof Leak | Region 1 | 13/06/2019 | |
| | 96201 MS - Peachtree Charter Middle Facility | CARPENTRY | Miscellaneous | Region 1 | 19/06/2019 | |
| | 96691 MS - Peachtree Charter Middle Facility | CARPENTRY | Miscellaneous | Region 1 | 26/06/2019 | 7/12/2019 |
| | 96788 MS - Peachtree Charter Middle Facility | CARPENTRY | Miscellaneous | Region 1 | 27/06/2019 | 7/2/2019 |
| | 96803 MS - Peachtree Charter Middle Facility | ELECTRICAL | Miscellaneous | Region 1 | 27/06/2019 | 7/2/2019 |
| | 98370 MS - Peachtree Charter Middle Facility | CARPENTRY | | Region 1 | 9/7/2019 | |
| | 98372 MS - Peachtree Charter Middle Facility | GROUNDS | | Region 1 | 9/7/2019 | |
| | 98555 MS - Peachtree Charter Middle Facility | PLUMBING | | Region 1 | 14/07/2019 | |
| | 98556 MS - Peachtree Charter Middle Facility | PAINTING / PRESSURE WASHING | Paint | Region 1 | 14/07/2019 | |
| | 98747 MS - Peachtree Charter Middle Facility | FIRE SAFETY | Alarm Systems | Region 1 | 15/07/2019 | |
| | 98783 MS - Peachtree Charter Middle Facility | CARPENTRY | Miscellaneous | Region 1 | 16/07/2019 | |
| | 98784 MS - Peachtree Charter Middle Facility | PLUMBING | Ceilings | Region 1 | 16/07/2019 | |
| | 98828 MS - Peachtree Charter Middle Facility | | Miscellaneous | Region 1 | 16/07/2019 | |
| | 98832 MS - Peachtree Charter Middle Facility | | Fire Alarm | Region 1 | 16/07/2019 | |
| M-5799 | , | CARPENTRY | | Region 1 | 25/06/2018 | |
| | 92640 MS - Sequoyah Middle Facility | GROUNDS | Miscellaneous | Region 1 | 13/05/2019 | |
| | 93349 MS - Sequoyah Middle Facility | ROOF | Roof Leak | Region 1 | 22/05/2019 | |
| | | | | -0 | , , | |
| | | | | | | |

| 93562 MS - Sequoyah Middle Facility | CARPENTRY | Structure | Region 1 | 24/05/2019 | |
|---|-----------------------------|---------------|----------|------------|-----------|
| 94027 MS - Sequoyah Middle Facility | HVAC | Room Too Hot | Region 1 | 31/05/2019 | 6/5/2019 |
| 95279 MS - Sequoyah Middle Facility | GROUNDS | Cove Base | Region 1 | 5/6/2019 | 6/10/2019 |
| 95743 MS - Sequoyah Middle Facility | ROOF | Roof Leak | Region 1 | 12/6/2019 | |
| 95747 MS - Sequoyah Middle Facility | CARPENTRY | Miscellaneous | Region 1 | 12/6/2019 | |
| 96124 MS - Sequoyah Middle Facility | HVAC | Room Too Hot | Region 1 | 18/06/2019 | |
| 96162 MS - Sequoyah Middle Facility | HVAC | Ceilings | Region 1 | 19/06/2019 | |
| 96663 MS - Sequoyah Middle Facility | LOCKSMITH | Locks / Keys | Region 1 | 26/06/2019 | 7/12/2019 |
| 96807 MS - Sequoyah Middle Facility | CARPENTRY | Cove Base | Region 1 | 29/06/2019 | 7/4/2019 |
| 97953 MS - Sequoyah Middle Facility | HVAC | Miscellaneous | Region 1 | 2/7/2019 | 7/7/2019 |
| 97994 MS - Sequoyah Middle Facility | VENDOR | Structure | Region 1 | 3/7/2019 | |
| 98044 MS - Sequoyah Middle Facility | FIRE SAFETY | Fire Alarm | Region 1 | 3/7/2019 | 7/8/2019 |
| 98315 MS - Sequoyah Middle Facility | GROUNDS | Miscellaneous | Region 1 | 9/7/2019 | |
| 98422 MS - Sequoyah Middle Facility | CARPENTRY | Structure | Region 1 | 10/7/2019 | |
| 98551 MS - Sequoyah Middle Facility | HVAC | Roof Leak | Region 1 | 12/7/2019 | |
| 98708 MS - Sequoyah Middle Facility | HVAC | Room Too Hot | Region 1 | 15/07/2019 | |
| 57224 AS - Sam Moss Service Center | ROOF | | Region 2 | 11/6/2018 | |
| 72773 AS - Sam Moss Service Center | ROOF | Roof Leak | Region 2 | 26/10/2018 | |
| 75899 AS - Sam Moss Service Center | HVAC | | Region 2 | 27/11/2018 | |
| 76074 AS - Sam Moss Service Center | CARPENTRY | Floors | Region 2 | 29/11/2018 | |
| 80137 AS - Sam Moss Service Center | ELECTRICAL | Lights Out | Region 2 | 17/01/2019 | |
| 85866 AS - Sam Moss Service Center | HAZARDOUS | Miscellaneous | Region 2 | 15/03/2019 | |
| 85947 AS - Sam Moss Service Center | HVAC | | Region 2 | 18/03/2019 | |
| 88816 AS - Sam Moss Service Center | ELECTRICAL | Lights Out | Region 2 | 9/4/2019 | |
| 90604 AS - Sam Moss Service Center | WAREHOUSE | | Region 2 | 29/04/2019 | 5/4/2019 |
| 90610 AS - Sam Moss Service Center | ELECTRICAL | | Region 2 | 29/04/2019 | 5/4/2019 |
| 90620 AS - Sam Moss Service Center | CARPENTRY | | Region 2 | 29/04/2019 | |
| 92188 AS - Sam Moss Service Center | FIRE SAFETY | | Region 2 | 6/5/2019 | 5/11/2019 |
| 92799 AS - Sam Moss Service Center | ELECTRICAL | | Region 2 | 14/05/2019 | |
| 92904 AS - Sam Moss Service Center | ROOF | | Region 2 | 16/05/2019 | |
| 95619 AS - Sam Moss Service Center | HVAC | | Region 2 | 10/6/2019 | |
| 96794 AS - Sam Moss Service Center | HVAC | | Region 2 | 27/06/2019 | 7/2/2019 |
| 98328 AS - Sam Moss Service Center | ELECTRICAL | Lights Out | Region 2 | 9/7/2019 | |
| 98329 AS - Sam Moss Service Center | ELECTRICAL | Lights Out | Region 2 | 9/7/2019 | |
| 98334 AS - Sam Moss Service Center | PLUMBING | Miscellaneous | Region 2 | 9/7/2019 | |
| 98339 AS - Sam Moss Service Center | PAINTING / PRESSURE WASHING | Paint | Region 2 | 9/7/2019 | |
| 98357 AS - Sam Moss Service Center | PEST CONTROL | | Region 2 | 9/7/2019 | 7/10/2019 |
| 98381 AS - Sam Moss Service Center | Welding | | Region 2 | 9/7/2019 | |
| 98415 AS - Sam Moss Service Center | ELECTRICAL | Lights Out | Region 2 | 10/7/2019 | |
| 83308 AS - William Bradley Bryant Tech Center | CARPENTRY | Broken Window | Region 2 | 21/02/2019 | |
| | | | | | |

| 92167 AS - William Bradley Bryant Tech Center | ELECTRICAL | No Power | Region 2 | 6/5/2019 | 5/11/2019 |
|---|-----------------------------|-------------------|----------|------------|-----------|
| 92699 AS - William Bradley Bryant Tech Center | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 13/05/2019 | |
| 93506 AS - William Bradley Bryant Tech Center | PAINTING / PRESSURE WASHING | Paint | Region 2 | 23/05/2019 | |
| 96190 AS - William Bradley Bryant Tech Center | CARPENTRY | Whiteboards | Region 2 | 19/06/2019 | |
| 98681 AS - William Bradley Bryant Tech Center | HVAC | | Region 2 | 15/07/2019 | |
| 92917 CO - DeKalb County Schools Region 2 | CARPENTRY | | Region 2 | 16/05/2019 | |
| 79489 EO - Coralwood Education | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 9/1/2019 | |
| 89753 EO - Coralwood Education | CARPENTRY | Doors | Region 2 | 19/04/2019 | |
| 92759 EO - Coralwood Education | HVAC | Room Too Hot | Region 2 | 14/05/2019 | |
| 97980 EO - Coralwood Education | HVAC | Room Too Hot | Region 2 | 3/7/2019 | |
| 98798 EO - Coralwood Education | ELECTRICAL | Lights Out | Region 2 | 16/07/2019 | |
| 68726 EO - Fernbank Science Center | HVAC | Miscellaneous | Region 2 | 14/09/2018 | |
| 79690 EO - Fernbank Science Center | HVAC | Room Too Cold | Region 2 | 11/1/2019 | |
| 79950 EO - Fernbank Science Center | HVAC | Move Items | Region 2 | 15/01/2019 | |
| 80004 EO - Fernbank Science Center | HVAC | Room Too Cold | Region 2 | 16/01/2019 | |
| 83893 EO - Fernbank Science Center | CARPENTRY | Doors | Region 2 | 28/02/2019 | |
| 85269 EO - Fernbank Science Center | HVAC | Room Too Cold | Region 2 | 8/3/2019 | |
| 85271 EO - Fernbank Science Center | GROUNDS | Miscellaneous | Region 2 | 8/3/2019 | |
| 85718 EO - Fernbank Science Center | HAZARDOUS | | Region 2 | 14/03/2019 | |
| 90181 EO - Fernbank Science Center | ROOF | Roof Leak | Region 2 | 24/04/2019 | |
| 95177 EO - Fernbank Science Center | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 3/6/2019 | 6/8/2019 |
| 96640 EO - Fernbank Science Center | ROOF | Roof Leak | Region 2 | 25/06/2019 | 7/12/2019 |
| 76160 ES - Avondale Elementary Facility | ROOF | Standing Water | Region 2 | 29/11/2018 | |
| 76940 ES - Avondale Elementary Facility | ELECTRICAL | No Power | Region 2 | 6/12/2018 | |
| 79251 ES - Avondale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 7/1/2019 | |
| 79274 ES - Avondale Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 2 | 8/1/2019 | |
| 79873 ES - Avondale Elementary Facility | ELECTRICAL | Noises | Region 2 | 14/01/2019 | |
| 80573 ES - Avondale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 22/01/2019 | |
| 82842 ES - Avondale Elementary Facility | FIRE SAFETY | Extinguisher | Region 2 | 12/2/2019 | |
| 83412 ES - Avondale Elementary Facility | ROOF | Water Leak | Region 2 | 21/02/2019 | |
| 83590 ES - Avondale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 25/02/2019 | |
| 85120 ES - Avondale Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 2 | 7/3/2019 | |
| 85784 ES - Avondale Elementary Facility | INSPECTION | | Region 2 | 14/03/2019 | |
| 85954 ES - Avondale Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 18/03/2019 | |
| 89383 ES - Avondale Elementary Facility | CARPENTRY | Doors | Region 2 | 15/04/2019 | |
| 89829 ES - Avondale Elementary Facility | ROOF | Roof Leak | Region 2 | 19/04/2019 | |
| 92927 ES - Avondale Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 16/05/2019 | |
| 92930 ES - Avondale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 16/05/2019 | |
| 92955 ES - Avondale Elementary Facility | PEST CONTROL | Miscellaneous | Region 2 | 16/05/2019 | |
| 93354 ES - Avondale Elementary Facility | GLAZING | Miscellaneous | Region 2 | 22/05/2019 | |
| | | | | | |

| 95563 ES - Avondale Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 10/6/2019 | |
|--|-----------------------------|------------------|----------|------------|-----------|
| 95564 ES - Avondale Elementary Facility | CARPENTRY | Whiteboards | Region 2 | 10/6/2019 | |
| 95567 ES - Avondale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 10/6/2019 | |
| 95651 ES - Avondale Elementary Facility | HVAC | Roof Leak | Region 2 | 10/6/2019 | |
| 95759 ES - Avondale Elementary Facility | GROUNDS | Trees | Region 2 | 12/6/2019 | |
| 95760 ES - Avondale Elementary Facility | CARPENTRY | Floors | Region 2 | 12/6/2019 | |
| 95785 ES - Avondale Elementary Facility | CARPENTRY | Doors | Region 2 | 12/6/2019 | |
| 96037 ES - Avondale Elementary Facility | GROUNDS | Debris | Region 2 | 17/06/2019 | |
| 96038 ES - Avondale Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 17/06/2019 | |
| 96041 ES - Avondale Elementary Facility | ROOF | Structure | Region 2 | 17/06/2019 | |
| 96042 ES - Avondale Elementary Facility | GROUNDS | Grass | Region 2 | 17/06/2019 | |
| 96044 ES - Avondale Elementary Facility | ROOF | Roof Leak | Region 2 | 17/06/2019 | |
| 96222 ES - Avondale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 19/06/2019 | |
| 96724 ES - Avondale Elementary Facility | LOCKSMITH | Doors | Region 2 | 26/06/2019 | 7/12/2019 |
| 97910 ES - Avondale Elementary Facility | FIRE SAFETY | Fire Alarm | Region 2 | 1/7/2019 | 7/6/2019 |
| 98432 ES - Avondale Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 10/7/2019 | |
| 98439 ES - Avondale Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 10/7/2019 | |
| 98441 ES - Avondale Elementary Facility | ROOF | Ceilings | Region 2 | 10/7/2019 | |
| 57331 ES - Briar Vista Elementary Facility | CARPENTRY | | Region 2 | 12/6/2018 | |
| 59356 ES - Briar Vista Elementary Facility | CARPENTRY | | Region 2 | 10/7/2018 | |
| 62859 ES - Briar Vista Elementary Facility | PLUMBING | Water Leak | Region 2 | 6/8/2018 | |
| 64919 ES - Briar Vista Elementary Facility | PLUMBING | Water Leak | Region 2 | 23/08/2018 | |
| 79572 ES - Briar Vista Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 2 | 10/1/2019 | |
| 80083 ES - Briar Vista Elementary Facility | ROOF | Roof Leak | Region 2 | 16/01/2019 | |
| 90106 ES - Briar Vista Elementary Facility | ROOF | Roof Leak | Region 2 | 23/04/2019 | |
| 90109 ES - Briar Vista Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 23/04/2019 | |
| 92306 ES - Briar Vista Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 8/5/2019 | |
| 92788 ES - Briar Vista Elementary Facility | CARPENTRY | Structure | Region 2 | 14/05/2019 | |
| 92961 ES - Briar Vista Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 16/05/2019 | |
| 92962 ES - Briar Vista Elementary Facility | GLAZING | Broken Window | Region 2 | 16/05/2019 | |
| 93792 ES - Briar Vista Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 2 | 28/05/2019 | 6/2/2019 |
| 95196 ES - Briar Vista Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 3/6/2019 | |
| 96733 ES - Briar Vista Elementary Facility | CARPENTRY | Floors | Region 2 | 26/06/2019 | 7/12/2019 |
| 98227 ES - Briar Vista Elementary Facility | ELECTRICAL | Broken Equipment | Region 2 | 8/7/2019 | |
| 98283 ES - Briar Vista Elementary Facility | HVAC | | Region 2 | 9/7/2019 | |
| 98399 ES - Briar Vista Elementary Facility | ELECTRICAL | | Region 2 | 10/7/2019 | |
| 98485 ES - Briar Vista Elementary Facility | ROOF | Roof Leak | Region 2 | 11/7/2019 | |
| 98754 ES - Briar Vista Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 15/07/2019 | |
| 98755 ES - Briar Vista Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 15/07/2019 | |
| 98757 ES - Briar Vista Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 15/07/2019 | |
| | | | | | |

| 98794 ES - Briar Vista Elementary Facility | FIRE SAFETY | | Region 2 | 16/07/2019 | |
|--|-----------------------------|----------------------|----------|------------|----------|
| 53565 ES - Briarlake Elementary Facility | CARPENTRY | | Region 2 | 2/5/2018 | |
| 60040 ES - Briarlake Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 19/07/2018 | |
| 62029 ES - Briarlake Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 1/8/2018 | |
| 63162 ES - Briarlake Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 8/8/2018 | |
| 69671 ES - Briarlake Elementary Facility | HVAC | Room Too Hot | Region 2 | 27/09/2018 | |
| 72921 ES - Briarlake Elementary Facility | ROOF | | Region 2 | 29/10/2018 | |
| 75396 ES - Briarlake Elementary Facility | ROOF | Roof Leak | Region 2 | 15/11/2018 | |
| 85087 ES - Briarlake Elementary Facility | ELECTRONICS | Miscellaneous | Region 2 | 6/3/2019 | |
| 87165 ES - Briarlake Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 2 | 27/03/2019 | |
| 87168 ES - Briarlake Elementary Facility | HVAC | Broken Equipment | Region 2 | 27/03/2019 | |
| 89029 ES - Briarlake Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 11/4/2019 | |
| 89539 ES - Briarlake Elementary Facility | HVAC | Miscellaneous | Region 2 | 17/04/2019 | |
| 89973 ES - Briarlake Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 22/04/2019 | |
| 90447 ES - Briarlake Elementary Facility | GLAZING | Broken Window | Region 2 | 26/04/2019 | 5/1/2019 |
| 90792 ES - Briarlake Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 30/04/2019 | 5/5/2019 |
| 90925 ES - Briarlake Elementary Facility | HVAC | Room Too Hot | Region 2 | 1/5/2019 | 5/6/2019 |
| 92643 ES - Briarlake Elementary Facility | CARPENTRY | Decking | Region 2 | 13/05/2019 | |
| 93546 ES - Briarlake Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 24/05/2019 | |
| 93547 ES - Briarlake Elementary Facility | GLAZING | Broken Window | Region 2 | 24/05/2019 | |
| 93552 ES - Briarlake Elementary Facility | ELECTRONICS | Clocks | Region 2 | 24/05/2019 | |
| 93553 ES - Briarlake Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 24/05/2019 | |
| 93554 ES - Briarlake Elementary Facility | CARPENTRY | Cove Base | Region 2 | 24/05/2019 | |
| 93564 ES - Briarlake Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 24/05/2019 | |
| 93581 ES - Briarlake Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 24/05/2019 | |
| 93830 ES - Briarlake Elementary Facility | HVAC | Room Too Hot | Region 2 | 29/05/2019 | 6/3/2019 |
| 93838 ES - Briarlake Elementary Facility | HOUSEKEEPING | Floors | Region 2 | 29/05/2019 | |
| 95409 ES - Briarlake Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 6/6/2019 | |
| 95823 ES - Briarlake Elementary Facility | ROOF | Roof Leak | Region 2 | 13/06/2019 | |
| 96709 ES - Briarlake Elementary Facility | PLUMBING | Water Leak | Region 2 | 26/06/2019 | 7/1/2019 |
| 96783 ES - Briarlake Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 27/06/2019 | |
| 98193 ES - Briarlake Elementary Facility | HVAC | | Region 2 | 8/7/2019 | |
| 98268 ES - Briarlake Elementary Facility | PLUMBING | Water Leak | Region 2 | 8/7/2019 | |
| 98748 ES - Briarlake Elementary Facility | HVAC | Room Too Hot | Region 2 | 15/07/2019 | |
| 98779 ES - Briarlake Elementary Facility | HVAC | Room Too Hot | Region 2 | 16/07/2019 | |
| 98780 ES - Briarlake Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 16/07/2019 | |
| 98781 ES - Briarlake Elementary Facility | GROUNDS | Trees | Region 2 | 16/07/2019 | |
| 45286 ES - Brockett Elementary Facility | HVAC | | Region 2 | 23/02/2018 | |
| 51151 ES - Brockett Elementary Facility | PAINTING / PRESSURE WASHING | | Region 2 | 23/04/2018 | |
| 71249 ES - Brockett Elementary Facility | LOCKSMITH | Doors | Region 2 | 9/10/2018 | |
| • • | | | - | | |

| 77908 ES - Brockett Elementary Facility | VENDOR | | Region 2 | 20/12/2018 | |
|--|-----------------------------|------------------|----------|------------|----------|
| 80056 ES - Brockett Elementary Facility | HVAC | Water Leak | Region 2 | 16/01/2019 | |
| 80793 ES - Brockett Elementary Facility | ROOF | Water Leak | Region 2 | 24/01/2019 | |
| 83205 ES - Brockett Elementary Facility | ROOF | Water Leak | Region 2 | 20/02/2019 | |
| 85940 ES - Brockett Elementary Facility | HVAC | Room Too Cold | Region 2 | 18/03/2019 | |
| 86398 ES - Brockett Elementary Facility | HVAC | Room Too Cold | Region 2 | 22/03/2019 | |
| 88960 ES - Brockett Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 11/4/2019 | |
| 88992 ES - Brockett Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 11/4/2019 | |
| 88993 ES - Brockett Elementary Facility | CARPENTRY | Doors | Region 2 | 11/4/2019 | |
| 89593 ES - Brockett Elementary Facility | ROOF | Roof Leak | Region 2 | 18/04/2019 | |
| 90327 ES - Brockett Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 25/04/2019 | |
| 90726 ES - Brockett Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 30/04/2019 | 5/5/2019 |
| 91866 ES - Brockett Elementary Facility | HVAC | Room Too Hot | Region 2 | 2/5/2019 | 5/7/2019 |
| 91868 ES - Brockett Elementary Facility | ROOF | Roof Leak | Region 2 | 2/5/2019 | 5/7/2019 |
| 92475 ES - Brockett Elementary Facility | HVAC | Water Leak | Region 2 | 10/5/2019 | |
| 92905 ES - Brockett Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 16/05/2019 | |
| 95208 ES - Brockett Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 4/6/2019 | 6/9/2019 |
| 95676 ES - Brockett Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95677 ES - Brockett Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95678 ES - Brockett Elementary Facility | HVAC | Miscellaneous | Region 2 | 11/6/2019 | |
| 95680 ES - Brockett Elementary Facility | HVAC | Miscellaneous | Region 2 | 11/6/2019 | |
| 96315 ES - Brockett Elementary Facility | ROOF | Roof Leak | Region 2 | 20/06/2019 | |
| 96763 ES - Brockett Elementary Facility | HVAC | Room Too Hot | Region 2 | 27/06/2019 | 7/2/2019 |
| 96765 ES - Brockett Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 27/06/2019 | 7/2/2019 |
| 98008 ES - Brockett Elementary Facility | GROUNDS | Debris | Region 2 | 3/7/2019 | |
| 98195 ES - Brockett Elementary Facility | HVAC | | Region 2 | 8/7/2019 | |
| 98735 ES - Brockett Elementary Facility | PLUMBING | Faucet Dripping | Region 2 | 15/07/2019 | |
| 72816 ES - Evansdale Elementary Facility | ELECTRICAL | Broken Equipment | Region 2 | 29/10/2018 | |
| 79513 ES - Evansdale Elementary Facility | ELECTRICAL | Broken Equipment | Region 2 | 9/1/2019 | |
| 80118 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 17/01/2019 | |
| 80119 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 17/01/2019 | |
| 82319 ES - Evansdale Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 5/2/2019 | |
| 82411 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 6/2/2019 | 2/7/2019 |
| 83573 ES - Evansdale Elementary Facility | CARPENTRY | Floors | Region 2 | 25/02/2019 | |
| 83784 ES - Evansdale Elementary Facility | CARPENTRY | Floors | Region 2 | 27/02/2019 | |
| 86318 ES - Evansdale Elementary Facility | ELECTRICAL | Broken Plug | Region 2 | 21/03/2019 | |
| 86404 ES - Evansdale Elementary Facility | GROUNDS | Trees | Region 2 | 22/03/2019 | |
| 87128 ES - Evansdale Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 26/03/2019 | |
| 87130 ES - Evansdale Elementary Facility | CARPENTRY | Debris | Region 2 | 26/03/2019 | |
| 90738 ES - Evansdale Elementary Facility | GLAZING | Broken Window | Region 2 | 30/04/2019 | 5/5/2019 |
| , , | | | - | | |

| 92309 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 8/5/2019 | |
|--|----------------------|----------------------|----------|------------|------------|
| 92651 ES - Evansdale Elementary Facility | ROOF | Roof Leak | Region 2 | 13/05/2019 | |
| 92652 ES - Evansdale Elementary Facility | ROOF | Standing Water | Region 2 | 13/05/2019 | |
| 92765 ES - Evansdale Elementary Facility | CARPENTRY | Floors | Region 2 | 14/05/2019 | |
| 94098 ES - Evansdale Elementary Facility | CARPENTRY | Move Items | Region 2 | 31/05/2019 | |
| 95287 ES - Evansdale Elementary Facility | ELECTRICAL | Ceilings | Region 2 | 5/6/2019 | 6/10/2019 |
| 95289 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 5/6/2019 | 6/10/2019 |
| 95627 ES - Evansdale Elementary Facility | CARPENTRY | Doors | Region 2 | 10/6/2019 | |
| 95634 ES - Evansdale Elementary Facility | ROOF | Roof Leak | Region 2 | 10/6/2019 | |
| 95702 ES - Evansdale Elementary Facility | CARPENTRY | Floors | Region 2 | 11/6/2019 | |
| 95829 ES - Evansdale Elementary Facility | PLUMBING | Standing Water | Region 2 | 13/06/2019 | |
| 96480 ES - Evansdale Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 24/06/2019 | |
| 96566 ES - Evansdale Elementary Facility | ELECTRICAL | Broken Plug | Region 2 | 25/06/2019 | |
| 96567 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 25/06/2019 | |
| 96568 ES - Evansdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 25/06/2019 | |
| 96725 ES - Evansdale Elementary Facility | ELECTRICAL | No Power | Region 2 | 26/06/2019 | 7/12/2019 |
| 96752 ES - Evansdale Elementary Facility | HVAC | Room Too Hot | Region 2 | 27/06/2019 | 7/2/2019 |
| 98742 ES - Evansdale Elementary Facility | CARPENTRY | Ceilings | Region 2 | 15/07/2019 | |
| 98759 ES - Evansdale Elementary Facility | CARPENTRY | Ceilings | Region 2 | 15/07/2019 | |
| 60914 ES - Fernbank Elementary Facility | CARPENTRY | Floors | Region 2 | 31/07/2018 | |
| 69770 ES - Fernbank Elementary Facility | HVAC | Room Too Hot | Region 2 | 28/09/2018 | |
| 74923 ES - Fernbank Elementary Facility | FIRE SAFETY | Extinguisher | Region 2 | 9/11/2018 | |
| 75140 ES - Fernbank Elementary Facility | ROOF | Ceilings | Region 2 | 13/11/2018 | |
| 77136 ES - Fernbank Elementary Facility | GLAZING | Broken Window | Region 2 | 10/12/2018 | 12/11/2018 |
| 78962 ES - Fernbank Elementary Facility | MECHANICAL EQUIPMENT | Pressure Washing | Region 2 | 3/1/2019 | |
| 80367 ES - Fernbank Elementary Facility | GLAZING | Broken Window | Region 2 | 18/01/2019 | |
| 80550 ES - Fernbank Elementary Facility | CARPENTRY | Structure | Region 2 | 22/01/2019 | |
| 80689 ES - Fernbank Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 23/01/2019 | |
| 82715 ES - Fernbank Elementary Facility | CARPENTRY | Floors | Region 2 | 11/2/2019 | |
| 83150 ES - Fernbank Elementary Facility | ELECTRICAL | Water Leak | Region 2 | 20/02/2019 | |
| 84796 ES - Fernbank Elementary Facility | CARPENTRY | Doors | Region 2 | 4/3/2019 | |
| 85709 ES - Fernbank Elementary Facility | ROOF | Roof Leak | Region 2 | 14/03/2019 | |
| 86028 ES - Fernbank Elementary Facility | FURNISHING | Miscellaneous | Region 2 | 19/03/2019 | |
| 86961 ES - Fernbank Elementary Facility | CARPENTRY | Doors | Region 2 | 25/03/2019 | |
| 88819 ES - Fernbank Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 2 | 10/4/2019 | |
| 89706 ES - Fernbank Elementary Facility | FURNISHING | Structure | Region 2 | 19/04/2019 | |
| 89786 ES - Fernbank Elementary Facility | CARPENTRY | Doors | Region 2 | 19/04/2019 | |
| 90490 ES - Fernbank Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 26/04/2019 | 5/1/2019 |
| 90674 ES - Fernbank Elementary Facility | CARPENTRY | Doors | Region 2 | 29/04/2019 | 5/4/2019 |
| 92474 ES - Fernbank Elementary Facility | HVAC | Room Too Hot | Region 2 | 10/5/2019 | |
| | | | | | |

| | 92480 ES - Fernbank Elementary Facility | HVAC | Room Too Hot | Region 2 | 10/5/2019 | |
|-------|---|-----------------------------|------------------|----------|------------|-----------|
| | 96545 ES - Fernbank Elementary Facility | CARPENTRY | Floors | Region 2 | 24/06/2019 | 7/12/2019 |
| | 96559 ES - Fernbank Elementary Facility | HVAC | Water Leak | Region 2 | 24/06/2019 | |
| | 96601 ES - Fernbank Elementary Facility | HVAC | Room Too Hot | Region 2 | 25/06/2019 | |
| | 96625 ES - Fernbank Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 25/06/2019 | |
| | 96626 ES - Fernbank Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 25/06/2019 | |
| | 97873 ES - Fernbank Elementary Facility | CARPENTRY | Floors | Region 2 | 1/7/2019 | 7/6/2019 |
| | 98316 ES - Fernbank Elementary Facility | CARPENTRY | Broken Window | Region 2 | 9/7/2019 | |
| | 98388 ES - Fernbank Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 2 | 10/7/2019 | |
| | 98389 ES - Fernbank Elementary Facility | KITCHEN EQUIPMENT | | Region 2 | 10/7/2019 | |
| | 98698 ES - Fernbank Elementary Facility | GROUNDS | Trees | Region 2 | 15/07/2019 | |
| M-580 | ES - Fernbank Elementary Facility | CARPENTRY | | Region 2 | 25/06/2018 | |
| | 62324 ES - Hawthorne Elementary Facility | HOUSEKEEPING | | Region 2 | 2/8/2018 | |
| | 77970 ES - Hawthorne Elementary Facility | CARPENTRY | Water Leak | Region 2 | 21/12/2018 | |
| | 89170 ES - Hawthorne Elementary Facility | ROOF | Roof Leak | Region 2 | 12/4/2019 | |
| | 89690 ES - Hawthorne Elementary Facility | ROOF | Roof Leak | Region 2 | 19/04/2019 | |
| | 89707 ES - Hawthorne Elementary Facility | ROOF | Roof Leak | Region 2 | 19/04/2019 | |
| | 92493 ES - Hawthorne Elementary Facility | HVAC | Miscellaneous | Region 2 | 10/5/2019 | |
| | 92820 ES - Hawthorne Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 15/05/2019 | |
| | 92822 ES - Hawthorne Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 15/05/2019 | |
| | 98005 ES - Hawthorne Elementary Facility | HVAC | Water Leak | Region 2 | 3/7/2019 | |
| | 76757 ES - Henderson Mill Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 5/12/2018 | |
| | 80555 ES - Henderson Mill Elementary Facility | CARPENTRY | Doors | Region 2 | 22/01/2019 | |
| | 83164 ES - Henderson Mill Elementary Facility | GLAZING | Miscellaneous | Region 2 | 20/02/2019 | |
| | 86120 ES - Henderson Mill Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 20/03/2019 | |
| | 89779 ES - Henderson Mill Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| | 90417 ES - Henderson Mill Elementary Facility | PLUMBING | Water Leak | Region 2 | 26/04/2019 | 5/1/2019 |
| | 91983 ES - Henderson Mill Elementary Facility | ELECTRICAL | Exit SIgns | Region 2 | 3/5/2019 | 5/8/2019 |
| | 92876 ES - Henderson Mill Elementary Facility | CARPENTRY | Structure | Region 2 | 15/05/2019 | |
| | 92877 ES - Henderson Mill Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 15/05/2019 | |
| | 92879 ES - Henderson Mill Elementary Facility | CARPENTRY | Floors | Region 2 | 15/05/2019 | |
| | 92880 ES - Henderson Mill Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 15/05/2019 | |
| | 93813 ES - Henderson Mill Elementary Facility | PLUMBING | Faucet Dripping | Region 2 | 29/05/2019 | 6/3/2019 |
| | 93817 ES - Henderson Mill Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 29/05/2019 | 6/3/2019 |
| | 93823 ES - Henderson Mill Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 29/05/2019 | 6/3/2019 |
| | 95767 ES - Henderson Mill Elementary Facility | ROOF | Roof Leak | Region 2 | 12/6/2019 | |
| | 95769 ES - Henderson Mill Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 12/6/2019 | |
| | 95773 ES - Henderson Mill Elementary Facility | HAZARDOUS | Water Leak | Region 2 | 12/6/2019 | |
| | 96543 ES - Henderson Mill Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 24/06/2019 | 7/12/2019 |
| | 96792 ES - Henderson Mill Elementary Facility | GROUNDS | Trees | Region 2 | 27/06/2019 | 7/2/2019 |
| | | | | | | |

| | | | | . /= / | = 1010010 |
|---|-----------------------------|-------------------|----------|--------------|-----------|
| 97870 ES - Henderson Mill Elementary Facility | FIRE SAFETY | Fire Alarm | Region 2 | 1/7/2019 | 7/6/2019 |
| 98289 ES - Henderson Mill Elementary Facility | FIRE SAFETY | Alarm Systems | Region 2 | 9/7/2019 | |
| 98718 ES - Henderson Mill Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 15/07/2019 | |
| 98720 ES - Henderson Mill Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 15/07/2019 | |
| 98721 ES - Henderson Mill Elementary Facility | CARPENTRY | Structure | Region 2 | 15/07/2019 | |
| 98737 ES - Henderson Mill Elementary Facility | HVAC | Room Too Hot | Region 2 | 15/07/2019 | |
| 98824 ES - Henderson Mill Elementary Facility | | Room Too Hot | Region 2 | 16/07/2019 | |
| 75032 ES - Idlewood Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 12/11/2018 | |
| 78996 ES - Idlewood Elementary Facility | ELECTRICAL | Water Leak | Region 2 | 4/1/2019 | |
| 83105 ES - Idlewood Elementary Facility | ROOF | Water Leak | Region 2 | 19/02/2019 | |
| 83129 ES - Idlewood Elementary Facility | CARPENTRY | Floors | Region 2 | 19/02/2019 | |
| 83243 ES - Idlewood Elementary Facility | HVAC | Room Too Cold | Region 2 | 20/02/2019 | |
| 83703 ES - Idlewood Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 26/02/2019 | |
| 85437 ES - Idlewood Elementary Facility | ELECTRICAL | Bad Odor | Region 2 | 11/3/2019 | |
| 86406 ES - Idlewood Elementary Facility | CARPENTRY | | Region 2 | 22/03/2019 | |
| 89119 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 12/4/2019 | |
| 89120 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 12/4/2019 | |
| 89504 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 17/04/2019 | |
| 89515 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 17/04/2019 | |
| 89596 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 18/04/2019 | |
| 89603 ES - Idlewood Elementary Facility | INSPECTION | Mold | Region 2 | 18/04/2019 | |
| 91479 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 1/5/2019 | 5/6/2019 |
| 91480 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 1/5/2019 | 5/6/2019 |
| 91543 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 1/5/2019 | 5/6/2019 |
| 91894 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 2/5/2019 | 5/7/2019 |
| 91900 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 2/5/2019 | 5/7/2019 |
| 92390 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 9/5/2019 | |
| 92696 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 13/05/2019 | |
| 92705 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 13/05/2019 | |
| 92977 ES - Idlewood Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 17/05/2019 | |
| 93313 ES - Idlewood Elementary Facility | GLAZING | Miscellaneous | Region 2 | 21/05/2019 | |
| 93328 ES - Idlewood Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 2 | 21/05/2019 | |
| 95260 ES - Idlewood Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 4/6/2019 | 6/9/2019 |
| 95300 ES - Idlewood Elementary Facility | ROOF | Roof Leak | Region 2 | 5/6/2019 | 6/10/2019 |
| 95976 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 17/06/2019 | |
| 96302 ES - Idlewood Elementary Facility | ELECTRICAL | No Power | Region 2 | 20/06/2019 | |
| 96497 ES - Idlewood Elementary Facility | HVAC | Room Too Hot | Region 2 | 24/06/2019 | |
| 96579 ES - Idlewood Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 25/06/2019 | |
| 98520 ES - Idlewood Elementary Facility | PLUMBING | Structure | Region 2 | 11/7/2019 | |
| 98792 ES - Idlewood Elementary Facility | | Compactor / Trash | Region 2 | 16/07/2019 | |
| | | 22pasto. /asii | | _5, 5., _515 | |

| 53927 ES - Laurel Ridge Elementary Facility | ADMINSTRATIVE | | Region 2 | 7/5/2018 | 5/8/2018 |
|---|-------------------|-------------------|----------|------------|-----------|
| 68885 ES - Laurel Ridge Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 18/09/2018 | |
| 74500 ES - Laurel Ridge Elementary Facility | ROOF | Miscellaneous | Region 2 | 5/11/2018 | |
| 81225 ES - Laurel Ridge Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 30/01/2019 | |
| 82593 ES - Laurel Ridge Elementary Facility | ROOF | Ceilings | Region 2 | 8/2/2019 | |
| 87242 ES - Laurel Ridge Elementary Facility | ELECTRICAL | | Region 2 | 28/03/2019 | |
| 88386 ES - Laurel Ridge Elementary Facility | HAZARDOUS | | Region 2 | 2/4/2019 | 4/2/2019 |
| 88387 ES - Laurel Ridge Elementary Facility | HAZARDOUS | | Region 2 | 2/4/2019 | 4/2/2019 |
| 89434 ES - Laurel Ridge Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 16/04/2019 | |
| 89655 ES - Laurel Ridge Elementary Facility | HOUSEKEEPING | Water Leak | Region 2 | 18/04/2019 | |
| 89742 ES - Laurel Ridge Elementary Facility | PEST CONTROL | Water Leak | Region 2 | 19/04/2019 | |
| 90930 ES - Laurel Ridge Elementary Facility | HVAC | | Region 2 | 1/5/2019 | 5/6/2019 |
| 95324 ES - Laurel Ridge Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 5/6/2019 | 6/10/2019 |
| 96180 ES - Laurel Ridge Elementary Facility | ELECTRICAL | | Region 2 | 19/06/2019 | |
| 96564 ES - Laurel Ridge Elementary Facility | KITCHEN EQUIPMENT | | Region 2 | 25/06/2019 | |
| 96774 ES - Laurel Ridge Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 27/06/2019 | 7/2/2019 |
| 97923 ES - Laurel Ridge Elementary Facility | HVAC | Water Leak | Region 2 | 2/7/2019 | 7/7/2019 |
| 98246 ES - Laurel Ridge Elementary Facility | GROUNDS | Grass | Region 2 | 8/7/2019 | |
| 98284 ES - Laurel Ridge Elementary Facility | HVAC | Room Too Hot | Region 2 | 9/7/2019 | |
| 98707 ES - Laurel Ridge Elementary Facility | ELECTRICAL | Freezer / Cooler | Region 2 | 15/07/2019 | |
| 69275 ES - Livsey Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 21/09/2018 | |
| 74748 ES - Livsey Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 7/11/2018 | |
| 80116 ES - Livsey Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 17/01/2019 | |
| 80117 ES - Livsey Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 17/01/2019 | |
| 82236 ES - Livsey Elementary Facility | ELECTRICAL | No Power | Region 2 | 4/2/2019 | |
| 82366 ES - Livsey Elementary Facility | HVAC | Water Leak | Region 2 | 6/2/2019 | |
| 82603 ES - Livsey Elementary Facility | ELECTRICAL | No Power | Region 2 | 8/2/2019 | |
| 83258 ES - Livsey Elementary Facility | HVAC | Broken Equipment | Region 2 | 20/02/2019 | |
| 85649 ES - Livsey Elementary Facility | WAREHOUSE | Lights Out | Region 2 | 13/03/2019 | |
| 87133 ES - Livsey Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 26/03/2019 | |
| 88792 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 9/4/2019 | |
| 88878 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 10/4/2019 | |
| 89113 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 12/4/2019 | |
| 89712 ES - Livsey Elementary Facility | FURNISHING | Roof Leak | Region 2 | 19/04/2019 | |
| 89744 ES - Livsey Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| 89746 ES - Livsey Elementary Facility | CARPENTRY | Cove Base | Region 2 | 19/04/2019 | |
| 89767 ES - Livsey Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| 90350 ES - Livsey Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 25/04/2019 | |
| 91118 ES - Livsey Elementary Facility | CARPENTRY | Decking | Region 2 | 1/5/2019 | 5/6/2019 |
| 92757 ES - Livsey Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 14/05/2019 | |
| | | | | | |

| 93476 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 23/05/2019 | |
|---|-----------------------------|------------------|----------|------------|-----------|
| 93493 ES - Livsey Elementary Facility | WAREHOUSE | Miscellaneous | Region 2 | 23/05/2019 | |
| 93503 ES - Livsey Elementary Facility | CARPENTRY | Move Items | Region 2 | 23/05/2019 | |
| 93844 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 29/05/2019 | 6/3/2019 |
| 93846 ES - Livsey Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 29/05/2019 | 6/3/2019 |
| 93896 ES - Livsey Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 30/05/2019 | |
| 94060 ES - Livsey Elementary Facility | HVAC | Broken Equipment | Region 2 | 31/05/2019 | 6/5/2019 |
| 94061 ES - Livsey Elementary Facility | CARPENTRY | Floors | Region 2 | 31/05/2019 | 6/5/2019 |
| 94065 ES - Livsey Elementary Facility | CARPENTRY | Decking | Region 2 | 31/05/2019 | |
| 94069 ES - Livsey Elementary Facility | PLUMBING | Faucet Dripping | Region 2 | 31/05/2019 | |
| 94071 ES - Livsey Elementary Facility | ELECTRICAL | Broken Equipment | Region 2 | 31/05/2019 | |
| 94073 ES - Livsey Elementary Facility | CARPENTRY | Floors | Region 2 | 31/05/2019 | |
| 94074 ES - Livsey Elementary Facility | CARPENTRY | Paint | Region 2 | 31/05/2019 | |
| 95112 ES - Livsey Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 3/6/2019 | |
| 95152 ES - Livsey Elementary Facility | HVAC | Roof Leak | Region 2 | 3/6/2019 | 6/8/2019 |
| 95169 ES - Livsey Elementary Facility | PEST CONTROL | Pest | Region 2 | 3/6/2019 | 6/8/2019 |
| 95638 ES - Livsey Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 10/6/2019 | |
| 95755 ES - Livsey Elementary Facility | ROOF | Roof Leak | Region 2 | 12/6/2019 | |
| 96127 ES - Livsey Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 18/06/2019 | |
| 96128 ES - Livsey Elementary Facility | ELECTRICAL | Deliver Material | Region 2 | 18/06/2019 | |
| 96546 ES - Livsey Elementary Facility | HVAC | Miscellaneous | Region 2 | 24/06/2019 | 7/12/2019 |
| 96558 ES - Livsey Elementary Facility | CARPENTRY | Cove Base | Region 2 | 24/06/2019 | |
| 97932 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 2/7/2019 | 7/7/2019 |
| 97935 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 2/7/2019 | 7/7/2019 |
| 98380 ES - Livsey Elementary Facility | HVAC | Room Too Hot | Region 2 | 9/7/2019 | |
| 98512 ES - Livsey Elementary Facility | FIRE SAFETY | Alarm Systems | Region 2 | 11/7/2019 | |
| 98683 ES - Livsey Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 15/07/2019 | |
| 98741 ES - Livsey Elementary Facility | CARPENTRY | Whiteboards | Region 2 | 15/07/2019 | |
| 98799 ES - Livsey Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 16/07/2019 | |
| 98829 ES - Livsey Elementary Facility | | Pest | Region 2 | 16/07/2019 | |
| 41907 ES - McLendon Elementary Facility | PAINTING / PRESSURE WASHING | | Region 2 | 23/01/2018 | |
| 58256 ES - McLendon Elementary Facility | CARPENTRY | | Region 2 | 27/06/2018 | |
| 62499 ES - McLendon Elementary Facility | GROUNDS | | Region 2 | 3/8/2018 | |
| 62975 ES - McLendon Elementary Facility | HVAC | Broken Equipment | Region 2 | 7/8/2018 | |
| 62985 ES - McLendon Elementary Facility | ENVIRONMENTAL SVCS | Discoloration | Region 2 | 7/8/2018 | |
| 63792 ES - McLendon Elementary Facility | ROOF | Broken Equipment | Region 2 | 13/08/2018 | |
| 71066 ES - McLendon Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 4/10/2018 | |
| 71389 ES - McLendon Elementary Facility | CARPENTRY | Discoloration | Region 2 | 9/10/2018 | |
| 71551 ES - McLendon Elementary Facility | ROOF | Roof Leak | Region 2 | 11/10/2018 | |
| 74440 ES - McLendon Elementary Facility | HVAC | Broken Equipment | Region 2 | 5/11/2018 | |
| | | * | | | |

| 75095 ES - McLendon Elementary Facility | ROOF | Roof Leak | Region 2 | 12/11/2018 | |
|---|-----------------------------|--------------------|----------|------------|-----------|
| 79132 ES - McLendon Elementary Facility | ROOF | Roof Leak | Region 2 | 7/1/2019 | |
| 80802 ES - McLendon Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 2 | 24/01/2019 | |
| 82801 ES - McLendon Elementary Facility | ELECTRICAL | Water Leak | Region 2 | 12/2/2019 | |
| 84979 ES - McLendon Elementary Facility | ROOF | | Region 2 | 5/3/2019 | 3/5/2019 |
| 85388 ES - McLendon Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 11/3/2019 | |
| 89420 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 16/04/2019 | |
| 89763 ES - McLendon Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| 89994 ES - McLendon Elementary Facility | ROOF | Roof Leak | Region 2 | 22/04/2019 | |
| 92152 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 6/5/2019 | 5/11/2019 |
| 93160 ES - McLendon Elementary Facility | HVAC | Room Too Hot | Region 2 | 20/05/2019 | |
| 93175 ES - McLendon Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 20/05/2019 | |
| 93365 ES - McLendon Elementary Facility | ELECTRICAL | Freezer / Cooler | Region 2 | 22/05/2019 | |
| 94083 ES - McLendon Elementary Facility | LOCKSMITH | Doors | Region 2 | 31/05/2019 | 6/5/2019 |
| 95331 ES - McLendon Elementary Facility | GROUNDS | Broken Equipment | Region 2 | 5/6/2019 | 6/10/2019 |
| 96141 ES - McLendon Elementary Facility | FIRE SAFETY | Fire Alarm | Region 2 | 18/06/2019 | |
| 96306 ES - McLendon Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 20/06/2019 | 8/2/2019 |
| 96319 ES - McLendon Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 20/06/2019 | |
| 96500 ES - McLendon Elementary Facility | PLUMBING | Toilet Overflowing | Region 2 | 24/06/2019 | |
| 96637 ES - McLendon Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 25/06/2019 | |
| 96678 ES - McLendon Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 26/06/2019 | 7/1/2019 |
| 97866 ES - McLendon Elementary Facility | HVAC | Broken Equipment | Region 2 | 1/7/2019 | 7/6/2019 |
| 97913 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 1/7/2019 | 7/6/2019 |
| 98536 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 11/7/2019 | |
| 98537 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 11/7/2019 | |
| 98538 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 11/7/2019 | |
| 98539 ES - McLendon Elementary Facility | CARPENTRY | Doors | Region 2 | 11/7/2019 | |
| 98851 ES - McLendon Elementary Facility | FIRE SAFETY | Fire Alarm | Region 2 | 16/07/2019 | |
| 55522 ES - Midvale Elementary Facility | ROOF | | Region 2 | 29/05/2018 | |
| 64657 ES - Midvale Elementary Facility | CARPENTRY | Ceilings | Region 2 | 21/08/2018 | |
| 65740 ES - Midvale Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 30/08/2018 | |
| 72080 ES - Midvale Elementary Facility | INSULATION | Miscellaneous | Region 2 | 17/10/2018 | |
| 72202 ES - Midvale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 18/10/2018 | |
| 79025 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 4/1/2019 | |
| 80352 ES - Midvale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 18/01/2019 | |
| 82178 ES - Midvale Elementary Facility | HVAC | Roof Leak | Region 2 | 4/2/2019 | |
| 82179 ES - Midvale Elementary Facility | CARPENTRY | Doors | Region 2 | 4/2/2019 | |
| 82537 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 7/2/2019 | |
| 83165 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 20/02/2019 | |
| 83278 ES - Midvale Elementary Facility | ROOF | Ceilings | Region 2 | 21/02/2019 | |
| | | | | | |

| 85227 ES - Midvale Elementary Facility | FIRE SAFETY | Miscellaneous | Region 2 | 7/3/2019 | |
|--|-----------------------------|------------------|----------|------------|-----------|
| 86328 ES - Midvale Elementary Facility | HVAC | Miscellaneous | Region 2 | 21/03/2019 | |
| 87176 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 27/03/2019 | |
| 89783 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 19/04/2019 | |
| 89785 ES - Midvale Elementary Facility | CARPENTRY | Floors | Region 2 | 19/04/2019 | |
| 89788 ES - Midvale Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| 89789 ES - Midvale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 19/04/2019 | |
| 89949 ES - Midvale Elementary Facility | MECHANICAL EQUIPMENT | Miscellaneous | Region 2 | 22/04/2019 | |
| 92155 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 6/5/2019 | 5/11/2019 |
| 92486 ES - Midvale Elementary Facility | CARPENTRY | Doors | Region 2 | 10/5/2019 | |
| 92797 ES - Midvale Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 14/05/2019 | |
| 95147 ES - Midvale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 3/6/2019 | 6/8/2019 |
| 95149 ES - Midvale Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 3/6/2019 | 6/8/2019 |
| 95299 ES - Midvale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 5/6/2019 | 6/10/2019 |
| 95789 ES - Midvale Elementary Facility | CARPENTRY | Standing Water | Region 2 | 12/6/2019 | |
| 96362 ES - Midvale Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 21/06/2019 | |
| 96551 ES - Midvale Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 24/06/2019 | 7/12/2019 |
| 96714 ES - Midvale Elementary Facility | PLUMBING | Water Leak | Region 2 | 26/06/2019 | |
| 96715 ES - Midvale Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 26/06/2019 | 7/1/2019 |
| 96806 ES - Midvale Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 27/06/2019 | 7/2/2019 |
| 97956 ES - Midvale Elementary Facility | HVAC | Supplies Needed | Region 2 | 2/7/2019 | 7/7/2019 |
| 97957 ES - Midvale Elementary Facility | GROUNDS | Grass | Region 2 | 2/7/2019 | 7/7/2019 |
| 98202 ES - Midvale Elementary Facility | HVAC | Room Too Hot | Region 2 | 8/7/2019 | |
| 98204 ES - Midvale Elementary Facility | HVAC | Water Leak | Region 2 | 8/7/2019 | |
| 98374 ES - Midvale Elementary Facility | HVAC | Room Too Hot | Region 2 | 9/7/2019 | |
| 98503 ES - Midvale Elementary Facility | ROOF | Roof Leak | Region 2 | 11/7/2019 | |
| 98833 ES - Midvale Elementary Facility | | Miscellaneous | Region 2 | 16/07/2019 | |
| 55665 ES - Oak Grove Elementary Facility | CARPENTRY | | Region 2 | 30/05/2018 | |
| 55666 ES - Oak Grove Elementary Facility | CARPENTRY | | Region 2 | 30/05/2018 | |
| 62449 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 3/8/2018 | |
| 63506 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 9/8/2018 | |
| 74359 ES - Oak Grove Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 2/11/2018 | |
| 74925 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 9/11/2018 | |
| 76199 ES - Oak Grove Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 30/11/2018 | |
| 79103 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 7/1/2019 | |
| 82860 ES - Oak Grove Elementary Facility | ROOF | Standing Water | Region 2 | 12/2/2019 | |
| 83221 ES - Oak Grove Elementary Facility | HVAC | Water Leak | Region 2 | 20/02/2019 | |
| 84957 ES - Oak Grove Elementary Facility | ELECTRICAL | Miscellaneous | Region 2 | 5/3/2019 | |
| 85477 ES - Oak Grove Elementary Facility | CARPENTRY | Structure | Region 2 | 12/3/2019 | |
| 87092 ES - Oak Grove Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 26/03/2019 | |
| | | | | | |

| 89713 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 19/04/2019 | |
|--|-----------------------------|------------------|----------|------------|-----------|
| 89714 ES - Oak Grove Elementary Facility | FURNISHING | Standing Water | Region 2 | 19/04/2019 | |
| 91838 ES - Oak Grove Elementary Facility | GROUNDS | Broken Equipment | Region 2 | 2/5/2019 | 5/7/2019 |
| 92392 ES - Oak Grove Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 9/5/2019 | |
| 92431 ES - Oak Grove Elementary Facility | CARPENTRY | Floors | Region 2 | 9/5/2019 | |
| 92505 ES - Oak Grove Elementary Facility | CARPENTRY | Floors | Region 2 | 10/5/2019 | |
| 92821 ES - Oak Grove Elementary Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 2 | 15/05/2019 | |
| 92894 ES - Oak Grove Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 15/05/2019 | |
| 93345 ES - Oak Grove Elementary Facility | CARPENTRY | Locks / Keys | Region 2 | 21/05/2019 | |
| 95684 ES - Oak Grove Elementary Facility | INSPECTION | Water Leak | Region 2 | 11/6/2019 | |
| 95685 ES - Oak Grove Elementary Facility | INSPECTION | Water Leak | Region 2 | 11/6/2019 | |
| 95686 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95688 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95690 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95691 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95692 ES - Oak Grove Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95693 ES - Oak Grove Elementary Facility | INSPECTION | Roof Leak | Region 2 | 11/6/2019 | |
| 95696 ES - Oak Grove Elementary Facility | CARPENTRY | Floors | Region 2 | 11/6/2019 | |
| 95699 ES - Oak Grove Elementary Facility | PLUMBING | Bad Odor | Region 2 | 11/6/2019 | |
| 95703 ES - Oak Grove Elementary Facility | CARPENTRY | Ceilings | Region 2 | 11/6/2019 | |
| 95714 ES - Oak Grove Elementary Facility | CARPENTRY | Whiteboards | Region 2 | 11/6/2019 | |
| 95716 ES - Oak Grove Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 11/6/2019 | |
| 95717 ES - Oak Grove Elementary Facility | CARPENTRY | Floors | Region 2 | 11/6/2019 | |
| 95718 ES - Oak Grove Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 11/6/2019 | |
| 95719 ES - Oak Grove Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 11/6/2019 | |
| 95720 ES - Oak Grove Elementary Facility | CARPENTRY | Ceilings | Region 2 | 11/6/2019 | |
| 95722 ES - Oak Grove Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 11/6/2019 | |
| 95834 ES - Oak Grove Elementary Facility | WAREHOUSE | Miscellaneous | Region 2 | 13/06/2019 | |
| 95835 ES - Oak Grove Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 13/06/2019 | |
| 96624 ES - Oak Grove Elementary Facility | CARPENTRY | Broken Equipment | Region 2 | 25/06/2019 | |
| 96674 ES - Oak Grove Elementary Facility | ELECTRICAL | No Power | Region 2 | 26/06/2019 | 7/12/2019 |
| 96696 ES - Oak Grove Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 26/06/2019 | 7/12/2019 |
| 96739 ES - Oak Grove Elementary Facility | ROOF | Water Leak | Region 2 | 27/06/2019 | 7/2/2019 |
| 96748 ES - Oak Grove Elementary Facility | CARPENTRY | Floors | Region 2 | 27/06/2019 | 7/2/2019 |
| 96754 ES - Oak Grove Elementary Facility | HVAC | Ceilings | Region 2 | 27/06/2019 | 7/12/2019 |
| 97989 ES - Oak Grove Elementary Facility | HVAC | Water Leak | Region 2 | 3/7/2019 | 7/8/2019 |
| 98278 ES - Oak Grove Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 9/7/2019 | |
| 98801 ES - Oak Grove Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 16/07/2019 | |
| 98810 ES - Oak Grove Elementary Facility | | Floors | Region 2 | 16/07/2019 | |
| 98811 ES - Oak Grove Elementary Facility | | Floors | Region 2 | 16/07/2019 | |
| | | | | | |

| | S - Oak Grove Elementary Facility | CARPENTRY | | Region 2 | 20/06/2018 | |
|---------|--|-----------------------------|--------------------|----------|------------|-----------|
| | S - Pleasantdale Elementary Facility | ELECTRICAL | | Region 2 | 31/01/2019 | |
| | S - Pleasantdale Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 5/5/2019 | 5/10/2019 |
| 92998 E | S - Pleasantdale Elementary Facility | PLUMBING | Miscellaneous | Region 2 | 17/05/2019 | |
| 96342 E | S - Pleasantdale Elementary Facility | PEST CONTROL | Pest | Region 2 | 20/06/2019 | |
| 96343 E | S - Pleasantdale Elementary Facility | LOCKSMITH | Locks / Keys | Region 2 | 20/06/2019 | |
| | S - Pleasantdale Elementary Facility | PLUMBING | Toilet Overflowing | Region 2 | 1/7/2019 | 7/6/2019 |
| 41880 E | S - Sagamore Hills Elementary Facility | ELECTRICAL | | Region 2 | 23/01/2018 | |
| 56731 E | S - Sagamore Hills Elementary Facility | ELECTRONICS | | Region 2 | 1/6/2018 | |
| 75117 E | S - Sagamore Hills Elementary Facility | ROOF | Roof Leak | Region 2 | 12/11/2018 | |
| 83069 E | S - Sagamore Hills Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 2 | 19/02/2019 | |
| 84783 E | S - Sagamore Hills Elementary Facility | ROOF | Water Leak | Region 2 | 4/3/2019 | 3/5/2019 |
| 87095 E | S - Sagamore Hills Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 26/03/2019 | |
| 87097 E | S - Sagamore Hills Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 26/03/2019 | |
| 89073 E | S - Sagamore Hills Elementary Facility | WAREHOUSE | | Region 2 | 12/4/2019 | |
| 89724 E | S - Sagamore Hills Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| 89793 E | S - Sagamore Hills Elementary Facility | ROOF | Water Leak | Region 2 | 19/04/2019 | |
| 90128 E | S - Sagamore Hills Elementary Facility | ROOF | Water Leak | Region 2 | 23/04/2019 | |
| 92327 E | S - Sagamore Hills Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 8/5/2019 | |
| 93174 E | S - Sagamore Hills Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 20/05/2019 | |
| 93711 E | S - Sagamore Hills Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 28/05/2019 | 6/2/2019 |
| 93791 E | S - Sagamore Hills Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 28/05/2019 | 6/2/2019 |
| 93902 E | S - Sagamore Hills Elementary Facility | ROOF | | Region 2 | 30/05/2019 | 6/4/2019 |
| 95346 E | S - Sagamore Hills Elementary Facility | PLUMBING | Water Leak | Region 2 | 5/6/2019 | |
| 95347 E | S - Sagamore Hills Elementary Facility | PLUMBING | Water Leak | Region 2 | 5/6/2019 | |
| 96712 E | S - Sagamore Hills Elementary Facility | ELECTRICAL | No Power | Region 2 | 26/06/2019 | 7/12/2019 |
| 97875 E | S - Sagamore Hills Elementary Facility | HVAC | Miscellaneous | Region 2 | 1/7/2019 | 7/6/2019 |
| 98212 E | S - Sagamore Hills Elementary Facility | HVAC | Room Too Hot | Region 2 | 8/7/2019 | |
| 98214 E | S - Sagamore Hills Elementary Facility | GROUNDS | Miscellaneous | Region 2 | 8/7/2019 | |
| 98219 E | S - Sagamore Hills Elementary Facility | PLUMBING | | Region 2 | 8/7/2019 | 7/9/2019 |
| 98239 E | S - Sagamore Hills Elementary Facility | ROOF | Roof Leak | Region 2 | 8/7/2019 | |
| 98241 E | S - Sagamore Hills Elementary Facility | CARPENTRY | Ceilings | Region 2 | 8/7/2019 | |
| 98487 E | S - Sagamore Hills Elementary Facility | ELECTRICAL | No Power | Region 2 | 11/7/2019 | |
| 98694 E | S - Sagamore Hills Elementary Facility | PAINTING / PRESSURE WASHING | | Region 2 | 15/07/2019 | |
| 98744 E | S - Sagamore Hills Elementary Facility | CARPENTRY | Miscellaneous | Region 2 | 15/07/2019 | |
| 98758 E | S - Sagamore Hills Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 15/07/2019 | |
| 98760 E | S - Sagamore Hills Elementary Facility | WASTE MANAGEMENT | Miscellaneous | Region 2 | 15/07/2019 | |
| 98778 E | S - Sagamore Hills Elementary Facility | ELECTRICAL | | Region 2 | 16/07/2019 | |
| 63451 E | S - Smoke Rise Elementary Facility | CARPENTRY | Floors | Region 2 | 9/8/2018 | |
| 71765 E | S - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 15/10/2018 | |
| | | | | | | |

| 71766 ES - Smoke Rise Elementary Facility | ROOF | Roof Leak | Region 2 | 15/10/2018 | |
|---|-----------------------------|------------------|----------|------------|----------|
| 75135 ES - Smoke Rise Elementary Facility | ROOF | Roof Leak | Region 2 | 13/11/2018 | |
| 77878 ES - Smoke Rise Elementary Facility | ROOF | Roof Leak | Region 2 | 20/12/2018 | |
| 79501 ES - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 9/1/2019 | |
| 79503 ES - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 9/1/2019 | |
| 79649 ES - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 11/1/2019 | |
| 80892 ES - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 25/01/2019 | |
| 82441 ES - Smoke Rise Elementary Facility | ELECTRICAL | Broken Plug | Region 2 | 7/2/2019 | |
| 83423 ES - Smoke Rise Elementary Facility | HVAC | Room Too Cold | Region 2 | 22/02/2019 | |
| 83574 ES - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 25/02/2019 | |
| 85054 ES - Smoke Rise Elementary Facility | ELECTRICAL | | Region 2 | 6/3/2019 | 3/6/2019 |
| 88978 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 11/4/2019 | |
| 90354 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 25/04/2019 | |
| 92408 ES - Smoke Rise Elementary Facility | HVAC | | Region 2 | 9/5/2019 | |
| 93293 ES - Smoke Rise Elementary Facility | GLAZING | Broken Equipment | Region 2 | 21/05/2019 | |
| 93538 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 24/05/2019 | |
| 93702 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 28/05/2019 | 6/2/2019 |
| 94031 ES - Smoke Rise Elementary Facility | ELECTRICAL | Lights Out | Region 2 | 31/05/2019 | 6/5/2019 |
| 94033 ES - Smoke Rise Elementary Facility | HVAC | Miscellaneous | Region 2 | 31/05/2019 | 6/5/2019 |
| 94037 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 31/05/2019 | |
| 94038 ES - Smoke Rise Elementary Facility | HVAC | Roof Leak | Region 2 | 31/05/2019 | |
| 95136 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 3/6/2019 | 6/8/2019 |
| 95535 ES - Smoke Rise Elementary Facility | HVAC | Room Too Hot | Region 2 | 10/6/2019 | |
| 95674 ES - Smoke Rise Elementary Facility | ROOF | Roof Leak | Region 2 | 11/6/2019 | |
| 95764 ES - Smoke Rise Elementary Facility | GROUNDS | Lights Out | Region 2 | 12/6/2019 | |
| 95768 ES - Smoke Rise Elementary Facility | HVAC | Miscellaneous | Region 2 | 12/6/2019 | |
| 97939 ES - Smoke Rise Elementary Facility | ELECTRICAL | Broken Plug | Region 2 | 2/7/2019 | 7/7/2019 |
| 97940 ES - Smoke Rise Elementary Facility | CARPENTRY | Cove Base | Region 2 | 2/7/2019 | 7/7/2019 |
| 48194 HS - Druid Hills High Facility | HVAC | | Region 2 | 11/3/2018 | |
| 50613 HS - Druid Hills High Facility | ROOF | | Region 2 | 15/04/2018 | |
| 54387 HS - Druid Hills High Facility | HVAC | | Region 2 | 14/05/2018 | |
| 57054 HS - Druid Hills High Facility | CARPENTRY | | Region 2 | 6/6/2018 | |
| 60205 HS - Druid Hills High Facility | HOUSEKEEPING | | Region 2 | 23/07/2018 | |
| 63295 HS - Druid Hills High Facility | ROOF | Roof Leak | Region 2 | 8/8/2018 | |
| 65111 HS - Druid Hills High Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 2 | 24/08/2018 | |
| 71079 HS - Druid Hills High Facility | HVAC | Broken Plug | Region 2 | 4/10/2018 | |
| 71211 HS - Druid Hills High Facility | HVAC | Room Too Hot | Region 2 | 8/10/2018 | |
| 75077 HS - Druid Hills High Facility | CARPENTRY | Floors | Region 2 | 12/11/2018 | |
| 75553 HS - Druid Hills High Facility | ROOF | Water Leak | Region 2 | 16/11/2018 | |
| 77419 HS - Druid Hills High Facility | ELECTRICAL | Miscellaneous | Region 2 | 12/12/2018 | |
| | | | | | |

| 77662 HS - Druid Hills High Facility | CARPENTRY | Miscellaneous | Region 2 | 17/12/2018 | |
|--------------------------------------|-----------------------------|------------------|----------|------------|-----------|
| 77667 HS - Druid Hills High Facility | PLUMBING | Standing Water | Region 2 | 17/12/2018 | |
| 77840 HS - Druid Hills High Facility | ROOF | Roof Leak | Region 2 | 19/12/2018 | |
| 77841 HS - Druid Hills High Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 19/12/2018 | |
| 77897 HS - Druid Hills High Facility | ROOF | Water Leak | Region 2 | 20/12/2018 | |
| 79313 HS - Druid Hills High Facility | ROOF | Water Leak | Region 2 | 8/1/2019 | |
| 79475 HS - Druid Hills High Facility | ROOF | Roof Leak | Region 2 | 9/1/2019 | 1/10/2019 |
| 80213 HS - Druid Hills High Facility | CARPENTRY | Broken Equipment | Region 2 | 17/01/2019 | |
| 82472 HS - Druid Hills High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 7/2/2019 | |
| 82483 HS - Druid Hills High Facility | GROUNDS | Miscellaneous | Region 2 | 7/2/2019 | |
| 82837 HS - Druid Hills High Facility | CARPENTRY | Structure | Region 2 | 12/2/2019 | |
| 83018 HS - Druid Hills High Facility | CARPENTRY | Broken Equipment | Region 2 | 15/02/2019 | |
| 83698 HS - Druid Hills High Facility | HVAC | Room Too Cold | Region 2 | 26/02/2019 | |
| 84781 HS - Druid Hills High Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 4/3/2019 | |
| 85059 HS - Druid Hills High Facility | CARPENTRY | Miscellaneous | Region 2 | 6/3/2019 | |
| 85229 HS - Druid Hills High Facility | HVAC | Water Leak | Region 2 | 7/3/2019 | 3/8/2019 |
| 86446 HS - Druid Hills High Facility | PEST CONTROL | Pest | Region 2 | 22/03/2019 | |
| 87123 HS - Druid Hills High Facility | KITCHEN EQUIPMENT | Stove / Oven | Region 2 | 26/03/2019 | |
| 87157 HS - Druid Hills High Facility | CARPENTRY | | Region 2 | 26/03/2019 | |
| 89442 HS - Druid Hills High Facility | MECHANICAL EQUIPMENT | Broken Equipment | Region 2 | 16/04/2019 | |
| 89447 HS - Druid Hills High Facility | CARPENTRY | Standing Water | Region 2 | 16/04/2019 | |
| 89459 HS - Druid Hills High Facility | ELECTRICAL | Lights Out | Region 2 | 16/04/2019 | |
| 89801 HS - Druid Hills High Facility | HVAC | Room Too Hot | Region 2 | 19/04/2019 | |
| 90046 HS - Druid Hills High Facility | HOUSEKEEPING | Standing Water | Region 2 | 22/04/2019 | |
| 90088 HS - Druid Hills High Facility | GROUNDS | Structure | Region 2 | 23/04/2019 | |
| 90094 HS - Druid Hills High Facility | GROUNDS | Broken Equipment | Region 2 | 23/04/2019 | |
| 90173 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 23/04/2019 | |
| 90361 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 25/04/2019 | |
| 90434 HS - Druid Hills High Facility | CARPENTRY | Miscellaneous | Region 2 | 26/04/2019 | 5/1/2019 |
| 92168 HS - Druid Hills High Facility | PEST CONTROL | Pest | Region 2 | 6/5/2019 | 5/11/2019 |
| 92182 HS - Druid Hills High Facility | CARPENTRY | Ceilings | Region 2 | 6/5/2019 | 5/11/2019 |
| 92185 HS - Druid Hills High Facility | WASTE MANAGEMENT | Broken Equipment | Region 2 | 6/5/2019 | 5/11/2019 |
| 92517 HS - Druid Hills High Facility | CARPENTRY | Miscellaneous | Region 2 | 10/5/2019 | |
| 92695 HS - Druid Hills High Facility | INSPECTION | Water Leak | Region 2 | 13/05/2019 | |
| 92842 HS - Druid Hills High Facility | GROUNDS | Deliver Material | Region 2 | 15/05/2019 | |
| 92867 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 15/05/2019 | |
| 93401 HS - Druid Hills High Facility | CARPENTRY | Structure | Region 2 | 22/05/2019 | |
| 93411 HS - Druid Hills High Facility | CARPENTRY | Ceilings | Region 2 | 22/05/2019 | |
| 93412 HS - Druid Hills High Facility | CARPENTRY | Ceilings | Region 2 | 22/05/2019 | |
| 93516 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 23/05/2019 | |
| | | | | | |

| | 93786 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 28/05/2019 | 6/2/2019 |
|---|--------------------------------------|----------------------|--------------------|----------|------------|-----------|
| | 95219 HS - Druid Hills High Facility | HVAC | Room Too Hot | Region 2 | 4/6/2019 | 6/9/2019 |
| ć | 95311 HS - Druid Hills High Facility | CARPENTRY | Floors | Region 2 | 5/6/2019 | 6/10/2019 |
| | 95838 HS - Druid Hills High Facility | GROUNDS | Miscellaneous | Region 2 | 13/06/2019 | |
| ç | 96215 HS - Druid Hills High Facility | HVAC | Room Too Hot | Region 2 | 19/06/2019 | |
| ç | 96219 HS - Druid Hills High Facility | HVAC | Room Too Hot | Region 2 | 19/06/2019 | |
| Ģ | 96477 HS - Druid Hills High Facility | HVAC | | Region 2 | 24/06/2019 | |
| Ġ | 97899 HS - Druid Hills High Facility | CARPENTRY | Install | Region 2 | 1/7/2019 | 7/6/2019 |
| Ġ | 97902 HS - Druid Hills High Facility | PLUMBING | Toilet Overflowing | Region 2 | 1/7/2019 | 7/6/2019 |
| Ģ | 97903 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 1/7/2019 | 7/6/2019 |
| Ģ | 97904 HS - Druid Hills High Facility | HVAC | Water Leak | Region 2 | 1/7/2019 | 7/6/2019 |
| 9 | 97905 HS - Druid Hills High Facility | CARPENTRY | Miscellaneous | Region 2 | 1/7/2019 | 7/6/2019 |
| Ģ | 97906 HS - Druid Hills High Facility | GROUNDS | Trees | Region 2 | 1/7/2019 | 7/6/2019 |
| Ç | 97959 HS - Druid Hills High Facility | HVAC | Broken Equipment | Region 2 | 2/7/2019 | 7/7/2019 |
| Ç | 97960 HS - Druid Hills High Facility | HVAC | Broken Equipment | Region 2 | 2/7/2019 | 7/7/2019 |
| Ģ | 97997 HS - Druid Hills High Facility | CARPENTRY | Miscellaneous | Region 2 | 3/7/2019 | 7/8/2019 |
| Ç | 98016 HS - Druid Hills High Facility | MECHANICAL EQUIPMENT | Broken Equipment | Region 2 | 3/7/2019 | 7/12/2019 |
| Ģ | 98049 HS - Druid Hills High Facility | FIRE SAFETY | Fire Alarm | Region 2 | 5/7/2019 | 7/10/2019 |
| Ç | 98200 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 8/7/2019 | |
| Ç | 98207 HS - Druid Hills High Facility | CARPENTRY | Floors | Region 2 | 8/7/2019 | |
| Ç | 98208 HS - Druid Hills High Facility | CARPENTRY | Doors | Region 2 | 8/7/2019 | |
| Ç | 98548 HS - Druid Hills High Facility | CARPENTRY | Locks / Keys | Region 2 | 11/7/2019 | |
| į | 59157 HS - Lakeside High Facility | CARPENTRY | | Region 2 | 5/7/2018 | |
| (| 51000 HS - Lakeside High Facility | CARPENTRY | | Region 2 | 31/07/2018 | |
| - | 72710 HS - Lakeside High Facility | MECHANICAL EQUIPMENT | Miscellaneous | Region 2 | 26/10/2018 | |
| - | 77508 HS - Lakeside High Facility | PLUMBING | Water Leak | Region 2 | 13/12/2018 | |
| 7 | 79717 HS - Lakeside High Facility | LOCKSMITH | Locks / Keys | Region 2 | 11/1/2019 | |
| 8 | 81037 HS - Lakeside High Facility | CARPENTRY | Doors | Region 2 | 28/01/2019 | |
| 8 | 83490 HS - Lakeside High Facility | GLAZING | Broken Window | Region 2 | 25/02/2019 | |
| 8 | 85629 HS - Lakeside High Facility | GROUNDS | Miscellaneous | Region 2 | 13/03/2019 | |
| 8 | 87120 HS - Lakeside High Facility | CARPENTRY | Doors | Region 2 | 26/03/2019 | |
| 8 | 89115 HS - Lakeside High Facility | LOCKSMITH | Doors | Region 2 | 12/4/2019 | |
| Ģ | 90025 HS - Lakeside High Facility | WASTE MANAGEMENT | Broken Equipment | Region 2 | 22/04/2019 | |
| Ç | 90313 HS - Lakeside High Facility | EQUIPMENT REPAIR | | Region 2 | 25/04/2019 | |
| Ç | 92159 HS - Lakeside High Facility | HVAC | Room Too Hot | Region 2 | 6/5/2019 | 5/11/2019 |
| Ç | 92330 HS - Lakeside High Facility | EQUIPMENT REPAIR | Broken Equipment | Region 2 | 8/5/2019 | |
| ç | 92333 HS - Lakeside High Facility | CARPENTRY | Miscellaneous | Region 2 | 8/5/2019 | |
| ç | 92760 HS - Lakeside High Facility | ELECTRICAL | | Region 2 | 14/05/2019 | |
| Ģ | 92999 HS - Lakeside High Facility | HVAC | Room Too Hot | Region 2 | 17/05/2019 | |
| ç | 93151 HS - Lakeside High Facility | WASTE MANAGEMENT | Broken Equipment | Region 2 | 20/05/2019 | |
| | | | • | | | |

| 93421 HS - Lakeside High Facility | GLAZING | | Region 2 | 22/05/2019 | |
|-----------------------------------|-------------------|------------------|----------|------------|-----------|
| 95116 HS - Lakeside High Facility | CARPENTRY | Decking | Region 2 | 3/6/2019 | 6/8/2019 |
| 95261 HS - Lakeside High Facility | WASTE MANAGEMENT | Broken Equipment | Region 2 | 4/6/2019 | 6/9/2019 |
| 95419 HS - Lakeside High Facility | CARPENTRY | Miscellaneous | Region 2 | 6/6/2019 | 6/11/2019 |
| 95694 HS - Lakeside High Facility | HOUSEKEEPING | Broken Equipment | Region 2 | 11/6/2019 | |
| 96474 HS - Lakeside High Facility | FIRE SAFETY | | Region 2 | 24/06/2019 | |
| 96531 HS - Lakeside High Facility | CARPENTRY | Miscellaneous | Region 2 | 24/06/2019 | 7/12/2019 |
| 96659 HS - Lakeside High Facility | ELECTRICAL | Lights Out | Region 2 | 26/06/2019 | 7/12/2019 |
| 96661 HS - Lakeside High Facility | CARPENTRY | Miscellaneous | Region 2 | 26/06/2019 | 7/12/2019 |
| 96664 HS - Lakeside High Facility | EQUIPMENT REPAIR | Miscellaneous | Region 2 | 26/06/2019 | 7/12/2019 |
| 98013 HS - Lakeside High Facility | LOCKSMITH | Doors | Region 2 | 3/7/2019 | 7/8/2019 |
| 98014 HS - Lakeside High Facility | CARPENTRY | Doors | Region 2 | 3/7/2019 | |
| 34775 HS - Tucker High Facility | GLAZING | | Region 2 | 9/11/2017 | |
| 62374 HS - Tucker High Facility | CARPENTRY | | Region 2 | 3/8/2018 | |
| 62965 HS - Tucker High Facility | ELECTRICAL | Broken Equipment | Region 2 | 7/8/2018 | |
| 64713 HS - Tucker High Facility | CARPENTRY | Structure | Region 2 | 21/08/2018 | |
| 65039 HS - Tucker High Facility | GLAZING | Grass | Region 2 | 23/08/2018 | |
| 72253 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 19/10/2018 | |
| 72254 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 19/10/2018 | |
| 74961 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 12/11/2018 | |
| 75145 HS - Tucker High Facility | CARPENTRY | Doors | Region 2 | 13/11/2018 | |
| 79552 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 10/1/2019 | |
| 79736 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 11/1/2019 | |
| 80260 HS - Tucker High Facility | ELECTRICAL | Miscellaneous | Region 2 | 18/01/2019 | |
| 82631 HS - Tucker High Facility | WAREHOUSE | Lights Out | Region 2 | 8/2/2019 | 2/9/2019 |
| 83515 HS - Tucker High Facility | CARPENTRY | Floors | Region 2 | 25/02/2019 | |
| 85465 HS - Tucker High Facility | ROOF | Roof Leak | Region 2 | 12/3/2019 | |
| 88553 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 8/4/2019 | |
| 88679 HS - Tucker High Facility | HAZARDOUS | | Region 2 | 9/4/2019 | |
| 88755 HS - Tucker High Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 2 | 9/4/2019 | |
| 89094 HS - Tucker High Facility | CARPENTRY | Miscellaneous | Region 2 | 12/4/2019 | |
| 90119 HS - Tucker High Facility | ROOF | Doors | Region 2 | 23/04/2019 | |
| 90468 HS - Tucker High Facility | ROOF | Water Leak | Region 2 | 26/04/2019 | 5/1/2019 |
| 90470 HS - Tucker High Facility | CARPENTRY | Exit SIgns | Region 2 | 26/04/2019 | 5/1/2019 |
| 90693 HS - Tucker High Facility | HVAC | Room Too Hot | Region 2 | 30/04/2019 | |
| 91910 HS - Tucker High Facility | ELECTRICAL | Miscellaneous | Region 2 | 2/5/2019 | 5/7/2019 |
| 92142 HS - Tucker High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 2 | 6/5/2019 | 5/11/2019 |
| 92269 HS - Tucker High Facility | GLAZING | Broken Window | Region 2 | 7/5/2019 | 5/12/2019 |
| 92271 HS - Tucker High Facility | GLAZING | Miscellaneous | Region 2 | 7/5/2019 | 5/12/2019 |
| 93739 HS - Tucker High Facility | HVAC | Room Too Hot | Region 2 | 28/05/2019 | 6/2/2019 |
| | | | | | |

| 93946 HS - Tucker High Facility | EQUIPMENT REPAIR | Miscellaneous | Region 2 | 30/05/2019 | 6/4/2019 |
|--|-----------------------------|-------------------|----------|------------|----------|
| 95103 HS - Tucker High Facility | HVAC | Room Too Hot | Region 2 | 3/6/2019 | |
| 95106 HS - Tucker High Facility | HVAC | | Region 2 | 3/6/2019 | 6/3/2019 |
| 95252 HS - Tucker High Facility | HVAC | Water Leak | Region 2 | 4/6/2019 | |
| 95588 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 10/6/2019 | |
| 95605 HS - Tucker High Facility | HVAC | | Region 2 | 10/6/2019 | |
| 96067 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 18/06/2019 | |
| 96068 HS - Tucker High Facility | HVAC | Water Leak | Region 2 | 18/06/2019 | |
| 96126 HS - Tucker High Facility | HVAC | | Region 2 | 18/06/2019 | |
| 96797 HS - Tucker High Facility | HVAC | Miscellaneous | Region 2 | 27/06/2019 | 7/2/2019 |
| 96798 HS - Tucker High Facility | PAINTING / PRESSURE WASHING | Paint | Region 2 | 27/06/2019 | |
| 96799 HS - Tucker High Facility | ELECTRICAL | Lights Out | Region 2 | 27/06/2019 | 7/2/2019 |
| 97977 HS - Tucker High Facility | HVAC | Room Too Hot | Region 2 | 3/7/2019 | |
| 97979 HS - Tucker High Facility | HVAC | Miscellaneous | Region 2 | 3/7/2019 | |
| 35406 MS - Druid Hills Middle Facility | CARPENTRY | | Region 2 | 16/11/2017 | |
| 51369 MS - Druid Hills Middle Facility | CARPENTRY | | Region 2 | 25/04/2018 | |
| 85713 MS - Druid Hills Middle Facility | HAZARDOUS | | Region 2 | 14/03/2019 | |
| 87286 MS - Druid Hills Middle Facility | ENVIRONMENTAL SVCS | Floors | Region 2 | 28/03/2019 | |
| 90436 MS - Druid Hills Middle Facility | HVAC | Noises | Region 2 | 26/04/2019 | 5/1/2019 |
| 93434 MS - Druid Hills Middle Facility | HVAC | Room Too Hot | Region 2 | 22/05/2019 | |
| 93442 MS - Druid Hills Middle Facility | HVAC | Room Too Hot | Region 2 | 22/05/2019 | |
| 95754 MS - Druid Hills Middle Facility | WASTE MANAGEMENT | Compactor / Trash | Region 2 | 12/6/2019 | |
| 95756 MS - Druid Hills Middle Facility | Mason/Concrete | Ceilings | Region 2 | 12/6/2019 | |
| 95980 MS - Druid Hills Middle Facility | GROUNDS | Paint | Region 2 | 17/06/2019 | |
| 95995 MS - Druid Hills Middle Facility | CARPENTRY | Miscellaneous | Region 2 | 17/06/2019 | |
| 96355 MS - Druid Hills Middle Facility | CARPENTRY | Miscellaneous | Region 2 | 20/06/2019 | |
| 68730 MS - Henderson Middle Facility | PLUMBING | Broken Equipment | Region 2 | 14/09/2018 | |
| 85361 MS - Henderson Middle Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 2 | 11/3/2019 | |
| 92518 MS - Henderson Middle Facility | MECHANICAL EQUIPMENT | Broken Equipment | Region 2 | 10/5/2019 | |
| 92648 MS - Henderson Middle Facility | CARPENTRY | | Region 2 | 13/05/2019 | |
| 93298 MS - Henderson Middle Facility | HVAC | | Region 2 | 21/05/2019 | |
| 93573 MS - Henderson Middle Facility | ELECTRICAL | Doors | Region 2 | 24/05/2019 | |
| 95229 MS - Henderson Middle Facility | ELECTRICAL | | Region 2 | 4/6/2019 | 6/9/2019 |
| 96638 MS - Henderson Middle Facility | CARPENTRY | Floors | Region 2 | 25/06/2019 | |
| 96642 MS - Henderson Middle Facility | MASON/CONCRETE | Debris | Region 2 | 25/06/2019 | |
| 98835 MS - Henderson Middle Facility | | Paint | Region 2 | 16/07/2019 | |
| 55408 MS - Tucker Middle Facility | ROOF | | Region 2 | 25/05/2018 | |
| 58251 MS - Tucker Middle Facility | CARPENTRY | | Region 2 | 27/06/2018 | |
| 60071 MS - Tucker Middle Facility | ELECTRICAL | | Region 2 | 19/07/2018 | |
| 71247 MS - Tucker Middle Facility | ELECTRICAL | Lights Out | Region 2 | 9/10/2018 | |
| | | | | | |

| 72732 MS - Tucker Middle Facility | ROOF | Roof Leak | Region 2 | 26/10/2018 | |
|---|-----------------------------|----------------------|----------|------------|-----------|
| 72924 MS - Tucker Middle Facility | ELECTRICAL | Broken Plug | Region 2 | 30/10/2018 | |
| 75307 MS - Tucker Middle Facility | ROOF | Roof Leak | Region 2 | 14/11/2018 | |
| 75442 MS - Tucker Middle Facility | ROOF | Roof Leak | Region 2 | 15/11/2018 | |
| 83904 MS - Tucker Middle Facility | ELECTRICAL | Lights Out | Region 2 | 28/02/2019 | 3/1/2019 |
| 84805 MS - Tucker Middle Facility | GROUNDS | Move Items | Region 2 | 4/3/2019 | 3/5/2019 |
| 85021 MS - Tucker Middle Facility | ELECTRICAL | Broken Plug | Region 2 | 6/3/2019 | |
| 85710 MS - Tucker Middle Facility | HAZARDOUS | | Region 2 | 14/03/2019 | |
| 85809 MS - Tucker Middle Facility | WAREHOUSE | | Region 2 | 15/03/2019 | |
| 86221 MS - Tucker Middle Facility | HVAC | Standing Water | Region 2 | 20/03/2019 | |
| 86372 MS - Tucker Middle Facility | CARPENTRY | Doors | Region 2 | 21/03/2019 | |
| 87184 MS - Tucker Middle Facility | FIRE SAFETY | Extinguisher | Region 2 | 27/03/2019 | |
| 87235 MS - Tucker Middle Facility | HVAC | Room Too Hot | Region 2 | 28/03/2019 | |
| 88610 MS - Tucker Middle Facility | CARPENTRY | Pest | Region 2 | 8/4/2019 | |
| 88694 MS - Tucker Middle Facility | ROOF | Water Leak | Region 2 | 9/4/2019 | |
| 88802 MS - Tucker Middle Facility | HVAC | | Region 2 | 9/4/2019 | |
| 89036 MS - Tucker Middle Facility | HVAC | | Region 2 | 11/4/2019 | |
| 89635 MS - Tucker Middle Facility | HVAC | Room Too Hot | Region 2 | 18/04/2019 | |
| 96514 MS - Tucker Middle Facility | CARPENTRY | Whiteboards | Region 2 | 24/06/2019 | |
| 98037 MS - Tucker Middle Facility | HVAC | Miscellaneous | Region 2 | 3/7/2019 | 7/8/2019 |
| 98540 MS - Tucker Middle Facility | ELECTRICAL | | Region 2 | 11/7/2019 | |
| 98777 MS - Tucker Middle Facility | CARPENTRY | Decking | Region 2 | 16/07/2019 | |
| 98817 MS - Tucker Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 2 | 16/07/2019 | |
| 67798 ES - Eldridge L. Miller Elementary Facility | ROOF | Roof Leak | Region 3 | 5/9/2018 | |
| 90393 ES - Eldridge L. Miller Elementary Facility | ELECTRICAL | Lights Out | Region 3 | 26/04/2019 | 5/1/2019 |
| 92782 ES - Eldridge L. Miller Elementary Facility | HVAC | Miscellaneous | Region 3 | 14/05/2019 | |
| 98392 ES - Eldridge L. Miller Elementary Facility | HVAC | | Region 3 | 10/7/2019 | |
| 98672 ES - Eldridge L. Miller Elementary Facility | ELECTRICAL | | Region 3 | 15/07/2019 | |
| 98684 ES - Eldridge L. Miller Elementary Facility | PAINTING / PRESSURE WASHING | | Region 3 | 15/07/2019 | |
| 78928 ES - Marbut Elementary Facility | CARPENTRY | Pressure Washing | Region 3 | 2/1/2019 | |
| 85277 ES - Marbut Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 3 | 8/3/2019 | |
| 85452 ES - Marbut Elementary Facility | CARPENTRY | Floors | Region 3 | 6/3/2019 | 3/12/2019 |
| 92297 ES - Marbut Elementary Facility | HVAC | Water Leak | Region 3 | 8/5/2019 | |
| 93009 ES - Marbut Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 3 | 17/05/2019 | |
| 93010 ES - Marbut Elementary Facility | GLAZING | Broken Window | Region 3 | 17/05/2019 | |
| 93347 ES - Marbut Elementary Facility | HVAC | Room Too Hot | Region 3 | 21/05/2019 | |
| 93557 ES - Marbut Elementary Facility | CARPENTRY | Floors | Region 3 | 24/05/2019 | |
| 97917 ES - Marbut Elementary Facility | HVAC | Trees | Region 3 | 1/7/2019 | 7/6/2019 |
| 97918 ES - Marbut Elementary Facility | HVAC | Water Leak | Region 3 | 1/7/2019 | 7/6/2019 |
| 97919 ES - Marbut Elementary Facility | HVAC | Room Too Hot | Region 3 | 1/7/2019 | 7/6/2019 |
| | | | | | |

| 98018 ES - Marbut Elementary Facility | FIRE SAFETY | Alarm Systems | Region 3 | 3/7/2019 | 7/8/2019 |
|---|-----------------------------|-------------------|----------|------------|-----------|
| 98019 ES - Marbut Elementary Facility | CARPENTRY | Floors | Region 3 | 3/7/2019 | |
| 98021 ES - Marbut Elementary Facility | HVAC | Water Leak | Region 3 | 3/7/2019 | |
| 98853 ES - Marbut Elementary Facility | HVAC | | Region 3 | 16/07/2019 | |
| 53468 ES - Pine Ridge Elementary Facility | CARPENTRY | | Region 3 | 1/5/2018 | |
| 86883 ES - Pine Ridge Elementary Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 3 | 25/03/2019 | |
| 90377 ES - Pine Ridge Elementary Facility | HVAC | Room Too Hot | Region 3 | 25/04/2019 | |
| 90765 ES - Pine Ridge Elementary Facility | HVAC | Room Too Hot | Region 3 | 30/04/2019 | 5/5/2019 |
| 91859 ES - Pine Ridge Elementary Facility | HVAC | Room Too Hot | Region 3 | 2/5/2019 | 5/7/2019 |
| 93207 ES - Pine Ridge Elementary Facility | WASTE MANAGEMENT | Recycling | Region 3 | 20/05/2019 | |
| 93921 ES - Pine Ridge Elementary Facility | GLAZING | Broken Window | Region 3 | 30/05/2019 | 6/4/2019 |
| 95126 ES - Pine Ridge Elementary Facility | GLAZING | Broken Window | Region 3 | 3/6/2019 | 6/8/2019 |
| 95165 ES - Pine Ridge Elementary Facility | CARPENTRY | Broken Window | Region 3 | 3/6/2019 | 6/8/2019 |
| 95380 ES - Pine Ridge Elementary Facility | CARPENTRY | Broken Window | Region 3 | 6/6/2019 | 6/11/2019 |
| 95665 ES - Pine Ridge Elementary Facility | PLUMBING | Miscellaneous | Region 3 | 11/6/2019 | |
| 97984 ES - Pine Ridge Elementary Facility | FIRE SAFETY | Alarm Systems | Region 3 | 3/7/2019 | 7/8/2019 |
| 98668 ES - Pine Ridge Elementary Facility | HVAC | Room Too Hot | Region 3 | 15/07/2019 | |
| 98669 ES - Pine Ridge Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 3 | 15/07/2019 | |
| 98736 ES - Pine Ridge Elementary Facility | HVAC | Room Too Hot | Region 3 | 15/07/2019 | |
| 98812 ES - Pine Ridge Elementary Facility | | Clocks | Region 3 | 16/07/2019 | |
| 98813 ES - Pine Ridge Elementary Facility | | Miscellaneous | Region 3 | 16/07/2019 | |
| 98814 ES - Pine Ridge Elementary Facility | | Recycling | Region 3 | 16/07/2019 | |
| 98816 ES - Pine Ridge Elementary Facility | | Room Too Hot | Region 3 | 16/07/2019 | |
| 72112 ES - Princeton Elementary Facility | PAINTING / PRESSURE WASHING | | Region 3 | 17/10/2018 | |
| 75345 ES - Princeton Elementary Facility | ROOF | Roof Leak | Region 3 | 14/11/2018 | |
| 77921 ES - Princeton Elementary Facility | ROOF | Roof Leak | Region 3 | 20/12/2018 | |
| 92969 ES - Princeton Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 3 | 17/05/2019 | |
| 93318 ES - Princeton Elementary Facility | WASTE MANAGEMENT | Recycling | Region 3 | 21/05/2019 | |
| 93360 ES - Princeton Elementary Facility | GLAZING | Miscellaneous | Region 3 | 22/05/2019 | |
| 93388 ES - Princeton Elementary Facility | KITCHEN EQUIPMENT | Stove / Oven | Region 3 | 22/05/2019 | |
| 95695 ES - Princeton Elementary Facility | ROOF | Roof Leak | Region 3 | 11/6/2019 | |
| 96575 ES - Princeton Elementary Facility | PLUMBING | Water Leak | Region 3 | 25/06/2019 | |
| 60298 ES - Redan Elementary Facility | PAINTING / PRESSURE WASHING | | Region 3 | 24/07/2018 | |
| 83219 ES - Redan Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 3 | 20/02/2019 | |
| 83220 ES - Redan Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 3 | 20/02/2019 | |
| 87148 ES - Redan Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 26/03/2019 | |
| 88741 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 9/4/2019 | |
| 88783 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 9/4/2019 | |
| 88832 ES - Redan Elementary Facility | ROOF | Roof Leak | Region 3 | 10/4/2019 | |
| 88980 ES - Redan Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 3 | 11/4/2019 | |
| | | | | | |

| 89416 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 16/04/2019 | |
|--|-----------------------------|---------------------------|----------|------------|-----------|
| 90180 ES - Redan Elementary Facility | WAREHOUSE | | Region 3 | 24/04/2019 | |
| 90372 ES - Redan Elementary Facility | GLAZING | Broken Equipment | Region 3 | 25/04/2019 | |
| 90463 ES - Redan Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 3 | 26/04/2019 | 5/1/2019 |
| 90465 ES - Redan Elementary Facility | CARPENTRY | Doors | Region 3 | 26/04/2019 | 5/1/2019 |
| 92238 ES - Redan Elementary Facility | HVAC | Room Too Hot | Region 3 | 7/5/2019 | 5/12/2019 |
| 92260 ES - Redan Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 7/5/2019 | 5/12/2019 |
| 92277 ES - Redan Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 7/5/2019 | 5/12/2019 |
| 92916 ES - Redan Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 3 | 16/05/2019 | |
| 93427 ES - Redan Elementary Facility | HVAC | Room Too Hot | Region 3 | 22/05/2019 | |
| 93428 ES - Redan Elementary Facility | HVAC | Room Too Hot | Region 3 | 22/05/2019 | |
| 93524 ES - Redan Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 3 | 24/05/2019 | |
| 93754 ES - Redan Elementary Facility | GLAZING | Broken Equipment | Region 3 | 28/05/2019 | 6/2/2019 |
| 93768 ES - Redan Elementary Facility | CARPENTRY | Doors | Region 3 | 28/05/2019 | 6/2/2019 |
| 93769 ES - Redan Elementary Facility | CARPENTRY | Doors | Region 3 | 28/05/2019 | 6/2/2019 |
| 95610 ES - Redan Elementary Facility | ROOF | Roof Leak | Region 3 | 10/6/2019 | |
| 95612 ES - Redan Elementary Facility | CARPENTRY | Ceilings | Region 3 | 10/6/2019 | |
| 96475 ES - Redan Elementary Facility | HVAC | | Region 3 | 24/06/2019 | |
| 98023 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 3/7/2019 | 7/8/2019 |
| 98024 ES - Redan Elementary Facility | CARPENTRY | Structure | Region 3 | 3/7/2019 | |
| 98026 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 3/7/2019 | 7/8/2019 |
| 98027 ES - Redan Elementary Facility | CARPENTRY | Cove Base | Region 3 | 3/7/2019 | 7/8/2019 |
| 98028 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 3/7/2019 | 7/8/2019 |
| 98029 ES - Redan Elementary Facility | PLUMBING | Miscellaneous | Region 3 | 3/7/2019 | 7/8/2019 |
| 98030 ES - Redan Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 3/7/2019 | 7/8/2019 |
| 98031 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 3/7/2019 | 7/8/2019 |
| 98032 ES - Redan Elementary Facility | CARPENTRY | Cove Base | Region 3 | 3/7/2019 | 7/8/2019 |
| 98033 ES - Redan Elementary Facility | CARPENTRY | Floors | Region 3 | 3/7/2019 | 7/8/2019 |
| 98034 ES - Redan Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 3/7/2019 | 7/8/2019 |
| 98244 ES - Redan Elementary Facility | CARPENTRY | Cove Base | Region 3 | 8/7/2019 | |
| 98488 ES - Redan Elementary Facility | HVAC | Miscellaneous | Region 3 | 11/7/2019 | |
| 70877 ES - Rock Chapel Elementary Facility | PLUMBING | Toilet Overflowing | Region 3 | 2/10/2018 | |
| 82344 ES - Rock Chapel Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 3 | 6/2/2019 | |
| 91916 ES - Rock Chapel Elementary Facility | CARPENTRY | Cove Base | Region 3 | 2/5/2019 | 5/7/2019 |
| 92813 ES - Rock Chapel Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 3 | 15/05/2019 | |
| 95869 ES - Rock Chapel Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 14/06/2019 | |
| 96114 ES - Rock Chapel Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 18/06/2019 | |
| 96555 ES - Rock Chapel Elementary Facility | GROUNDS | | Region 3 | 24/06/2019 | |
| 96556 ES - Rock Chapel Elementary Facility | VENDOR | | Region 3 | 24/06/2019 | |
| 96665 ES - Rock Chapel Elementary Facility | HVAC | Miscellaneous | Region 3 | 26/06/2019 | 7/12/2019 |
| | | | | | |

| 96671 ES - Rock Chapel Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 26/06/2019 | 7/12/2019 |
|---|-----------------------------|------------------|----------|------------|-----------|
| 98056 ES - Rock Chapel Elementary Facility | LOCKSMITH | Locks / Keys | Region 3 | 5/7/2019 | 7/10/2019 |
| 98178 ES - Rock Chapel Elementary Facility | GROUNDS | Trees | Region 3 | 8/7/2019 | |
| 98300 ES - Rock Chapel Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 9/7/2019 | |
| 98351 ES - Rock Chapel Elementary Facility | PAINTING / PRESSURE WASHING | Miscellaneous | Region 3 | 9/7/2019 | |
| 98402 ES - Rock Chapel Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 10/7/2019 | |
| 98403 ES - Rock Chapel Elementary Facility | PEST CONTROL | Pest | Region 3 | 10/7/2019 | |
| 98430 ES - Rock Chapel Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 10/7/2019 | |
| 98473 ES - Rock Chapel Elementary Facility | LOCKSMITH | Miscellaneous | Region 3 | 10/7/2019 | |
| 98475 ES - Rock Chapel Elementary Facility | HVAC | Miscellaneous | Region 3 | 10/7/2019 | |
| 98513 ES - Rock Chapel Elementary Facility | LOCKSMITH | Miscellaneous | Region 3 | 11/7/2019 | |
| 98543 ES - Rock Chapel Elementary Facility | ELECTRICAL | Lights Out | Region 3 | 11/7/2019 | |
| 98678 ES - Rock Chapel Elementary Facility | HVAC | Room Too Hot | Region 3 | 15/07/2019 | |
| 98790 ES - Rock Chapel Elementary Facility | | Room Too Hot | Region 3 | 16/07/2019 | |
| 89745 ES - Shadow Rock Elementary School Facility | ROOF | Roof Leak | Region 3 | 19/04/2019 | |
| 90443 ES - Shadow Rock Elementary School Facility | ROOF | Roof Leak | Region 3 | 26/04/2019 | 5/1/2019 |
| 92968 ES - Shadow Rock Elementary School Facility | WASTE MANAGEMENT | Broken Equipment | Region 3 | 17/05/2019 | |
| 93426 ES - Shadow Rock Elementary School Facility | HVAC | Freezer / Cooler | Region 3 | 22/05/2019 | |
| 93525 ES - Shadow Rock Elementary School Facility | GROUNDS | Miscellaneous | Region 3 | 24/05/2019 | |
| 93764 ES - Shadow Rock Elementary School Facility | GROUNDS | Miscellaneous | Region 3 | 28/05/2019 | 6/2/2019 |
| 96356 ES - Shadow Rock Elementary School Facility | ELECTRICAL | Lights Out | Region 3 | 20/06/2019 | |
| 96593 ES - Shadow Rock Elementary School Facility | HVAC | | Region 3 | 25/06/2019 | |
| 97982 ES - Shadow Rock Elementary School Facility | GROUNDS | Miscellaneous | Region 3 | 3/7/2019 | |
| 98716 ES - Shadow Rock Elementary School Facility | HVAC | Miscellaneous | Region 3 | 15/07/2019 | |
| 98848 ES - Shadow Rock Elementary School Facility | PLUMBING | Miscellaneous | Region 3 | 16/07/2019 | |
| 80353 ES - Stoneview Elementary Facility | CARPENTRY | Structure | Region 3 | 18/01/2019 | |
| 80577 ES - Stoneview Elementary Facility | PAINTING / PRESSURE WASHING | | Region 3 | 22/01/2019 | |
| 93377 ES - Stoneview Elementary Facility | GROUNDS | Miscellaneous | Region 3 | 22/05/2019 | |
| 95561 ES - Stoneview Elementary Facility | ROOF | Roof Leak | Region 3 | 10/6/2019 | |
| 95859 ES - Stoneview Elementary Facility | HVAC | | Region 3 | 13/06/2019 | |
| 96161 ES - Stoneview Elementary Facility | HVAC | | Region 3 | 19/06/2019 | |
| 96296 ES - Stoneview Elementary Facility | HVAC | Room Too Hot | Region 3 | 20/06/2019 | |
| 97961 ES - Stoneview Elementary Facility | HVAC | | Region 3 | 2/7/2019 | 7/7/2019 |
| 97962 ES - Stoneview Elementary Facility | HVAC | | Region 3 | 2/7/2019 | 7/7/2019 |
| 98045 ES - Stoneview Elementary Facility | GROUNDS | | Region 3 | 3/7/2019 | 7/8/2019 |
| 98255 ES - Stoneview Elementary Facility | CARPENTRY | Doors | Region 3 | 8/7/2019 | |
| 98269 ES - Stoneview Elementary Facility | CARPENTRY | | Region 3 | 8/7/2019 | |
| 98431 ES - Stoneview Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 10/7/2019 | |
| 98456 ES - Stoneview Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 10/7/2019 | |
| 98731 ES - Stoneview Elementary Facility | LOCKSMITH | | Region 3 | 15/07/2019 | |
| | | | | | |

| 98743 ES - Stoneview Elementary Facility | CARPENTRY | Miscellaneous | Region 3 | 15/07/2019 | |
|--|-------------------|----------------------|----------|------------|-----------|
| 71691 ES - Wynbrooke Elementary Facility | ROOF | Roof Leak | Region 3 | 12/10/2018 | |
| 74415 ES - Wynbrooke Elementary Facility | CARPENTRY | Ceilings | Region 3 | 5/11/2018 | |
| 79499 ES - Wynbrooke Elementary Facility | ROOF | Ceilings | Region 3 | 9/1/2019 | |
| 89986 ES - Wynbrooke Elementary Facility | HVAC | | Region 3 | 22/04/2019 | |
| 95312 ES - Wynbrooke Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 3 | 5/6/2019 | |
| 95602 ES - Wynbrooke Elementary Facility | ROOF | Roof Leak | Region 3 | 10/6/2019 | |
| 95977 ES - Wynbrooke Elementary Facility | PEST CONTROL | Pest | Region 3 | 17/06/2019 | |
| 96487 ES - Wynbrooke Elementary Facility | GROUNDS | | Region 3 | 24/06/2019 | |
| 98248 ES - Wynbrooke Elementary Facility | HVAC | | Region 3 | 8/7/2019 | |
| 63535 HS - Arabia Mountain High Facility | ROOF | Roof Leak | Region 3 | 10/8/2018 | |
| 71193 HS - Arabia Mountain High Facility | PLUMBING | Water Leak | Region 3 | 8/10/2018 | |
| 76874 HS - Arabia Mountain High Facility | CARPENTRY | Move Items | Region 3 | 6/12/2018 | 12/7/2018 |
| 79612 HS - Arabia Mountain High Facility | GLAZING | Broken Window | Region 3 | 10/1/2019 | |
| 83396 HS - Arabia Mountain High Facility | PLUMBING | Broken Equipment | Region 3 | 21/02/2019 | |
| 88620 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 8/4/2019 | |
| 89774 HS - Arabia Mountain High Facility | ROOF | Roof Leak | Region 3 | 19/04/2019 | |
| 89943 HS - Arabia Mountain High Facility | FIRE SAFETY | Fire Alarm | Region 3 | 22/04/2019 | |
| 89969 HS - Arabia Mountain High Facility | GROUNDS | Miscellaneous | Region 3 | 22/04/2019 | |
| 90158 HS - Arabia Mountain High Facility | PEST CONTROL | Pest | Region 3 | 23/04/2019 | |
| 90379 HS - Arabia Mountain High Facility | GLAZING | Broken Window | Region 3 | 25/04/2019 | |
| 91956 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 3/5/2019 | 5/8/2019 |
| 91965 HS - Arabia Mountain High Facility | EQUIPMENT REPAIR | Broken Equipment | Region 3 | 3/5/2019 | 5/8/2019 |
| 92137 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 6/5/2019 | 5/11/2019 |
| 92529 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 10/5/2019 | |
| 93299 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 21/05/2019 | |
| 93353 HS - Arabia Mountain High Facility | CARPENTRY | Locks / Keys | Region 3 | 22/05/2019 | |
| 93355 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 22/05/2019 | |
| 95259 HS - Arabia Mountain High Facility | CARPENTRY | Miscellaneous | Region 3 | 4/6/2019 | 6/9/2019 |
| 95799 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 12/6/2019 | |
| 96018 HS - Arabia Mountain High Facility | PEST CONTROL | Pest | Region 3 | 17/06/2019 | |
| 96590 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 25/06/2019 | |
| 96592 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 25/06/2019 | |
| 96649 HS - Arabia Mountain High Facility | HVAC | Room Too Hot | Region 3 | 25/06/2019 | 7/12/2019 |
| 96690 HS - Arabia Mountain High Facility | EQUIPMENT REPAIR | Broken Equipment | Region 3 | 26/06/2019 | 7/12/2019 |
| 98054 HS - Arabia Mountain High Facility | FIRE SAFETY | Fire Alarm | Region 3 | 5/7/2019 | 7/12/2019 |
| 98393 HS - Arabia Mountain High Facility | HVAC | | Region 3 | 10/7/2019 | |
| 98796 HS - Arabia Mountain High Facility | PEST CONTROL | Pest | Region 3 | 16/07/2019 | |
| 75313 HS - Lithonia High Facility | ROOF | Roof Leak | Region 3 | 14/11/2018 | |
| 82948 HS - Lithonia High Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 3 | 14/02/2019 | |
| | | | | | |

| 90206 HS - Lithonia High Facility | WAREHOUSE | Compactor / Trash | Region 3 | 24/04/2019 | |
|-------------------------------------|-----------------------------|-------------------|----------|------------|-----------|
| 90207 HS - Lithonia High Facility | HVAC | Freezer / Cooler | Region 3 | 24/04/2019 | |
| 91556 HS - Lithonia High Facility | CARPENTRY | Miscellaneous | Region 3 | 1/5/2019 | 5/6/2019 |
| 93011 HS - Lithonia High Facility | KITCHEN EQUIPMENT | Water Leak | Region 3 | 17/05/2019 | |
| 93012 HS - Lithonia High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 3 | 17/05/2019 | |
| 93405 HS - Lithonia High Facility | GLAZING | Broken Window | Region 3 | 22/05/2019 | |
| 93494 HS - Lithonia High Facility | HVAC | Room Too Hot | Region 3 | 23/05/2019 | |
| 93866 HS - Lithonia High Facility | HVAC | Room Too Hot | Region 3 | 29/05/2019 | |
| 95356 HS - Lithonia High Facility | PLUMBING | | Region 3 | 6/6/2019 | 6/11/2019 |
| 95635 HS - Lithonia High Facility | GROUNDS | Miscellaneous | Region 3 | 10/6/2019 | |
| 95771 HS - Lithonia High Facility | ROOF | Roof Leak | Region 3 | 12/6/2019 | |
| 96597 HS - Lithonia High Facility | CARPENTRY | Ceilings | Region 3 | 25/06/2019 | |
| 96598 HS - Lithonia High Facility | ELECTRICAL | Lights Out | Region 3 | 25/06/2019 | |
| 96630 HS - Lithonia High Facility | ROOF | Roof Leak | Region 3 | 25/06/2019 | |
| 96633 HS - Lithonia High Facility | HVAC | Roof Leak | Region 3 | 25/06/2019 | |
| 96770 HS - Lithonia High Facility | HOUSEKEEPING | Miscellaneous | Region 3 | 27/06/2019 | 7/12/2019 |
| 97876 HS - Lithonia High Facility | HVAC | | Region 3 | 1/7/2019 | 7/6/2019 |
| 34176 HS - Redan High Facility | ELECTRICAL | | Region 3 | 2/11/2017 | |
| 80695 HS - Redan High Facility | ROOF | Roof Leak | Region 3 | 23/01/2019 | |
| 90231 HS - Redan High Facility | FIRE SAFETY | | Region 3 | 24/04/2019 | |
| 92768 HS - Redan High Facility | ROOF | Roof Leak | Region 3 | 14/05/2019 | |
| 92841 HS - Redan High Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 3 | 15/05/2019 | |
| 92951 HS - Redan High Facility | HVAC | No Power | Region 3 | 16/05/2019 | |
| 93260 HS - Redan High Facility | HVAC | Room Too Hot | Region 3 | 21/05/2019 | |
| 93417 HS - Redan High Facility | HVAC | Miscellaneous | Region 3 | 22/05/2019 | |
| 94043 HS - Redan High Facility | GROUNDS | Miscellaneous | Region 3 | 31/05/2019 | |
| 96195 HS - Redan High Facility | PLUMBING | Miscellaneous | Region 3 | 19/06/2019 | |
| 96309 HS - Redan High Facility | HVAC | Room Too Hot | Region 3 | 20/06/2019 | |
| 98046 HS - Redan High Facility | GROUNDS | | Region 3 | 3/7/2019 | 7/8/2019 |
| 98345 HS - Redan High Facility | HVAC | | Region 3 | 9/7/2019 | |
| 98364 HS - Redan High Facility | HVAC | | Region 3 | 9/7/2019 | |
| 98550 HS - Redan High Facility | HVAC | Water Leak | Region 3 | 11/7/2019 | |
| 68942 HS - Stephenson High Facility | ROOF | Roof Leak | Region 3 | 18/09/2018 | |
| 69751 HS - Stephenson High Facility | ROOF | Roof Leak | Region 3 | 28/09/2018 | |
| 71012 HS - Stephenson High Facility | GLAZING | Miscellaneous | Region 3 | 3/10/2018 | |
| 74918 HS - Stephenson High Facility | ROOF | Roof Leak | Region 3 | 9/11/2018 | |
| 75046 HS - Stephenson High Facility | ROOF | Roof Leak | Region 3 | 12/11/2018 | |
| 84722 HS - Stephenson High Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 3 | 1/3/2019 | 3/2/2019 |
| 84727 HS - Stephenson High Facility | GROUNDS | Structure | Region 3 | 1/3/2019 | 3/2/2019 |
| 85722 HS - Stephenson High Facility | HAZARDOUS | | Region 3 | 14/03/2019 | |
| | | | | | |

| 88391 HS - Stephenson High Facility | HAZARDOUS | | Region 3 | 2/4/2019 | 4/2/2019 |
|-------------------------------------|-------------------|---------------------------|----------|------------|-----------|
| 89004 HS - Stephenson High Facility | CARPENTRY | Broken Window | Region 3 | 11/4/2019 | |
| 90157 HS - Stephenson High Facility | HVAC | Room Too Hot | Region 3 | 23/04/2019 | |
| 91924 HS - Stephenson High Facility | HVAC | Room Too Hot | Region 3 | 2/5/2019 | 5/7/2019 |
| 92242 HS - Stephenson High Facility | GROUNDS | Miscellaneous | Region 3 | 7/5/2019 | 5/12/2019 |
| 92789 HS - Stephenson High Facility | KITCHEN EQUIPMENT | Stove / Oven | Region 3 | 14/05/2019 | |
| 93381 HS - Stephenson High Facility | HVAC | Room Too Hot | Region 3 | 22/05/2019 | |
| 95554 HS - Stephenson High Facility | ROOF | Ceilings | Region 3 | 10/6/2019 | |
| 96024 HS - Stephenson High Facility | HVAC | Room Too Hot | Region 3 | 17/06/2019 | |
| 96337 HS - Stephenson High Facility | PLUMBING | Toilet Overflowing | Region 3 | 20/06/2019 | |
| 97858 HS - Stephenson High Facility | CARPENTRY | Miscellaneous | Region 3 | 1/7/2019 | |
| 98262 HS - Stephenson High Facility | HVAC | Room Too Hot | Region 3 | 8/7/2019 | |
| 98263 HS - Stephenson High Facility | ELECTRICAL | Lights Out | Region 3 | 8/7/2019 | |
| 79080 MS - Lithonia Middle Facility | GLAZING | | Region 3 | 4/1/2019 | |
| 79349 MS - Lithonia Middle Facility | CARPENTRY | Broken Equipment | Region 3 | 8/1/2019 | |
| 83132 MS - Lithonia Middle Facility | GLAZING | | Region 3 | 20/02/2019 | |
| 86896 MS - Lithonia Middle Facility | CARPENTRY | Doors | Region 3 | 25/03/2019 | |
| 89053 MS - Lithonia Middle Facility | CARPENTRY | Floors | Region 3 | 11/4/2019 | |
| 89183 MS - Lithonia Middle Facility | HVAC | Room Too Hot | Region 3 | 12/4/2019 | |
| 90319 MS - Lithonia Middle Facility | HVAC | Room Too Hot | Region 3 | 25/04/2019 | |
| 91907 MS - Lithonia Middle Facility | CARPENTRY | Floors | Region 3 | 2/5/2019 | 5/7/2019 |
| 97886 MS - Lithonia Middle Facility | GROUNDS | Miscellaneous | Region 3 | 1/7/2019 | 7/6/2019 |
| 97964 MS - Lithonia Middle Facility | GROUNDS | Roof Leak | Region 3 | 2/7/2019 | 7/7/2019 |
| 98366 MS - Lithonia Middle Facility | HVAC | Room Too Hot | Region 3 | 9/7/2019 | |
| 98367 MS - Lithonia Middle Facility | CARPENTRY | Doors | Region 3 | 9/7/2019 | |
| 98368 MS - Lithonia Middle Facility | CARPENTRY | Doors | Region 3 | 9/7/2019 | |
| 59995 MS - Redan Middle Facility | CARPENTRY | | Region 3 | 18/07/2018 | |
| 59997 MS - Redan Middle Facility | CARPENTRY | | Region 3 | 18/07/2018 | |
| 75610 MS - Redan Middle Facility | CARPENTRY | | Region 3 | 20/11/2018 | |
| 77616 MS - Redan Middle Facility | ROOF | Roof Leak | Region 3 | 14/12/2018 | |
| 83646 MS - Redan Middle Facility | GLAZING | Broken Window | Region 3 | 26/02/2019 | |
| 83745 MS - Redan Middle Facility | WAREHOUSE | Supplies Needed | Region 3 | 27/02/2019 | 3/1/2019 |
| 84761 MS - Redan Middle Facility | CARPENTRY | Freezer / Cooler | Region 3 | 4/3/2019 | |
| 88836 MS - Redan Middle Facility | GLAZING | | Region 3 | 10/4/2019 | |
| 92944 MS - Redan Middle Facility | ELECTRICAL | | Region 3 | 16/05/2019 | |
| 93386 MS - Redan Middle Facility | CARPENTRY | | Region 3 | 22/05/2019 | |
| 95737 MS - Redan Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 3 | 11/6/2019 | |
| 95840 MS - Redan Middle Facility | HVAC | Room Too Hot | Region 3 | 13/06/2019 | |
| 95851 MS - Redan Middle Facility | PLUMBING | Toilet Overflowing | Region 3 | 13/06/2019 | |
| 96541 MS - Redan Middle Facility | HVAC | Broken Equipment | Region 3 | 24/06/2019 | 7/12/2019 |
| | | | | | |

| 96616 MS - Redan Middle Facility | HVAC | Water Leak | Region 3 | 25/06/2019 | |
|---------------------------------------|------------------|-------------------|----------|------------|-----------|
| 98035 MS - Redan Middle Facility | CARPENTRY | Doors | Region 3 | 3/7/2019 | 7/8/2019 |
| 98062 MS - Redan Middle Facility | GROUNDS | Miscellaneous | Region 3 | 5/7/2019 | 7/10/2019 |
| 98243 MS - Redan Middle Facility | GLAZING | Broken Equipment | Region 3 | 8/7/2019 | |
| 98252 MS - Redan Middle Facility | GLAZING | | Region 3 | 8/7/2019 | |
| 98492 MS - Redan Middle Facility | EQUIPMENT REPAIR | Broken Equipment | Region 3 | 11/7/2019 | |
| 98714 MS - Redan Middle Facility | LOCKSMITH | Locks / Keys | Region 3 | 15/07/2019 | |
| 47768 MS - Stephenson Middle Facility | INSPECTION | | Region 3 | 5/3/2018 | |
| 50702 MS - Stephenson Middle Facility | ELECTRICAL | | Region 3 | 16/04/2018 | |
| 88390 MS - Stephenson Middle Facility | HAZARDOUS | | Region 3 | 2/4/2019 | 4/2/2019 |
| 90742 MS - Stephenson Middle Facility | HVAC | Broken Equipment | Region 3 | 30/04/2019 | 5/5/2019 |
| 98497 MS - Stephenson Middle Facility | HVAC | Room Too Hot | Region 3 | 11/7/2019 | |
| 95862 AC - DeKalb ECA | ELECTRICAL | Broken Plug | Region 4 | 13/06/2019 | |
| 70760 AC - Eagle Woods | ELECTRICAL | | Region 4 | 1/10/2018 | 10/1/2018 |
| 78967 AC - Eagle Woods | ROOF | Ceilings | Region 4 | 3/1/2019 | |
| 86969 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 25/03/2019 | |
| 87236 AC - Eagle Woods | ELECTRICAL | Broken Plug | Region 4 | 28/03/2019 | |
| 87249 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 28/03/2019 | |
| 89517 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 17/04/2019 | |
| 93917 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 30/05/2019 | 6/4/2019 |
| 95121 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 3/6/2019 | 6/8/2019 |
| 95375 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 6/6/2019 | 6/11/2019 |
| 95555 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 10/6/2019 | |
| 95556 AC - Eagle Woods | ROOF | Ceilings | Region 4 | 10/6/2019 | |
| 96186 AC - Eagle Woods | ELECTRICAL | Broken Plug | Region 4 | 19/06/2019 | |
| 96187 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 19/06/2019 | |
| 96345 AC - Eagle Woods | CARPENTRY | Doors | Region 4 | 20/06/2019 | |
| 96604 AC - Eagle Woods | ROOF | Ceilings | Region 4 | 25/06/2019 | |
| 96606 AC - Eagle Woods | CARPENTRY | Ceilings | Region 4 | 25/06/2019 | |
| 96695 AC - Eagle Woods | ELECTRICAL | Lights Out | Region 4 | 26/06/2019 | 7/1/2019 |
| 97937 AC - Eagle Woods | HVAC | | Region 4 | 2/7/2019 | 7/7/2019 |
| 98258 AC - Eagle Woods | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 8/7/2019 | |
| 98500 AC - Eagle Woods | LOCKSMITH | Locks / Keys | Region 4 | 11/7/2019 | |
| 98517 AC - Eagle Woods | | Miscellaneous | Region 4 | 11/7/2019 | |
| 98715 AC - Eagle Woods | WASTE MANAGEMENT | Debris | Region 4 | 15/07/2019 | |
| 98827 AC - Eagle Woods | GROUNDS | | Region 4 | 16/07/2019 | |
| 98281 AF - Halford James R Stadium | ROOF | | Region 4 | 9/7/2019 | |
| 89626 AS - A1C Mountain Industrial | ELECTRICAL | Lights Out | Region 4 | 18/04/2019 | |
| 90767 AS - A1C Mountain Industrial | ROOF | Roof Leak | Region 4 | 30/04/2019 | 5/5/2019 |
| 93821 AS - A1C Mountain Industrial | HVAC | | Region 4 | 29/05/2019 | 6/3/2019 |
| | | | | | |

| 95826 AS - A1C Mountain Industrial | HVAC | | Region 4 | 13/06/2019 | |
|---|-----------------------------|-------------------|----------|------------|-----------|
| 96518 AS - A1C Mountain Industrial | FIRE SAFETY | Exit SIgns | Region 4 | 24/06/2019 | |
| 97944 AS - A1C Mountain Industrial | PLUMBING | Faucet Dripping | Region 4 | 2/7/2019 | 7/7/2019 |
| 98486 AS - A1C Mountain Industrial | CARPENTRY | | Region 4 | 11/7/2019 | |
| 77166 EO - Shadow Rock Center | ROOF | Roof Leak | Region 4 | 10/12/2018 | |
| 90324 EO - Shadow Rock Center | GROUNDS | Trees | Region 4 | 25/04/2019 | |
| 92115 EO - Shadow Rock Center | GROUNDS | Miscellaneous | Region 4 | 6/5/2019 | 5/11/2019 |
| 93019 EO - Shadow Rock Center | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 17/05/2019 | |
| 97996 EO - Shadow Rock Center | CARPENTRY | Ceilings | Region 4 | 3/7/2019 | 7/8/2019 |
| 98260 EO - Shadow Rock Center | ROOF | Roof Leak | Region 4 | 8/7/2019 | |
| 98261 EO - Shadow Rock Center | LOCKSMITH | Locks / Keys | Region 4 | 8/7/2019 | |
| 80934 ES - Allgood Elementary Facility | ROOF | Roof Leak | Region 4 | 25/01/2019 | |
| 83400 ES - Allgood Elementary Facility | CARPENTRY | Floors | Region 4 | 21/02/2019 | |
| 96101 ES - Allgood Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 18/06/2019 | |
| 98286 ES - Allgood Elementary Facility | FIRE SAFETY | | Region 4 | 9/7/2019 | |
| 89483 ES - Dunaire Elementary Facility | KITCHEN EQUIPMENT | Doors | Region 4 | 16/04/2019 | |
| 90774 ES - Dunaire Elementary Facility | ROOF | Roof Leak | Region 4 | 30/04/2019 | 5/5/2019 |
| 93336 ES - Dunaire Elementary Facility | ELECTRICAL | | Region 4 | 21/05/2019 | |
| 98458 ES - Dunaire Elementary Facility | CARPENTRY | | Region 4 | 10/7/2019 | |
| 98661 ES - Dunaire Elementary Facility | KITCHEN EQUIPMENT | | Region 4 | 15/07/2019 | |
| 98663 ES - Dunaire Elementary Facility | DELIVERY | | Region 4 | 15/07/2019 | |
| 98676 ES - Dunaire Elementary Facility | ELECTRICAL | | Region 4 | 15/07/2019 | |
| 98690 ES - Dunaire Elementary Facility | PAINTING / PRESSURE WASHING | | Region 4 | 15/07/2019 | |
| 98772 ES - Dunaire Elementary Facility | ELECTRICAL | Lights Out | Region 4 | 15/07/2019 | |
| 98773 ES - Dunaire Elementary Facility | ELECTRICAL | Broken Plug | Region 4 | 15/07/2019 | |
| 79643 ES - Hambrick Elementary Facility | CARPENTRY | Miscellaneous | Region 4 | 10/1/2019 | |
| 93316 ES - Hambrick Elementary Facility | GLAZING | Broken Equipment | Region 4 | 21/05/2019 | |
| 96610 ES - Hambrick Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 25/06/2019 | |
| 96611 ES - Hambrick Elementary Facility | WAREHOUSE | Move Items | Region 4 | 25/06/2019 | |
| 96623 ES - Hambrick Elementary Facility | CARPENTRY | Ceilings | Region 4 | 25/06/2019 | |
| 96631 ES - Hambrick Elementary Facility | GROUNDS | Debris | Region 4 | 25/06/2019 | 7/12/2019 |
| 98553 ES - Hambrick Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 14/07/2019 | |
| 98826 ES - Hambrick Elementary Facility | CARPENTRY | Ceilings | Region 4 | 16/07/2019 | |
| 98830 ES - Hambrick Elementary Facility | WAREHOUSE | Move Items | Region 4 | 16/07/2019 | |
| 98831 ES - Hambrick Elementary Facility | ELECTRICAL | Broken Plug | Region 4 | 16/07/2019 | |
| 88818 ES - Indian Creek Elementary Facility | CARPENTRY | Floors | Region 4 | 9/4/2019 | |
| 93874 ES - Indian Creek Elementary Facility | GROUNDS | Structure | Region 4 | 29/05/2019 | |
| 95321 ES - Indian Creek Elementary Facility | PEST CONTROL | Pest | Region 4 | 5/6/2019 | 6/10/2019 |
| 96160 ES - Indian Creek Elementary Facility | PLUMBING | Water Leak | Region 4 | 18/06/2019 | |
| 71186 ES - Jolly Elementary Facility | KITCHEN EQUIPMENT | Move Items | Region 4 | 8/10/2018 | |
| | | | | | |

| 75060 ES - Jolly Elementary Facility | ROOF | Roof Leak | Region 4 | 12/11/2018 | |
|---|-----------------------------|-------------------|----------|------------|-----------|
| 79011 ES - Jolly Elementary Facility | ROOF | Roof Leak | Region 4 | 4/1/2019 | |
| 83808 ES - Jolly Elementary Facility | ROOF | Ceilings | Region 4 | 27/02/2019 | |
| 88596 ES - Jolly Elementary Facility | ROOF | Roof Leak | Region 4 | 8/4/2019 | |
| 89358 ES - Jolly Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 15/04/2019 | |
| 89516 ES - Jolly Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 17/04/2019 | |
| 89740 ES - Jolly Elementary Facility | ROOF | Water Leak | Region 4 | 19/04/2019 | |
| 89795 ES - Jolly Elementary Facility | ROOF | Water Leak | Region 4 | 19/04/2019 | |
| 89796 ES - Jolly Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 19/04/2019 | |
| 90018 ES - Jolly Elementary Facility | PEST CONTROL | Pest | Region 4 | 22/04/2019 | |
| 92995 ES - Jolly Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 17/05/2019 | |
| 93389 ES - Jolly Elementary Facility | GLAZING | Broken Equipment | Region 4 | 22/05/2019 | |
| 96178 ES - Jolly Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 19/06/2019 | |
| 96570 ES - Jolly Elementary Facility | KITCHEN EQUIPMENT | Stove / Oven | Region 4 | 25/06/2019 | |
| 96571 ES - Jolly Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 4 | 25/06/2019 | |
| 96572 ES - Jolly Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 4 | 25/06/2019 | |
| 96795 ES - Jolly Elementary Facility | CARPENTRY | Doors | Region 4 | 27/06/2019 | 7/12/2019 |
| 96796 ES - Jolly Elementary Facility | CARPENTRY | Floors | Region 4 | 27/06/2019 | 7/12/2019 |
| 97974 ES - Jolly Elementary Facility | CARPENTRY | Doors | Region 4 | 2/7/2019 | 7/7/2019 |
| 97990 ES - Jolly Elementary Facility | PLUMBING | Water Leak | Region 4 | 3/7/2019 | 7/8/2019 |
| 78950 ES - Rockbridge Replacement Facility | ROOF | Ceilings | Region 4 | 3/1/2019 | |
| 95301 ES - Rockbridge Replacement Facility | EQUIPMENT REPAIR | Broken Equipment | Region 4 | 5/6/2019 | 6/10/2019 |
| 95302 ES - Rockbridge Replacement Facility | EQUIPMENT REPAIR | Broken Equipment | Region 4 | 5/6/2019 | 6/10/2019 |
| 95710 ES - Rockbridge Replacement Facility | CARPENTRY | Room Too Cold | Region 4 | 11/6/2019 | |
| 34212 ES - Stone Mill Elementary Facility | ROOF | | Region 4 | 2/11/2017 | |
| 74272 ES - Stone Mill Elementary Facility | CARPENTRY | Doors | Region 4 | 1/11/2018 | |
| 80814 ES - Stone Mill Elementary Facility | CARPENTRY | Ceilings | Region 4 | 24/01/2019 | |
| 85803 ES - Stone Mill Elementary Facility | ELECTRICAL | Lights Out | Region 4 | 15/03/2019 | |
| 85892 ES - Stone Mill Elementary Facility | CARPENTRY | Miscellaneous | Region 4 | 16/03/2019 | |
| 85893 ES - Stone Mill Elementary Facility | CARPENTRY | Ceilings | Region 4 | 16/03/2019 | |
| 93542 ES - Stone Mill Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 4 | 24/05/2019 | |
| 86920 ES - Stone Mountain Elementary Facility | HVAC | | Region 4 | 25/03/2019 | |
| 89023 ES - Stone Mountain Elementary Facility | PEST CONTROL | Pest | Region 4 | 11/4/2019 | |
| 93148 ES - Stone Mountain Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 20/05/2019 | |
| 95334 ES - Stone Mountain Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 5/6/2019 | |
| 95335 ES - Stone Mountain Elementary Facility | GROUNDS | Miscellaneous | Region 4 | 5/6/2019 | 6/10/2019 |
| 96003 ES - Stone Mountain Elementary Facility | ROOF | Roof Leak | Region 4 | 17/06/2019 | |
| 96007 ES - Stone Mountain Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 4 | 17/06/2019 | |
| 98788 ES - Stone Mountain Elementary Facility | CARPENTRY | Structure | Region 4 | 16/07/2019 | |
| 98789 ES - Stone Mountain Elementary Facility | CARPENTRY | Doors | Region 4 | 16/07/2019 | |
| | | | | | |

| 48753 HS - Clarkston High Facility | ROOF | | Region 4 | 19/03/2018 | |
|---|-----------------------------|-------------------|----------|------------|-----------|
| 60382 HS - Clarkston High Facility | CARPENTRY | Floors | Region 4 | 24/07/2018 | |
| 62832 HS - Clarkston High Facility | ROOF | | Region 4 | 6/8/2018 | 8/7/2018 |
| 71619 HS - Clarkston High Facility | ROOF | Roof Leak | Region 4 | 11/10/2018 | 5,1,2525 |
| 75546 HS - Clarkston High Facility | ROOF | Roof Leak | Region 4 | 16/11/2018 | |
| 82612 HS - Clarkston High Facility | ROOF | Roof Leak | Region 4 | 8/2/2019 | |
| 83781 HS - Clarkston High Facility | GROUNDS | Roof Leak | Region 4 | 27/02/2019 | |
| 84939 HS - Clarkston High Facility | WAREHOUSE | Recycling | Region 4 | 5/3/2019 | |
| 90165 HS - Clarkston High Facility | GROUNDS | Miscellaneous | Region 4 | 23/04/2019 | |
| 91934 HS - Clarkston High Facility | EQUIPMENT REPAIR | Locks / Keys | Region 4 | 2/5/2019 | 5/7/2019 |
| 92318 HS - Clarkston High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 4 | 8/5/2019 | |
| 93232 HS - Clarkston High Facility | CARPENTRY | Miscellaneous | Region 4 | 20/05/2019 | |
| 93233 HS - Clarkston High Facility | GROUNDS | Standing Water | Region 4 | 20/05/2019 | |
| 93420 HS - Clarkston High Facility | GLAZING | Miscellaneous | Region 4 | 22/05/2019 | |
| 95997 HS - Clarkston High Facility | ROOF | | Region 4 | 17/06/2019 | |
| 96773 HS - Clarkston High Facility | CARPENTRY | Floors | Region 4 | 27/06/2019 | 7/2/2019 |
| 97900 HS - Clarkston High Facility | ROOF | Roof Leak | Region 4 | 1/7/2019 | 7/6/2019 |
| 98211 HS - Clarkston High Facility | PAINTING / PRESSURE WASHING | Paint | Region 4 | 8/7/2019 | |
| 98270 HS - Clarkston High Facility | GROUNDS | Trees | Region 4 | 8/7/2019 | |
| 98433 HS - Clarkston High Facility | KITCHEN EQUIPMENT | | Region 4 | 10/7/2019 | 7/11/2019 |
| 98478 HS - Clarkston High Facility | ELECTRICAL | No Power | Region 4 | 10/7/2019 | |
| 98660 HS - Clarkston High Facility | KITCHEN EQUIPMENT | | Region 4 | 15/07/2019 | |
| M-57778 HS - Clarkston High Facility | ROOF | | Region 4 | 19/06/2018 | |
| 96635 HS - Miller Grove High Facility | HVAC | Room Too Hot | Region 4 | 25/06/2019 | 7/12/2019 |
| 77033 HS - Stone Mountain High Facility | GLAZING | Broken Window | Region 4 | 7/12/2018 | |
| 82453 HS - Stone Mountain High Facility | CARPENTRY | Doors | Region 4 | 7/2/2019 | 5/1/2019 |
| 84788 HS - Stone Mountain High Facility | GLAZING | Broken Window | Region 4 | 4/3/2019 | 3/5/2019 |
| 85974 HS - Stone Mountain High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 4 | 18/03/2019 | |
| 86919 HS - Stone Mountain High Facility | HVAC | | Region 4 | 25/03/2019 | |
| 90384 HS - Stone Mountain High Facility | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 25/04/2019 | |
| 95127 HS - Stone Mountain High Facility | PLUMBING | Water Leak | Region 4 | 3/6/2019 | 6/8/2019 |
| 95265 HS - Stone Mountain High Facility | WASTE MANAGEMENT | Compactor / Trash | Region 4 | 4/6/2019 | 6/9/2019 |
| 95394 HS - Stone Mountain High Facility | CARPENTRY | Doors | Region 4 | 6/6/2019 | |
| 96057 HS - Stone Mountain High Facility | KITCHEN EQUIPMENT | | Region 4 | 17/06/2019 | |
| 96094 HS - Stone Mountain High Facility | GROUNDS | Broken Equipment | Region 4 | 18/06/2019 | |
| 96248 HS - Stone Mountain High Facility | ELECTRICAL | Miscellaneous | Region 4 | 19/06/2019 | |
| 96249 HS - Stone Mountain High Facility | CARPENTRY | Doors | Region 4 | 19/06/2019 | |
| 96251 HS - Stone Mountain High Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 4 | 19/06/2019 | |
| 96253 HS - Stone Mountain High Facility | GLAZING | Miscellaneous | Region 4 | 19/06/2019 | |
| 96260 HS - Stone Mountain High Facility | ROOF | Water Leak | Region 4 | 19/06/2019 | |
| | | | | | |

| 96336 HS - Stone Mountain High Facility | PLUMBING | Miscellaneous | Region 4 | 20/06/2019 | |
|---|-------------------|------------------|----------|------------|----------|
| 97952 HS - Stone Mountain High Facility | CARPENTRY | Miscellaneous | Region 4 | 2/7/2019 | 7/7/2019 |
| 98264 HS - Stone Mountain High Facility | ROOF | Water Leak | Region 4 | 8/7/2019 | |
| 98448 HS - Stone Mountain High Facility | GLAZING | Miscellaneous | Region 4 | 10/7/2019 | |
| 98450 HS - Stone Mountain High Facility | ROOF | Roof Leak | Region 4 | 10/7/2019 | |
| 98467 HS - Stone Mountain High Facility | ROOF | Roof Leak | Region 4 | 10/7/2019 | |
| 98711 HS - Stone Mountain High Facility | LOCKSMITH | Locks / Keys | Region 4 | 15/07/2019 | |
| 47626 MS - Champion Middle Theme Facility | CARPENTRY | | Region 4 | 2/3/2018 | |
| 62455 MS - Champion Middle Theme Facility | CARPENTRY | | Region 4 | 3/8/2018 | |
| 65612 MS - Champion Middle Theme Facility | KITCHEN EQUIPMENT | Discoloration | Region 4 | 29/08/2018 | |
| 69075 MS - Champion Middle Theme Facility | PEST CONTROL | Doors | Region 4 | 20/09/2018 | |
| 76297 MS - Champion Middle Theme Facility | EQUIPMENT REPAIR | Broken Equipment | Region 4 | 30/11/2018 | |
| 77438 MS - Champion Middle Theme Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 4 | 12/12/2018 | |
| 82554 MS - Champion Middle Theme Facility | ROOF | Ceilings | Region 4 | 7/2/2019 | 2/8/2019 |
| 85720 MS - Champion Middle Theme Facility | HAZARDOUS | | Region 4 | 14/03/2019 | |
| 86087 MS - Champion Middle Theme Facility | CARPENTRY | Doors | Region 4 | 19/03/2019 | |
| 86894 MS - Champion Middle Theme Facility | GROUNDS | Miscellaneous | Region 4 | 25/03/2019 | |
| 89398 MS - Champion Middle Theme Facility | PEST CONTROL | Pest | Region 4 | 16/04/2019 | |
| 92914 MS - Champion Middle Theme Facility | CARPENTRY | Doors | Region 4 | 16/05/2019 | |
| 94099 MS - Champion Middle Theme Facility | CARPENTRY | Doors | Region 4 | 31/05/2019 | 6/5/2019 |
| 95172 MS - Champion Middle Theme Facility | CARPENTRY | Ceilings | Region 4 | 3/6/2019 | 6/8/2019 |
| 98313 MS - Champion Middle Theme Facility | PEST CONTROL | Pest | Region 4 | 9/7/2019 | |
| 98385 MS - Champion Middle Theme Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 4 | 9/7/2019 | |
| 98414 MS - Champion Middle Theme Facility | ELECTRICAL | Miscellaneous | Region 4 | 10/7/2019 | |
| 98423 MS - Champion Middle Theme Facility | MASON/CONCRETE | | Region 4 | 10/7/2019 | |
| 44107 MS - Freedom Middle Facility | ROOF | | Region 4 | 9/2/2018 | |
| 48070 MS - Freedom Middle Facility | CARPENTRY | | Region 4 | 9/3/2018 | |
| 48466 MS - Freedom Middle Facility | ROOF | | Region 4 | 14/03/2018 | |
| 80024 MS - Freedom Middle Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 4 | 16/01/2019 | |
| 82307 MS - Freedom Middle Facility | ROOF | Roof Leak | Region 4 | 5/2/2019 | |
| 89402 MS - Freedom Middle Facility | ROOF | Roof Leak | Region 4 | 16/04/2019 | |
| 90338 MS - Freedom Middle Facility | PEST CONTROL | | Region 4 | 25/04/2019 | |
| 96484 MS - Freedom Middle Facility | CARPENTRY | Doors | Region 4 | 24/06/2019 | |
| 96490 MS - Freedom Middle Facility | ELECTRICAL | Broken Equipment | Region 4 | 24/06/2019 | |
| 50709 MS - Stone Mountain Middle Facility | GROUNDS | | Region 4 | 16/04/2018 | |
| 83154 MS - Stone Mountain Middle Facility | ROOF | Roof Leak | Region 4 | 20/02/2019 | |
| 92922 MS - Stone Mountain Middle Facility | GLAZING | Broken Window | Region 4 | 16/05/2019 | |
| 95249 MS - Stone Mountain Middle Facility | CARPENTRY | Structure | Region 4 | 4/6/2019 | 6/9/2019 |
| 95658 MS - Stone Mountain Middle Facility | HVAC | | Region 4 | 11/6/2019 | |
| 83013 ES - Bob Mathis Elementary Facility | GLAZING | Broken Window | Region 5 | 15/02/2019 | |
| | | | | | |

| 88563 ES - Bob Mathis Elementary Facility | ROOF | Roof Leak | Region 5 | 8/4/2019 | |
|--|------------------|------------------|----------|------------|-----------|
| 89678 ES - Bob Mathis Elementary Facility | ROOF | Water Leak | Region 5 | 19/04/2019 | |
| 89683 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 19/04/2019 | |
| 93224 ES - Bob Mathis Elementary Facility | HOUSEKEEPING | Water Leak | Region 5 | 20/05/2019 | |
| 93479 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 23/05/2019 | |
| 96205 ES - Bob Mathis Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 19/06/2019 | |
| 96470 ES - Bob Mathis Elementary Facility | HVAC | | Region 5 | 24/06/2019 | |
| 98051 ES - Bob Mathis Elementary Facility | HVAC | Water Leak | Region 5 | 5/7/2019 | 7/10/2019 |
| 98052 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 5/7/2019 | 7/10/2019 |
| 98053 ES - Bob Mathis Elementary Facility | WAREHOUSE | Broken Equipment | Region 5 | 5/7/2019 | |
| 98175 ES - Bob Mathis Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 8/7/2019 | |
| 98176 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 8/7/2019 | |
| 98191 ES - Bob Mathis Elementary Facility | HVAC | | Region 5 | 8/7/2019 | |
| 98305 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 9/7/2019 | |
| 98405 ES - Bob Mathis Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 10/7/2019 | |
| 98406 ES - Bob Mathis Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 10/7/2019 | |
| 98410 ES - Bob Mathis Elementary Facility | ELECTRONICS | Lights Out | Region 5 | 10/7/2019 | |
| 98411 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 10/7/2019 | |
| 98412 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 10/7/2019 | |
| 98413 ES - Bob Mathis Elementary Facility | HVAC | Room Too Hot | Region 5 | 10/7/2019 | |
| 98834 ES - Bob Mathis Elementary Facility | | Lights Out | Region 5 | 16/07/2019 | |
| 98836 ES - Bob Mathis Elementary Facility | | Miscellaneous | Region 5 | 16/07/2019 | |
| 98837 ES - Bob Mathis Elementary Facility | | Miscellaneous | Region 5 | 16/07/2019 | |
| 98838 ES - Bob Mathis Elementary Facility | | Miscellaneous | Region 5 | 16/07/2019 | |
| 98839 ES - Bob Mathis Elementary Facility | | Lights Out | Region 5 | 16/07/2019 | |
| 98840 ES - Bob Mathis Elementary Facility | | Lights Out | Region 5 | 16/07/2019 | |
| 98841 ES - Bob Mathis Elementary Facility | | Lights Out | Region 5 | 16/07/2019 | |
| 98842 ES - Bob Mathis Elementary Facility | | Lights Out | Region 5 | 16/07/2019 | |
| 98843 ES - Bob Mathis Elementary Facility | | Miscellaneous | Region 5 | 16/07/2019 | |
| 98845 ES - Bob Mathis Elementary Facility | PLUMBING | Miscellaneous | Region 5 | 16/07/2019 | |
| 98846 ES - Bob Mathis Elementary Facility | PLUMBING | Broken Equipment | Region 5 | 16/07/2019 | |
| 98847 ES - Bob Mathis Elementary Facility | CARPENTRY | Floors | Region 5 | 16/07/2019 | |
| 49502 ES - Browns Mill Elementary Facility | CARPENTRY | | Region 5 | 28/03/2018 | |
| 50067 ES - Browns Mill Elementary Facility | CARPENTRY | | Region 5 | 2/4/2018 | |
| 60289 ES - Browns Mill Elementary Facility | CARPENTRY | | Region 5 | 24/07/2018 | |
| 75709 ES - Browns Mill Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 26/11/2018 | |
| 85729 ES - Browns Mill Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 5 | 14/03/2019 | |
| 88380 ES - Browns Mill Elementary Facility | WAREHOUSE | Cove Base | Region 5 | 1/4/2019 | |
| 88754 ES - Browns Mill Elementary Facility | HVAC | Water Leak | Region 5 | 9/4/2019 | |
| 88842 ES - Browns Mill Elementary Facility | HVAC | Room Too Hot | Region 5 | 10/4/2019 | |
| | | | | | |

| 89301 ES - Browns Mill Elementary Facility | ROOF | Roof Leak | Region 5 | 15/04/2019 | |
|--|-----------------------------|----------------------|----------|------------|-----------|
| 89569 ES - Browns Mill Elementary Facility | HVAC | Room Too Hot | Region 5 | 17/04/2019 | |
| 89729 ES - Browns Mill Elementary Facility | ROOF | Roof Leak | Region 5 | 19/04/2019 | |
| 92202 ES - Browns Mill Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 7/5/2019 | 5/12/2019 |
| 92671 ES - Browns Mill Elementary Facility | HVAC | Water Leak | Region 5 | 13/05/2019 | 3,12,2013 |
| 93005 ES - Browns Mill Elementary Facility | HVAC | Room Too Hot | Region 5 | 17/05/2019 | |
| 93006 ES - Browns Mill Elementary Facility | HVAC | Room Too Hot | Region 5 | 17/05/2019 | |
| 93501 ES - Browns Mill Elementary Facility | ENVIRONMENTAL SVCS | Room roo not | Region 5 | 23/05/2019 | |
| 93770 ES - Browns Mill Elementary Facility | CARPENTRY | Doors | Region 5 | 28/05/2019 | 6/2/2019 |
| 95156 ES - Browns Mill Elementary Facility | HVAC | Water Leak | _ | 3/6/2019 | 6/8/2019 |
| | | | Region 5 | | 0/8/2019 |
| 96011 ES - Browns Mill Elementary Facility | ELECTRICAL CARPENTRY | Lights Out Floors | Region 5 | 17/06/2019 | 7/12/2010 |
| 96538 ES - Browns Mill Elementary Facility | | F1001S | Region 5 | 24/06/2019 | 7/12/2019 |
| 96608 ES - Browns Mill Elementary Facility | PLUMBING | | Region 5 | 25/06/2019 | |
| 98174 ES - Browns Mill Elementary Facility | HVAC | | Region 5 | 8/7/2019 | |
| 98216 ES - Browns Mill Elementary Facility | PLUMBING | | Region 5 | 8/7/2019 | |
| 98319 ES - Browns Mill Elementary Facility | HVAC | Room Too Hot | Region 5 | 9/7/2019 | |
| 98455 ES - Browns Mill Elementary Facility | CARPENTRY | Ceilings | Region 5 | 10/7/2019 | |
| 98494 ES - Browns Mill Elementary Facility | ELECTRICAL | Exit SIgns | Region 5 | 11/7/2019 | |
| 98693 ES - Browns Mill Elementary Facility | PAINTING / PRESSURE WASHING | | Region 5 | 15/07/2019 | |
| 98787 ES - Browns Mill Elementary Facility | CARPENTRY | | Region 5 | 16/07/2019 | |
| 98818 ES - Browns Mill Elementary Facility | | Doors | Region 5 | 16/07/2019 | |
| 55460 ES - Chapel Hill Elementary Facility | CARPENTRY | | Region 5 | 26/05/2018 | |
| 60125 ES - Chapel Hill Elementary Facility | CARPENTRY | | Region 5 | 19/07/2018 | |
| 67905 ES - Chapel Hill Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 5 | 6/9/2018 | |
| 77759 ES - Chapel Hill Elementary Facility | GLAZING | | Region 5 | 18/12/2018 | |
| 82412 ES - Chapel Hill Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 5 | 6/2/2019 | 2/7/2019 |
| 85336 ES - Chapel Hill Elementary Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 5 | 11/3/2019 | |
| 90285 ES - Chapel Hill Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 5 | 25/04/2019 | |
| 90617 ES - Chapel Hill Elementary Facility | WAREHOUSE | Miscellaneous | Region 5 | 29/04/2019 | 5/4/2019 |
| 90702 ES - Chapel Hill Elementary Facility | WAREHOUSE | Lights Out | Region 5 | 30/04/2019 | 5/5/2019 |
| 92388 ES - Chapel Hill Elementary Facility | CARPENTRY | Structure | Region 5 | 9/5/2019 | |
| 92956 ES - Chapel Hill Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 16/05/2019 | |
| 93351 ES - Chapel Hill Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 22/05/2019 | |
| 93590 ES - Chapel Hill Elementary Facility | CARPENTRY | Locks / Keys | Region 5 | 24/05/2019 | |
| 94990 ES - Chapel Hill Elementary Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 5 | 2/6/2019 | |
| 94991 ES - Chapel Hill Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 2/6/2019 | |
| 94992 ES - Chapel Hill Elementary Facility | VENDOR | Floors | Region 5 | 2/6/2019 | |
| 96199 ES - Chapel Hill Elementary Facility | FURNISHING | Whiteboards | Region 5 | 19/06/2019 | |
| 96525 ES - Chapel Hill Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 5 | 24/06/2019 | |
| 96636 ES - Chapel Hill Elementary Facility | HVAC | | Region 5 | 25/06/2019 | |
| | | | | | |

| 96732 ES - Chapel Hill Elementary Facility | DELIVERY | Ceilings | Region 5 | 26/06/2019 | 7/12/2019 |
|---|-----------------------------|--------------------|----------------------|------------|-----------|
| 97925 ES - Chapel Hill Elementary Facility | HVAC | CCIIII63 | Region 5 | 2/7/2019 | 7/7/2019 |
| 98192 ES - Chapel Hill Elementary Facility | HVAC | | Region 5 | 8/7/2019 | 7,7,2013 |
| 98457 ES - Chapel Hill Elementary Facility | PLUMBING | Water Leak | Region 5 | 10/7/2019 | |
| 98459 ES - Chapel Hill Elementary Facility | HVAC | Room Too Hot | Region 5 | 10/7/2019 | |
| 98528 ES - Chapel Hill Elementary Facility | HVAC | Broken Equipment | Region 5 | 11/7/2019 | |
| 98542 ES - Chapel Hill Elementary Facility | PLUMBING | Broken Equipment | Region 5 | 11/7/2019 | |
| 98730 ES - Chapel Hill Elementary Facility | HVAC | Water Leak | Region 5 | 15/07/2019 | |
| 57312 ES - Edward L. Bouie, Sr. Elementary Facility | PLUMBING | Water Leak | Region 5 | 12/6/2018 | |
| 85261 ES - Edward L. Bouie, Sr. Elementary Facility | ROOF | Roof Leak | Region 5 | 7/3/2019 | |
| 92795 ES - Edward L. Bouie, Sr. Elementary Facility | ELECTRONICS | Intercom | Region 5 | 14/05/2019 | |
| 93706 ES - Edward L. Bouie, Sr. Elementary Facility | HVAC | Water Leak | Region 5 | 28/05/2019 | 6/2/2019 |
| 94093 ES - Edward L. Bouie, Sr. Elementary Facility | GLAZING | Broken Window | Region 5 | 31/05/2019 | 0,2,2013 |
| 96066 ES - Edward L. Bouie, Sr. Elementary Facility | HVAC | Broken Willdow | Region 5 | 18/06/2019 | |
| 96520 ES - Edward L. Bouie, Sr. Elementary Facility | FIRE SAFETY | Fire Alarm | Region 5 | 24/06/2019 | 7/12/2019 |
| 96522 ES - Edward L. Bouie, Sr. Elementary Facility | LOCKSMITH | Locks / Keys | Region 5 | 24/06/2019 | 7/12/2013 |
| 96734 ES - Edward L. Bouie, Sr. Elementary Facility | ROOF | Roof Leak | Region 5 | 26/06/2019 | 7/12/2019 |
| 96735 ES - Edward L. Bouie, Sr. Elementary Facility | PLUMBING | Toilet Overflowing | Region 5 | 26/06/2019 | 7/12/2019 |
| 98670 ES - Edward L. Bouie, Sr. Elementary Facility | ELECTRICAL | Tollet Overnowing | Region 5 | 15/07/2019 | 7/12/2013 |
| 89684 ES - Fairington Elementary Facility | PAINTING / PRESSURE WASHING | Floors | Region 5 | 19/04/2019 | |
| 93563 ES - Fairington Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 24/05/2019 | |
| 93704 ES - Fairington Elementary Facility | HVAC | Miscellaneous | Region 5 | 28/05/2019 | 6/2/2019 |
| 95818 ES - Fairington Elementary Facility | CARPENTRY | Ceilings | Region 5 | 13/06/2019 | 0/2/2013 |
| 96122 ES - Fairington Elementary Facility | GLAZING | Miscellaneous | Region 5 | 18/06/2019 | |
| 96123 ES - Fairington Elementary Facility | GROUNDS | Miscellaneous | Region 5 | 18/06/2019 | |
| 98506 ES - Fairington Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98507 ES - Fairington Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98509 ES - Fairington Elementary Facility | PLUMBING | Water Leak | Region 5 | 11/7/2019 | |
| 98786 ES - Fairington Elementary Facility | CARPENTRY | water Leak | Region 5 | 16/07/2019 | |
| 59091 ES - Flat Rock Elementary facility | CARPENTRY | | Region 5 | 3/7/2019 | 7/4/2018 |
| 62273 ES - Flat Rock Elementary facility | ROOF | Ceilings | _ | 2/8/2018 | 7/4/2018 |
| | PAINTING / PRESSURE WASHING | Paint | Region 5 | 30/08/2018 | |
| 65710 ES - Flat Rock Elementary facility 77285 ES - Flat Rock Elementary facility | ROOF | Roof Leak | Region 5 Region 5 | 11/12/2018 | |
| 77265 ES - Flat Rock Elementary facility | CARPENTRY | Miscellaneous | Region 5 | 20/12/2018 | |
| • • • | | | · · | | |
| 81075 ES - Flat Rock Elementary facility | ELECTRICAL | Lights Out | Region 5 | 28/01/2019 | |
| 82748 ES - Flat Rock Elementary facility | HVAC ROOF | Roof Leak | Region 5 | 11/2/2019 | |
| 85860 ES - Flat Rock Elementary facility | | | Region 5 | 15/03/2019 | |
| 85968 ES - Flat Rock Elementary facility | WAREHOUSE | Miscellaneous | Region 5 | 18/03/2019 | |
| 89761 ES - Flat Rock Elementary facility | ROOF | Roof Leak | Region 5 | 19/04/2019 | |
| 90099 ES - Flat Rock Elementary facility | ROOF | Roof Leak | Region 5 | 23/04/2019 | |

| 90655 ES - Flat Rock Elementary facility | HVAC | Room Too Hot | Region 5 | 29/04/2019 | 5/4/2019 |
|---|-----------------------------|-------------------|----------|------------|-----------|
| 92973 ES - Flat Rock Elementary facility | WASTE MANAGEMENT | Compactor / Trash | Region 5 | 17/05/2019 | |
| 96047 ES - Flat Rock Elementary facility | HVAC | Room Too Hot | Region 5 | 17/06/2019 | |
| 96185 ES - Flat Rock Elementary facility | GROUNDS | Structure | Region 5 | 19/06/2019 | |
| 97985 ES - Flat Rock Elementary facility | FIRE SAFETY | Fire Alarm | Region 5 | 3/7/2019 | 7/8/2019 |
| 98220 ES - Flat Rock Elementary facility | HVAC | Room Too Hot | Region 5 | 8/7/2019 | |
| 98222 ES - Flat Rock Elementary facility | ELECTRICAL | Lights Out | Region 5 | 8/7/2019 | |
| 98226 ES - Flat Rock Elementary facility | GROUNDS | Broken Equipment | Region 5 | 8/7/2019 | |
| 98229 ES - Flat Rock Elementary facility | LOCKSMITH | Doors | Region 5 | 8/7/2019 | |
| 76910 ES - Murphy Candler Elementary Facility | ROOF | Roof Leak | Region 5 | 6/12/2018 | |
| 78983 ES - Murphy Candler Elementary Facility | ROOF | Roof Leak | Region 5 | 3/1/2019 | |
| 82959 ES - Murphy Candler Elementary Facility | ROOF | Roof Leak | Region 5 | 14/02/2019 | |
| 83178 ES - Murphy Candler Elementary Facility | ROOF | Roof Leak | Region 5 | 20/02/2019 | |
| 89645 ES - Murphy Candler Elementary Facility | HVAC | Room Too Hot | Region 5 | 18/04/2019 | |
| 90282 ES - Murphy Candler Elementary Facility | KITCHEN EQUIPMENT | Water Leak | Region 5 | 25/04/2019 | |
| 90667 ES - Murphy Candler Elementary Facility | HVAC | Miscellaneous | Region 5 | 29/04/2019 | 5/4/2019 |
| 92179 ES - Murphy Candler Elementary Facility | HVAC | Miscellaneous | Region 5 | 6/5/2019 | 5/11/2019 |
| 93138 ES - Murphy Candler Elementary Facility | HVAC | Room Too Hot | Region 5 | 20/05/2019 | |
| 93450 ES - Murphy Candler Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 23/05/2019 | |
| 93455 ES - Murphy Candler Elementary Facility | HVAC | Room Too Hot | Region 5 | 23/05/2019 | |
| 95362 ES - Murphy Candler Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 6/6/2019 | 6/11/2019 |
| 95373 ES - Murphy Candler Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 6/6/2019 | 6/11/2019 |
| 95575 ES - Murphy Candler Elementary Facility | ROOF | Roof Leak | Region 5 | 10/6/2019 | |
| 96223 ES - Murphy Candler Elementary Facility | HVAC | Room Too Hot | Region 5 | 19/06/2019 | |
| 96323 ES - Murphy Candler Elementary Facility | HVAC | Room Too Hot | Region 5 | 20/06/2019 | |
| 96485 ES - Murphy Candler Elementary Facility | HVAC | Room Too Hot | Region 5 | 24/06/2019 | |
| 96771 ES - Murphy Candler Elementary Facility | HVAC | Miscellaneous | Region 5 | 27/06/2019 | 7/12/2019 |
| 96772 ES - Murphy Candler Elementary Facility | PLUMBING | Miscellaneous | Region 5 | 27/06/2019 | 7/12/2019 |
| 96804 ES - Murphy Candler Elementary Facility | PAINTING / PRESSURE WASHING | Miscellaneous | Region 5 | 27/06/2019 | 7/2/2019 |
| 96805 ES - Murphy Candler Elementary Facility | CARPENTRY | Doors | Region 5 | 27/06/2019 | |
| 97856 ES - Murphy Candler Elementary Facility | HVAC | Miscellaneous | Region 5 | 1/7/2019 | |
| 98397 ES - Murphy Candler Elementary Facility | HVAC | | Region 5 | 10/7/2019 | |
| 98671 ES - Murphy Candler Elementary Facility | GROUNDS | Miscellaneous | Region 5 | 15/07/2019 | |
| 98680 ES - Murphy Candler Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 15/07/2019 | |
| 98756 ES - Murphy Candler Elementary Facility | HVAC | | Region 5 | 15/07/2019 | |
| 60887 ES - Panola Way Elementary Facility | CARPENTRY | Ceilings | Region 5 | 31/07/2018 | 8/1/2018 |
| 62468 ES - Panola Way Elementary Facility | GLAZING | Broken Window | Region 5 | 3/8/2018 | |
| 71607 ES - Panola Way Elementary Facility | GLAZING | Broken Window | Region 5 | 11/10/2018 | |
| 76775 ES - Panola Way Elementary Facility | ROOF | Roof Leak | Region 5 | 5/12/2018 | |
| 81232 ES - Panola Way Elementary Facility | GLAZING | Broken Window | Region 5 | 30/01/2019 | |
| · , , | | | - | | |

| 85752 ES - Panola Way Elementary Facility | GLAZING | Broken Window | Region 5 | 14/03/2019 | |
|---|-----------------------------|-------------------|----------|------------|------------|
| 86374 ES - Panola Way Elementary Facility | GLAZING | Broken Window | Region 5 | 21/03/2019 | |
| 86441 ES - Panola Way Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 22/03/2019 | |
| 91553 ES - Panola Way Elementary Facility | HVAC | Roof Leak | Region 5 | 1/5/2019 | 5/6/2019 |
| 95170 ES - Panola Way Elementary Facility | HVAC | Room Too Hot | Region 5 | 3/6/2019 | 6/8/2019 |
| 95786 ES - Panola Way Elementary Facility | PAINTING / PRESSURE WASHING | Miscellaneous | Region 5 | 12/6/2019 | |
| 95787 ES - Panola Way Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 12/6/2019 | |
| 96217 ES - Panola Way Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 19/06/2019 | |
| 96784 ES - Panola Way Elementary Facility | HVAC | Water Leak | Region 5 | 27/06/2019 | 7/2/2019 |
| 98362 ES - Panola Way Elementary Facility | HVAC | | Region 5 | 9/7/2019 | |
| 98421 ES - Panola Way Elementary Facility | GROUNDS | Trees | Region 5 | 10/7/2019 | |
| 98514 ES - Panola Way Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98515 ES - Panola Way Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98516 ES - Panola Way Elementary Facility | ELECTRONICS | Miscellaneous | Region 5 | 11/7/2019 | |
| 98695 ES - Panola Way Elementary Facility | GROUNDS | Miscellaneous | Region 5 | 15/07/2019 | |
| 98705 ES - Panola Way Elementary Facility | HVAC | Room Too Hot | Region 5 | 15/07/2019 | |
| 98785 ES - Panola Way Elementary Facility | CARPENTRY | | Region 5 | 16/07/2019 | |
| 71518 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 10/10/2018 | |
| 71555 ES - Rainbow Elementary Facility | ROOF | Roof Leak | Region 5 | 11/10/2018 | |
| 75190 ES - Rainbow Elementary Facility | ROOF | Roof Leak | Region 5 | 13/11/2018 | |
| 76903 ES - Rainbow Elementary Facility | CARPENTRY | Doors | Region 5 | 6/12/2018 | |
| 77140 ES - Rainbow Elementary Facility | ROOF | Roof Leak | Region 5 | 10/12/2018 | 12/10/2018 |
| 77327 ES - Rainbow Elementary Facility | CARPENTRY | Doors | Region 5 | 11/12/2018 | |
| 79085 ES - Rainbow Elementary Facility | ROOF | Roof Leak | Region 5 | 4/1/2019 | |
| 82408 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 6/2/2019 | 2/6/2019 |
| 86235 ES - Rainbow Elementary Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 20/03/2019 | |
| 86247 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 20/03/2019 | |
| 87161 ES - Rainbow Elementary Facility | HVAC | | Region 5 | 27/03/2019 | |
| 88772 ES - Rainbow Elementary Facility | GROUNDS | Compactor / Trash | Region 5 | 9/4/2019 | |
| 89771 ES - Rainbow Elementary Facility | ROOF | Miscellaneous | Region 5 | 19/04/2019 | |
| 89772 ES - Rainbow Elementary Facility | ROOF | Miscellaneous | Region 5 | 19/04/2019 | |
| 89814 ES - Rainbow Elementary Facility | ROOF | Water Leak | Region 5 | 19/04/2019 | |
| 90459 ES - Rainbow Elementary Facility | WAREHOUSE | Miscellaneous | Region 5 | 26/04/2019 | 5/1/2019 |
| 90460 ES - Rainbow Elementary Facility | WAREHOUSE | Supplies Needed | Region 5 | 26/04/2019 | 5/1/2019 |
| 92784 ES - Rainbow Elementary Facility | ELECTRONICS | Miscellaneous | Region 5 | 14/05/2019 | |
| 92932 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
| 92933 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
| 92934 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
| 92935 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
| 92936 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
| | | | | | |

| 92938 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
|--|-------------------|---------------|----------|------------|-----------|
| 92959 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 16/05/2019 | |
| 93840 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 29/05/2019 | 6/3/2019 |
| 93912 ES - Rainbow Elementary Facility | HVAC | Miscellaneous | Region 5 | 30/05/2019 | |
| 95135 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 3/6/2019 | |
| 95137 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 3/6/2019 | |
| 95420 ES - Rainbow Elementary Facility | ELECTRICAL | Miscellaneous | Region 5 | 6/6/2019 | 6/11/2019 |
| 95560 ES - Rainbow Elementary Facility | ELECTRICAL | Miscellaneous | Region 5 | 10/6/2019 | |
| 95711 ES - Rainbow Elementary Facility | WASTE MANAGEMENT | Miscellaneous | Region 5 | 11/6/2019 | |
| 95857 ES - Rainbow Elementary Facility | MASON/CONCRETE | Miscellaneous | Region 5 | 13/06/2019 | |
| 95858 ES - Rainbow Elementary Facility | ELECTRICAL | Miscellaneous | Region 5 | 13/06/2019 | |
| 96340 ES - Rainbow Elementary Facility | ELECTRICAL | Noises | Region 5 | 20/06/2019 | |
| 97929 ES - Rainbow Elementary Facility | PEST CONTROL | Pest | Region 5 | 2/7/2019 | 7/7/2019 |
| 98310 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 9/7/2019 | |
| 98361 ES - Rainbow Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 9/7/2019 | |
| 98447 ES - Rainbow Elementary Facility | HVAC | Miscellaneous | Region 5 | 10/7/2019 | |
| 98479 ES - Rainbow Elementary Facility | KITCHEN EQUIPMENT | | Region 5 | 11/7/2019 | |
| 98489 ES - Rainbow Elementary Facility | FIRE SAFETY | Fire Alarm | Region 5 | 11/7/2019 | |
| 98501 ES - Rainbow Elementary Facility | ELECTRICAL | Miscellaneous | Region 5 | 11/7/2019 | |
| 98502 ES - Rainbow Elementary Facility | ELECTRICAL | Miscellaneous | Region 5 | 11/7/2019 | |
| 98665 ES - Rainbow Elementary Facility | FIRE SAFETY | | Region 5 | 15/07/2019 | |
| 98674 ES - Rainbow Elementary Facility | FIRE SAFETY | Fire Alarm | Region 5 | 15/07/2019 | |
| 98701 ES - Rainbow Elementary Facility | EQUIPMENT REPAIR | Miscellaneous | Region 5 | 15/07/2019 | |
| 98703 ES - Rainbow Elementary Facility | DELIVERY | Miscellaneous | Region 5 | 15/07/2019 | |
| 98722 ES - Rainbow Elementary Facility | PLUMBING | Miscellaneous | Region 5 | 15/07/2019 | |
| 98797 ES - Rainbow Elementary Facility | ROOF | Roof Leak | Region 5 | 16/07/2019 | |
| 98844 ES - Rainbow Elementary Facility | FIRE SAFETY | Fire Alarm | Region 5 | 16/07/2019 | |
| 96717 ES - Rowland Elementary Facility | HVAC | Room Too Hot | Region 5 | 26/06/2019 | |
| 98713 ES - Rowland Elementary Facility | HVAC | Room Too Hot | Region 5 | 15/07/2019 | 8/4/2019 |
| 60995 ES - Woodridge Elementary Facility | CARPENTRY | Floors | Region 5 | 31/07/2018 | |
| 75183 ES - Woodridge Elementary Facility | ROOF | Roof Leak | Region 5 | 13/11/2018 | |
| 83549 ES - Woodridge Elementary Facility | HVAC | Room Too Hot | Region 5 | 25/02/2019 | |
| 86891 ES - Woodridge Elementary Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 25/03/2019 | |
| 88681 ES - Woodridge Elementary Facility | HAZARDOUS | | Region 5 | 9/4/2019 | |
| 93850 ES - Woodridge Elementary Facility | CARPENTRY | Doors | Region 5 | 29/05/2019 | 6/3/2019 |
| 95544 ES - Woodridge Elementary Facility | HVAC | Ceilings | Region 5 | 10/6/2019 | |
| 95750 ES - Woodridge Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 12/6/2019 | |
| 96264 ES - Woodridge Elementary Facility | HVAC | Room Too Hot | Region 5 | 19/06/2019 | |
| 96349 ES - Woodridge Elementary Facility | HVAC | Room Too Hot | Region 5 | 20/06/2019 | |
| 96361 ES - Woodridge Elementary Facility | GROUNDS | Trees | Region 5 | 20/06/2019 | |
| | | | | | |

| 96530 ES - Woodridge Elementary Facility | CARPENTRY | Doors | Region 5 | 24/06/2019 | 7/12/2019 |
|---|-----------------------------|------------------|----------|------------|-----------|
| 96532 ES - Woodridge Elementary Facility | WASTE MANAGEMENT | Broken Equipment | Region 5 | 24/06/2019 | |
| 96713 ES - Woodridge Elementary Facility | HVAC | Broken Equipment | Region 5 | 26/06/2019 | 7/12/2019 |
| 96718 ES - Woodridge Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 5 | 26/06/2019 | |
| 98057 ES - Woodridge Elementary Facility | CARPENTRY | Doors | Region 5 | 5/7/2019 | |
| 98302 ES - Woodridge Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 9/7/2019 | |
| 98303 ES - Woodridge Elementary Facility | CARPENTRY | Doors | Region 5 | 9/7/2019 | |
| 98304 ES - Woodridge Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 9/7/2019 | |
| 98306 ES - Woodridge Elementary Facility | PEST CONTROL | Pest | Region 5 | 9/7/2019 | |
| 98428 ES - Woodridge Elementary Facility | GROUNDS | Trees | Region 5 | 10/7/2019 | |
| 98518 ES - Woodridge Elementary Facility | HVAC | Room Too Hot | Region 5 | 11/7/2019 | |
| 98521 ES - Woodridge Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98522 ES - Woodridge Elementary Facility | CARPENTRY | Floors | Region 5 | 11/7/2019 | |
| 98523 ES - Woodridge Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 11/7/2019 | |
| 98541 ES - Woodridge Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98544 ES - Woodridge Elementary Facility | CARPENTRY | Miscellaneous | Region 5 | 11/7/2019 | |
| 98546 ES - Woodridge Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 11/7/2019 | |
| 98547 ES - Woodridge Elementary Facility | ELECTRICAL | Lights Out | Region 5 | 11/7/2019 | |
| 98549 ES - Woodridge Elementary Facility | PEST CONTROL | Pest | Region 5 | 11/7/2019 | |
| 98725 ES - Woodridge Elementary Facility | GROUNDS | Miscellaneous | Region 5 | 15/07/2019 | |
| 43850 HS - Martin Luther King Jr. High Facility | ROOF | | Region 5 | 7/2/2018 | 2/8/2018 |
| 43869 HS - Martin Luther King Jr. High Facility | ROOF | | Region 5 | 7/2/2018 | |
| 53833 HS - Martin Luther King Jr. High Facility | GLAZING | | Region 5 | 4/5/2018 | |
| 56958 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 5/6/2018 | |
| 57249 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 11/6/2018 | |
| 59344 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 10/7/2018 | 7/11/2018 |
| 60554 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 26/07/2018 | |
| 69587 HS - Martin Luther King Jr. High Facility | ROOF | Miscellaneous | Region 5 | 26/09/2018 | |
| 71307 HS - Martin Luther King Jr. High Facility | ROOF | Roof Leak | Region 5 | 9/10/2018 | |
| 71598 HS - Martin Luther King Jr. High Facility | ROOF | Miscellaneous | Region 5 | 11/10/2018 | |
| 71599 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 11/10/2018 | |
| 72496 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 23/10/2018 | |
| 72983 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 30/10/2018 | |
| 77182 HS - Martin Luther King Jr. High Facility | ROOF | Miscellaneous | Region 5 | 10/12/2018 | |
| 77305 HS - Martin Luther King Jr. High Facility | GLAZING | Miscellaneous | Region 5 | 11/12/2018 | |
| 77311 HS - Martin Luther King Jr. High Facility | GLAZING | Miscellaneous | Region 5 | 11/12/2018 | |
| 77677 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 17/12/2018 | |
| 77772 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 18/12/2018 | |
| 79206 HS - Martin Luther King Jr. High Facility | GROUNDS | Miscellaneous | Region 5 | 7/1/2019 | |
| 79209 HS - Martin Luther King Jr. High Facility | GROUNDS | Miscellaneous | Region 5 | 7/1/2019 | |
| | | | | | |

| 79430 HS - Martin Luther King Jr. High Facility | GLAZING | Miscellaneous | Region 5 | 9/1/2019 | |
|---|-------------------|----------------------|----------|------------|-----------|
| 80675 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 23/01/2019 | |
| 81213 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 30/01/2019 | |
| 82191 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 4/2/2019 | |
| 82209 HS - Martin Luther King Jr. High Facility | GLAZING | Broken Window | Region 5 | 4/2/2019 | |
| 82332 HS - Martin Luther King Jr. High Facility | GLAZING | Broken Window | Region 5 | 5/2/2019 | |
| 82349 HS - Martin Luther King Jr. High Facility | GLAZING | Broken Window | Region 5 | 6/2/2019 | |
| 83168 HS - Martin Luther King Jr. High Facility | ROOF | Miscellaneous | Region 5 | 20/02/2019 | |
| 83303 HS - Martin Luther King Jr. High Facility | ROOF | Miscellaneous | Region 5 | 21/02/2019 | |
| 83446 HS - Martin Luther King Jr. High Facility | ROOF | Miscellaneous | Region 5 | 22/02/2019 | |
| 85058 HS - Martin Luther King Jr. High Facility | PEST CONTROL | Miscellaneous | Region 5 | 6/3/2019 | 3/7/2019 |
| 88373 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 1/4/2019 | |
| 90659 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 29/04/2019 | |
| 90716 HS - Martin Luther King Jr. High Facility | HVAC | Miscellaneous | Region 5 | 30/04/2019 | 5/5/2019 |
| 92231 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 7/5/2019 | 5/12/2019 |
| 92263 HS - Martin Luther King Jr. High Facility | HVAC | Miscellaneous | Region 5 | 7/5/2019 | 5/12/2019 |
| 92483 HS - Martin Luther King Jr. High Facility | GLAZING | Miscellaneous | Region 5 | 10/5/2019 | |
| 92703 HS - Martin Luther King Jr. High Facility | HVAC | Miscellaneous | Region 5 | 13/05/2019 | |
| 92704 HS - Martin Luther King Jr. High Facility | CARPENTRY | Doors | Region 5 | 13/05/2019 | |
| 92707 HS - Martin Luther King Jr. High Facility | GROUNDS | Miscellaneous | Region 5 | 13/05/2019 | |
| 92716 HS - Martin Luther King Jr. High Facility | GROUNDS | Decking | Region 5 | 13/05/2019 | |
| 92829 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 15/05/2019 | |
| 92834 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 15/05/2019 | |
| 92855 HS - Martin Luther King Jr. High Facility | GROUNDS | Miscellaneous | Region 5 | 15/05/2019 | |
| 92890 HS - Martin Luther King Jr. High Facility | GROUNDS | Miscellaneous | Region 5 | 15/05/2019 | |
| 92893 HS - Martin Luther King Jr. High Facility | GROUNDS | Miscellaneous | Region 5 | 15/05/2019 | |
| 93022 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 17/05/2019 | |
| 93588 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 24/05/2019 | |
| 95120 HS - Martin Luther King Jr. High Facility | FIRE SAFETY | | Region 5 | 3/6/2019 | 6/8/2019 |
| 95153 HS - Martin Luther King Jr. High Facility | HVAC | Miscellaneous | Region 5 | 3/6/2019 | 6/8/2019 |
| 95181 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 3/6/2019 | 6/8/2019 |
| 95182 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 3/6/2019 | 6/8/2019 |
| 95183 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 3/6/2019 | 6/8/2019 |
| 95189 HS - Martin Luther King Jr. High Facility | CARPENTRY | Broken Window | Region 5 | 3/6/2019 | 6/8/2019 |
| 95192 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 3/6/2019 | 6/8/2019 |
| 95194 HS - Martin Luther King Jr. High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 3/6/2019 | 6/8/2019 |
| 95195 HS - Martin Luther King Jr. High Facility | CARPENTRY | Locks / Keys | Region 5 | 3/6/2019 | 6/8/2019 |
| 95243 HS - Martin Luther King Jr. High Facility | WASTE MANAGEMENT | Miscellaneous | Region 5 | 4/6/2019 | 6/9/2019 |
| 95366 HS - Martin Luther King Jr. High Facility | WASTE MANAGEMENT | Compactor / Trash | Region 5 | 6/6/2019 | 6/11/2019 |
| 95546 HS - Martin Luther King Jr. High Facility | WASTE MANAGEMENT | Compactor / Trash | Region 5 | 10/6/2019 | |
| | | | | | |

| 95673 HS - Martin Luther King Jr. High Facility | WASTE MANAGEMENT | Compactor / Trash | Region 5 | 11/6/2019 | |
|---|-----------------------------|-------------------|----------|------------|----------|
| 96046 HS - Martin Luther King Jr. High Facility | PLUMBING | Miscellaneous | Region 5 | 17/06/2019 | |
| 96268 HS - Martin Luther King Jr. High Facility | ELECTRICAL | Miscellaneous | Region 5 | 19/06/2019 | |
| 96326 HS - Martin Luther King Jr. High Facility | ELECTRICAL | Lights Out | Region 5 | 20/06/2019 | |
| 96328 HS - Martin Luther King Jr. High Facility | GLAZING | Miscellaneous | Region 5 | 20/06/2019 | |
| 96330 HS - Martin Luther King Jr. High Facility | ADMINSTRATIVE | Miscellaneous | Region 5 | 20/06/2019 | |
| 96333 HS - Martin Luther King Jr. High Facility | HVAC | Miscellaneous | Region 5 | 20/06/2019 | |
| 96641 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 25/06/2019 | |
| 96643 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 25/06/2019 | 7/5/2019 |
| 96703 HS - Martin Luther King Jr. High Facility | HOUSEKEEPING | | Region 5 | 26/06/2019 | 7/1/2019 |
| 96777 HS - Martin Luther King Jr. High Facility | HVAC | | Region 5 | 27/06/2019 | 7/2/2019 |
| 98247 HS - Martin Luther King Jr. High Facility | HVAC | | Region 5 | 8/7/2019 | |
| 98336 HS - Martin Luther King Jr. High Facility | LOCKSMITH | Miscellaneous | Region 5 | 9/7/2019 | |
| 98390 HS - Martin Luther King Jr. High Facility | CARPENTRY | | Region 5 | 10/7/2019 | |
| 98419 HS - Martin Luther King Jr. High Facility | PAINTING / PRESSURE WASHING | | Region 5 | 10/7/2019 | |
| 98443 HS - Martin Luther King Jr. High Facility | ELECTRICAL | Miscellaneous | Region 5 | 10/7/2019 | |
| 98444 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 10/7/2019 | |
| 98717 HS - Martin Luther King Jr. High Facility | PAINTING / PRESSURE WASHING | Discoloration | Region 5 | 15/07/2019 | |
| 98746 HS - Martin Luther King Jr. High Facility | ELECTRICAL | Miscellaneous | Region 5 | 15/07/2019 | |
| 98767 HS - Martin Luther King Jr. High Facility | CARPENTRY | Miscellaneous | Region 5 | 15/07/2019 | |
| 98782 HS - Martin Luther King Jr. High Facility | GROUNDS | Grass | Region 5 | 16/07/2019 | |
| 34536 HS - Miller Grove High Facility | FIRE SAFETY | | Region 5 | 7/11/2017 | |
| 35315 HS - Miller Grove High Facility | ELECTRONICS | | Region 5 | 15/11/2017 | |
| 40716 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 5/1/2018 | |
| 43797 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 7/2/2018 | |
| 43841 HS - Miller Grove High Facility | ROOF | | Region 5 | 7/2/2018 | |
| 44073 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 9/2/2018 | |
| 55120 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 22/05/2018 | |
| 57147 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 8/6/2018 | 6/9/2018 |
| 57149 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 8/6/2018 | 6/9/2018 |
| 63776 HS - Miller Grove High Facility | CARPENTRY | Miscellaneous | Region 5 | 13/08/2018 | |
| 64019 HS - Miller Grove High Facility | PLUMBING | Water Leak | Region 5 | 14/08/2018 | |
| 64627 HS - Miller Grove High Facility | ROOF | Water Leak | Region 5 | 21/08/2018 | |
| 75594 HS - Miller Grove High Facility | CARPENTRY | Structure | Region 5 | 20/11/2018 | |
| 75736 HS - Miller Grove High Facility | ELECTRICAL | Structure | Region 5 | 26/11/2018 | |
| 77213 HS - Miller Grove High Facility | ROOF | Water Leak | Region 5 | 10/12/2018 | |
| 77948 HS - Miller Grove High Facility | PAINTING / PRESSURE WASHING | | Region 5 | 20/12/2018 | |
| 79372 HS - Miller Grove High Facility | GLAZING | Broken Window | Region 5 | 8/1/2019 | |
| 79688 HS - Miller Grove High Facility | FIRE SAFETY | Miscellaneous | Region 5 | 11/1/2019 | |
| 80366 HS - Miller Grove High Facility | GLAZING | Broken Window | Region 5 | 18/01/2019 | |
| | | | | | |

| | 80554 HS - Miller Grove High Facility | CARPENTRY | Floors | Region 5 | 22/01/2019 | |
|------|---|----------------------|----------------------|----------|------------|----------|
| | 83281 HS - Miller Grove High Facility | ROOF | Water Leak | Region 5 | 21/02/2019 | |
| | 83283 HS - Miller Grove High Facility | ROOF | Water Leak | Region 5 | 21/02/2019 | |
| | 83680 HS - Miller Grove High Facility | CARPENTRY | Broken Equipment | Region 5 | 26/02/2019 | |
| | 83831 HS - Miller Grove High Facility | ELECTRICAL | Lights Out | Region 5 | 28/02/2019 | 3/1/2019 |
| | 88524 HS - Miller Grove High Facility | HVAC | Broken Equipment | Region 5 | 8/4/2019 | |
| | 88828 HS - Miller Grove High Facility | MECHANICAL EQUIPMENT | Broken Equipment | Region 5 | 10/4/2019 | |
| | 89782 HS - Miller Grove High Facility | ROOF | Water Leak | Region 5 | 19/04/2019 | |
| | 90663 HS - Miller Grove High Facility | HVAC | Room Too Hot | Region 5 | 29/04/2019 | 5/4/2019 |
| | 90787 HS - Miller Grove High Facility | GROUNDS | Water Leak | Region 5 | 30/04/2019 | |
| | 90789 HS - Miller Grove High Facility | ELECTRONICS | Broken Equipment | Region 5 | 30/04/2019 | 5/5/2019 |
| | 92455 HS - Miller Grove High Facility | HVAC | | Region 5 | 9/5/2019 | |
| | 93457 HS - Miller Grove High Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 23/05/2019 | |
| | 95251 HS - Miller Grove High Facility | CARPENTRY | Broken Window | Region 5 | 4/6/2019 | 6/9/2019 |
| | 95852 HS - Miller Grove High Facility | CARPENTRY | Broken Equipment | Region 5 | 13/06/2019 | |
| | 96107 HS - Miller Grove High Facility | MASON/CONCRETE | Structure | Region 5 | 18/06/2019 | |
| | 98048 HS - Miller Grove High Facility | CARPENTRY | Structure | Region 5 | 3/7/2019 | |
| | 98232 HS - Miller Grove High Facility | HVAC | Water Leak | Region 5 | 8/7/2019 | |
| | 98468 HS - Miller Grove High Facility | PLUMBING | Water Leak | Region 5 | 10/7/2019 | |
| M-57 | 7766 HS - Miller Grove High Facility | CARPENTRY | | Region 5 | 19/06/2018 | |
| | 32047 HS - Southwest Dekalb High Facility | GLAZING | | Region 5 | 20/10/2017 | |
| | 32048 HS - Southwest Dekalb High Facility | GLAZING | | Region 5 | 20/10/2017 | |
| | 44038 HS - Southwest Dekalb High Facility | ROOF | | Region 5 | 8/2/2018 | |
| | 53578 HS - Southwest Dekalb High Facility | GLAZING | | Region 5 | 2/5/2018 | 5/3/2018 |
| | 56917 HS - Southwest Dekalb High Facility | HVAC | | Region 5 | 5/6/2018 | |
| | 56922 HS - Southwest Dekalb High Facility | CARPENTRY | | Region 5 | 5/6/2018 | |
| | 56935 HS - Southwest Dekalb High Facility | CARPENTRY | | Region 5 | 5/6/2018 | |
| | 56939 HS - Southwest Dekalb High Facility | HVAC | | Region 5 | 5/6/2018 | |
| | 64911 HS - Southwest Dekalb High Facility | CARPENTRY | Miscellaneous | Region 5 | 22/08/2018 | |
| | 68919 HS - Southwest Dekalb High Facility | CARPENTRY | Miscellaneous | Region 5 | 18/09/2018 | |
| | 72311 HS - Southwest Dekalb High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 19/10/2018 | |
| | 72438 HS - Southwest Dekalb High Facility | HVAC | Miscellaneous | Region 5 | 22/10/2018 | |
| | 77161 HS - Southwest Dekalb High Facility | ROOF | Ceilings | Region 5 | 10/12/2018 | |
| | 77602 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 14/12/2018 | |
| | 80062 HS - Southwest Dekalb High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 16/01/2019 | |
| | 83466 HS - Southwest Dekalb High Facility | HVAC | Gas Smell | Region 5 | 22/02/2019 | |
| | 83859 HS - Southwest Dekalb High Facility | HVAC | | Region 5 | 28/02/2019 | |
| | 84926 HS - Southwest Dekalb High Facility | HVAC | Miscellaneous | Region 5 | 5/3/2019 | |
| | 87326 HS - Southwest Dekalb High Facility | PEST CONTROL | Paint | Region 5 | 29/03/2019 | |
| | 88774 HS - Southwest Dekalb High Facility | GLAZING | Miscellaneous | Region 5 | 9/4/2019 | |
| | 5 , | | | - | • • | |

| 89019 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 11/4/2019 | |
|---|-------------------|------------------|----------|------------|----------|
| 89390 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 15/04/2019 | |
| 89768 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 19/04/2019 | |
| 89802 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 19/04/2019 | |
| 89803 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 19/04/2019 | |
| 92191 HS - Southwest Dekalb High Facility | PLUMBING | | Region 5 | 6/5/2019 | 5/7/2019 |
| 93283 HS - Southwest Dekalb High Facility | GLAZING | Miscellaneous | Region 5 | 21/05/2019 | |
| 93284 HS - Southwest Dekalb High Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 21/05/2019 | |
| 93285 HS - Southwest Dekalb High Facility | PLUMBING | | Region 5 | 21/05/2019 | |
| 93406 HS - Southwest Dekalb High Facility | HVAC | Room Too Hot | Region 5 | 22/05/2019 | |
| 93809 HS - Southwest Dekalb High Facility | ELECTRONICS | | Region 5 | 29/05/2019 | 6/3/2019 |
| 95429 HS - Southwest Dekalb High Facility | ROOF | Roof Leak | Region 5 | 8/6/2019 | |
| 95698 HS - Southwest Dekalb High Facility | GROUNDS | Grass | Region 5 | 11/6/2019 | |
| 96072 HS - Southwest Dekalb High Facility | HVAC | | Region 5 | 18/06/2019 | |
| 96167 HS - Southwest Dekalb High Facility | FIRE SAFETY | | Region 5 | 19/06/2019 | |
| 98251 HS - Southwest Dekalb High Facility | CARPENTRY | Miscellaneous | Region 5 | 8/7/2019 | 8/2/2019 |
| 98471 HS - Southwest Dekalb High Facility | CARPENTRY | Floors | Region 5 | 10/7/2019 | |
| 98480 HS - Southwest Dekalb High Facility | HVAC | | Region 5 | 11/7/2019 | |
| 98709 HS - Southwest Dekalb High Facility | PEST CONTROL | Pest | Region 5 | 15/07/2019 | |
| 98710 HS - Southwest Dekalb High Facility | PEST CONTROL | Pest | Region 5 | 15/07/2019 | |
| 44546 MS - Chapel Hill Middle Facility | GLAZING | | Region 5 | 15/02/2018 | |
| 45210 MS - Chapel Hill Middle Facility | CARPENTRY | | Region 5 | 23/02/2018 | |
| 53684 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 5 | 3/5/2018 | |
| 55061 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | | Region 5 | 22/05/2018 | |
| 55078 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | | Region 5 | 22/05/2018 | |
| 63743 MS - Chapel Hill Middle Facility | ROOF | Roof Leak | Region 5 | 13/08/2018 | |
| 68454 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 12/9/2018 | |
| 71906 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 5 | 16/10/2018 | |
| 71912 MS - Chapel Hill Middle Facility | ROOF | Ceilings | Region 5 | 16/10/2018 | |
| 72423 MS - Chapel Hill Middle Facility | ROOF | | Region 5 | 22/10/2018 | |
| 75082 MS - Chapel Hill Middle Facility | ROOF | Roof Leak | Region 5 | 12/11/2018 | |
| 75909 MS - Chapel Hill Middle Facility | ROOF | Roof Leak | Region 5 | 27/11/2018 | |
| 76141 MS - Chapel Hill Middle Facility | CARPENTRY | Structure | Region 5 | 29/11/2018 | |
| 77888 MS - Chapel Hill Middle Facility | ROOF | Roof Leak | Region 5 | 20/12/2018 | |
| 79026 MS - Chapel Hill Middle Facility | ROOF | Ceilings | Region 5 | 4/1/2019 | |
| 79653 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 11/1/2019 | |
| 80290 MS - Chapel Hill Middle Facility | GLAZING | Broken Window | Region 5 | 18/01/2019 | |
| 82174 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 4/2/2019 | 2/5/2019 |
| 82533 MS - Chapel Hill Middle Facility | GLAZING | Broken Window | Region 5 | 7/2/2019 | 2/8/2019 |
| 82566 MS - Chapel Hill Middle Facility | ROOF | Roof Leak | Region 5 | 8/2/2019 | |
| • | | | - | | |

| 82572 MS - Chapel Hill Middle Facility | CARPENTRY | Move Items | Region 5 | 8/2/2019 | |
|---|-----------------------------|------------------|----------|------------|-----------|
| 83136 MS - Chapel Hill Middle Facility | CARPENTRY | Move Items | Region 5 | 20/02/2019 | |
| 86070 MS - Chapel Hill Middle Facility | HVAC | | Region 5 | 19/03/2019 | |
| 86292 MS - Chapel Hill Middle Facility | CARPENTRY | Miscellaneous | Region 5 | 21/03/2019 | |
| 88392 MS - Chapel Hill Middle Facility | CARPENTRY | Move Items | Region 5 | 2/4/2019 | 4/3/2019 |
| 89296 MS - Chapel Hill Middle Facility | CARPENTRY | Doors | Region 5 | 15/04/2019 | |
| 90709 MS - Chapel Hill Middle Facility | HVAC | | Region 5 | 30/04/2019 | 5/5/2019 |
| 90727 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 30/04/2019 | 5/5/2019 |
| 92149 MS - Chapel Hill Middle Facility | HVAC | Water Leak | Region 5 | 6/5/2019 | 5/11/2019 |
| 92412 MS - Chapel Hill Middle Facility | HVAC | | Region 5 | 9/5/2019 | |
| 92413 MS - Chapel Hill Middle Facility | HVAC | | Region 5 | 9/5/2019 | |
| 92415 MS - Chapel Hill Middle Facility | HVAC | | Region 5 | 9/5/2019 | |
| 92909 MS - Chapel Hill Middle Facility | KITCHEN EQUIPMENT | Steamer / Warmer | Region 5 | 16/05/2019 | |
| 92970 MS - Chapel Hill Middle Facility | HVAC | Room Too Hot | Region 5 | 17/05/2019 | |
| 93574 MS - Chapel Hill Middle Facility | ELECTRICAL | Freezer / Cooler | Region 5 | 24/05/2019 | |
| 93824 MS - Chapel Hill Middle Facility | HVAC | Room Too Hot | Region 5 | 29/05/2019 | 6/3/2019 |
| 96014 MS - Chapel Hill Middle Facility | ELECTRICAL | Broken Equipment | Region 5 | 17/06/2019 | |
| 96764 MS - Chapel Hill Middle Facility | GROUNDS | Grass | Region 5 | 27/06/2019 | 7/2/2019 |
| 96780 MS - Chapel Hill Middle Facility | DELIVERY | Deliver Material | Region 5 | 27/06/2019 | 7/12/2019 |
| 97995 MS - Chapel Hill Middle Facility | ELECTRONICS | Intercom | Region 5 | 3/7/2019 | 7/8/2019 |
| 98002 MS - Chapel Hill Middle Facility | LOCKSMITH | Locks / Keys | Region 5 | 3/7/2019 | 7/8/2019 |
| 98187 MS - Chapel Hill Middle Facility | ELECTRICAL | | Region 5 | 8/7/2019 | 7/9/2019 |
| 69026 MS - Miller Grove Middle Facility | CARPENTRY | Doors | Region 5 | 19/09/2018 | |
| 85767 MS - Miller Grove Middle Facility | GROUNDS | Trees | Region 5 | 14/03/2019 | |
| 87277 MS - Miller Grove Middle Facility | CARPENTRY | Decking | Region 5 | 28/03/2019 | |
| 89311 MS - Miller Grove Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 15/04/2019 | |
| 89574 MS - Miller Grove Middle Facility | CARPENTRY | Miscellaneous | Region 5 | 17/04/2019 | |
| 89666 MS - Miller Grove Middle Facility | GROUNDS | Miscellaneous | Region 5 | 18/04/2019 | |
| 93180 MS - Miller Grove Middle Facility | ELECTRICAL | Miscellaneous | Region 5 | 20/05/2019 | |
| 93941 MS - Miller Grove Middle Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 5 | 30/05/2019 | 6/4/2019 |
| 93942 MS - Miller Grove Middle Facility | CARPENTRY | Miscellaneous | Region 5 | 30/05/2019 | 6/4/2019 |
| 97922 MS - Miller Grove Middle Facility | GROUNDS | | Region 5 | 2/7/2019 | 7/7/2019 |
| 97931 MS - Miller Grove Middle Facility | CARPENTRY | Doors | Region 5 | 2/7/2019 | |
| 97934 MS - Miller Grove Middle Facility | CARPENTRY | Doors | Region 5 | 2/7/2019 | |
| 97936 MS - Miller Grove Middle Facility | ELECTRICAL | Miscellaneous | Region 5 | 2/7/2019 | 7/7/2019 |
| 98198 MS - Miller Grove Middle Facility | GROUNDS | Trees | Region 5 | 8/7/2019 | |
| 98519 MS - Miller Grove Middle Facility | PAINTING / PRESSURE WASHING | Graffiti | Region 5 | 11/7/2019 | |
| 41703 MS - Salem MIddle Facility | ROOF | | Region 5 | 22/01/2018 | |
| 41704 MS - Salem MIddle Facility | ROOF | | Region 5 | 22/01/2018 | |
| 41705 MS - Salem MIddle Facility | ROOF | | Region 5 | 22/01/2018 | |
| | | | | | |

| 41710 MS - Salem MIddle Facility | ROOF | | Region 5 | 22/01/2018 | |
|---|-----------------------------|------------------|----------|------------|------------|
| 41712 MS - Salem MIddle Facility | ROOF | | Region 5 | 22/01/2018 | |
| 41716 MS - Salem MIddle Facility | ROOF | | Region 5 | 22/01/2018 | |
| 42380 MS - Salem MIddle Facility | ROOF | | Region 5 | 29/01/2018 | |
| 43904 MS - Salem MIddle Facility | ROOF | | Region 5 | 7/2/2018 | |
| 55792 MS - Salem MIddle Facility | CARPENTRY | | Region 5 | 31/05/2018 | |
| 59859 MS - Salem MIddle Facility | ROOF | Roof Leak | Region 5 | 17/07/2018 | |
| 59861 MS - Salem MIddle Facility | ROOF | Roof Leak | Region 5 | 17/07/2018 | |
| 59866 MS - Salem MIddle Facility | ROOF | Roof Leak | Region 5 | 17/07/2018 | |
| 74977 MS - Salem MIddle Facility | FIRE SAFETY | Extinguisher | Region 5 | 12/11/2018 | |
| 77078 MS - Salem MIddle Facility | HVAC | Broken Equipment | Region 5 | 10/12/2018 | 12/11/2018 |
| 77080 MS - Salem MIddle Facility | HVAC | Broken Equipment | Region 5 | 10/12/2018 | 12/11/2018 |
| 77700 MS - Salem MIddle Facility | ROOF | Water Leak | Region 5 | 17/12/2018 | |
| 77707 MS - Salem MIddle Facility | ROOF | Water Leak | Region 5 | 17/12/2018 | |
| 77708 MS - Salem MIddle Facility | ROOF | Water Leak | Region 5 | 17/12/2018 | |
| 77724 MS - Salem MIddle Facility | ROOF | Roof Leak | Region 5 | 18/12/2018 | |
| 77733 MS - Salem MIddle Facility | ROOF | Roof Leak | Region 5 | 18/12/2018 | |
| 77979 MS - Salem MIddle Facility | ROOF | Roof Leak | Region 5 | 21/12/2018 | |
| 83734 MS - Salem MIddle Facility | ELECTRICAL | Lights Out | Region 5 | 27/02/2019 | |
| 85791 MS - Salem Middle Facility | CARPENTRY | Doors | Region 5 | 14/03/2019 | |
| 86948 MS - Salem MIddle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 5 | 25/03/2019 | |
| 89461 MS - Salem MIddle Facility | ELECTRICAL | Lights Out | Region 5 | 16/04/2019 | |
| 89808 MS - Salem MIddle Facility | CARPENTRY | Broken Equipment | Region 5 | 19/04/2019 | |
| 90160 MS - Salem MIddle Facility | HVAC | Water Leak | Region 5 | 23/04/2019 | |
| 90161 MS - Salem MIddle Facility | HVAC | Water Leak | Region 5 | 23/04/2019 | |
| 93900 MS - Salem MIddle Facility | ELECTRICAL | Lights Out | Region 5 | 30/05/2019 | |
| 95268 MS - Salem MIddle Facility | CARPENTRY | Supplies Needed | Region 5 | 4/6/2019 | 6/9/2019 |
| 95269 MS - Salem MIddle Facility | EQUIPMENT REPAIR | Supplies Needed | Region 5 | 4/6/2019 | 6/9/2019 |
| 96116 MS - Salem MIddle Facility | CARPENTRY | Ceilings | Region 5 | 18/06/2019 | |
| 96198 MS - Salem MIddle Facility | ELECTRICAL | | Region 5 | 19/06/2019 | |
| 96281 MS - Salem MIddle Facility | DELIVERY | Ceilings | Region 5 | 19/06/2019 | |
| 98387 MS - Salem MIddle Facility | GROUNDS | Supplies Needed | Region 5 | 9/7/2019 | |
| 98394 MS - Salem MIddle Facility | ELECTRICAL | | Region 5 | 10/7/2019 | |
| 98679 MS - Salem MIddle Facility | PLUMBING | Water Leak | Region 5 | 15/07/2019 | |
| 98697 MS - Salem MIddle Facility | PLUMBING | Water Leak | Region 5 | 15/07/2019 | |
| 76504 AS - East Camous 2 Transportation | ROOF | Roof Leak | Region 6 | 3/12/2018 | 12/4/2018 |
| 80839 AS - East Camous 2 Transportation | ROOF | Roof Leak | Region 6 | 24/01/2019 | |
| 96554 AS - East Camous 2 Transportation | CARPENTRY | | Region 6 | 24/06/2019 | |
| 59602 EO - East Campus 1 DeKalb Alt | PAINTING / PRESSURE WASHING | | Region 6 | 13/07/2018 | |
| 69050 EO - East Campus 1 DeKalb Alt | ROOF | Roof Leak | Region 6 | 19/09/2018 | |
| | | | | | |

| 82526 EO - East Campus 1 DeKalb Alt | ROOF | Roof Leak | Region 6 | 7/2/2019 | 2/8/2019 |
|---|-----------------------------|---------------------------|----------|------------|-----------|
| 85852 EO - East Campus 1 DeKalb Alt | PLUMBING | Roof Leak | Region 6 | 15/03/2019 | |
| 86277 EO - East Campus 1 DeKalb Alt | ROOF | | Region 6 | 20/03/2019 | |
| 86915 EO - East Campus 1 DeKalb Alt | HVAC | | Region 6 | 25/03/2019 | |
| 89765 EO - East Campus 1 DeKalb Alt | ROOF | Roof Leak | Region 6 | 19/04/2019 | |
| 90687 EO - East Campus 1 DeKalb Alt | HVAC | | Region 6 | 29/04/2019 | 5/4/2019 |
| 98055 EO - East Campus 1 DeKalb Alt | PLUMBING | Broken Equipment | Region 6 | 5/7/2019 | 7/12/2019 |
| 98185 EO - East Campus 1 DeKalb Alt | HVAC | Room Too Hot | Region 6 | 8/7/2019 | |
| 98327 EO - East Campus 1 DeKalb Alt | PEST CONTROL | | Region 6 | 9/7/2019 | 7/9/2019 |
| 98793 EO - East Campus 1 DeKalb Alt | | Doors | Region 6 | 16/07/2019 | |
| 68573 ES - Canby Lane Elementary Facility | GLAZING | Broken Window | Region 6 | 13/09/2018 | |
| 86902 ES - Canby Lane Elementary Facility | HVAC | | Region 6 | 25/03/2019 | |
| 87209 ES - Canby Lane Elementary Facility | ROOF | Roof Leak | Region 6 | 27/03/2019 | |
| 94055 ES - Canby Lane Elementary Facility | CARPENTRY | Floors | Region 6 | 31/05/2019 | 6/5/2019 |
| 95733 ES - Canby Lane Elementary Facility | PLUMBING | Faucet Dripping | Region 6 | 11/6/2019 | |
| 96136 ES - Canby Lane Elementary Facility | LOCKSMITH | Locks / Keys | Region 6 | 18/06/2019 | |
| 96137 ES - Canby Lane Elementary Facility | PLUMBING | Standing Water | Region 6 | 18/06/2019 | |
| 85779 ES - Columbia Elementary Facility | HOUSEKEEPING | Broken Equipment | Region 6 | 14/03/2019 | |
| 86903 ES - Columbia Elementary Facility | HVAC | | Region 6 | 25/03/2019 | |
| 88791 ES - Columbia Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 9/4/2019 | |
| 89773 ES - Columbia Elementary Facility | ROOF | Roof Leak | Region 6 | 19/04/2019 | |
| 90118 ES - Columbia Elementary Facility | LOCKSMITH | Doors | Region 6 | 23/04/2019 | |
| 92258 ES - Columbia Elementary Facility | PLUMBING | Toilet Overflowing | Region 6 | 7/5/2019 | 5/12/2019 |
| 92528 ES - Columbia Elementary Facility | CARPENTRY | Doors | Region 6 | 10/5/2019 | |
| 92688 ES - Columbia Elementary Facility | FIRE SAFETY | Extinguisher | Region 6 | 13/05/2019 | |
| 95833 ES - Columbia Elementary Facility | HVAC | Room Too Hot | Region 6 | 13/06/2019 | |
| 96469 ES - Columbia Elementary Facility | HVAC | | Region 6 | 24/06/2019 | |
| 98038 ES - Columbia Elementary Facility | HVAC | | Region 6 | 3/7/2019 | 7/8/2019 |
| 98354 ES - Columbia Elementary Facility | HVAC | | Region 6 | 9/7/2019 | |
| 98355 ES - Columbia Elementary Facility | CARPENTRY | | Region 6 | 9/7/2019 | |
| 98391 ES - Columbia Elementary Facility | HVAC | | Region 6 | 10/7/2019 | |
| 98530 ES - Columbia Elementary Facility | PLUMBING | Water Leak | Region 6 | 11/7/2019 | |
| 98531 ES - Columbia Elementary Facility | CARPENTRY | Doors | Region 6 | 11/7/2019 | |
| 98692 ES - Columbia Elementary Facility | PAINTING / PRESSURE WASHING | | Region 6 | 15/07/2019 | |
| 48988 ES - Peachcrest Elementary Facility | GLAZING | | Region 6 | 21/03/2018 | |
| 59834 ES - Peachcrest Elementary Facility | ELECTRONICS | | Region 6 | 17/07/2018 | |
| 62637 ES - Peachcrest Elementary Facility | ROOF | Roof Leak | Region 6 | 6/8/2018 | |
| 62805 ES - Peachcrest Elementary Facility | ROOF | Roof Leak | Region 6 | 6/8/2018 | 8/7/2018 |
| 63922 ES - Peachcrest Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 6 | 14/08/2018 | |
| 78976 ES - Peachcrest Elementary Facility | GLAZING | Miscellaneous | Region 6 | 3/1/2019 | |
| | | | | | |

| 86905 ES - Peachcrest Elementary Facility | HVAC | | Region 6 | 25/03/2019 | |
|---|-------------------|-------------------|----------|------------|-----------|
| 89578 ES - Peachcrest Elementary Facility | PLUMBING | Miscellaneous | Region 6 | 17/04/2019 | |
| 91854 ES - Peachcrest Elementary Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 6 | 2/5/2019 | 5/7/2019 |
| 93801 ES - Peachcrest Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 28/05/2019 | 6/2/2019 |
| 95258 ES - Peachcrest Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 4/6/2019 | |
| 95984 ES - Peachcrest Elementary Facility | HVAC | Room Too Hot | Region 6 | 17/06/2019 | |
| 96239 ES - Peachcrest Elementary Facility | ELECTRONICS | Clocks | Region 6 | 19/06/2019 | |
| 98667 ES - Peachcrest Elementary Facility | FIRE SAFETY | | Region 6 | 15/07/2019 | |
| 62524 ES - Rowland Elementary Facility | ROOF | | Region 6 | 3/8/2018 | |
| 62542 ES - Rowland Elementary Facility | ROOF | | Region 6 | 3/8/2018 | |
| 71536 ES - Rowland Elementary Facility | ROOF | Ceilings | Region 6 | 11/10/2018 | |
| 74967 ES - Rowland Elementary Facility | ROOF | Roof Leak | Region 6 | 12/11/2018 | |
| 75168 ES - Rowland Elementary Facility | ROOF | Roof Leak | Region 6 | 13/11/2018 | |
| 79142 ES - Rowland Elementary Facility | ROOF | Ceilings | Region 6 | 7/1/2019 | |
| 84934 ES - Rowland Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 6 | 5/3/2019 | |
| 84936 ES - Rowland Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 6 | 5/3/2019 | |
| 86279 ES - Rowland Elementary Facility | CARPENTRY | Structure | Region 6 | 20/03/2019 | |
| 89719 ES - Rowland Elementary Facility | ROOF | Water Leak | Region 6 | 19/04/2019 | |
| 89974 ES - Rowland Elementary Facility | PLUMBING | Water Leak | Region 6 | 22/04/2019 | |
| 93531 ES - Rowland Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 6 | 24/05/2019 | |
| 93540 ES - Rowland Elementary Facility | CARPENTRY | Structure | Region 6 | 24/05/2019 | |
| 93541 ES - Rowland Elementary Facility | CARPENTRY | Structure | Region 6 | 24/05/2019 | |
| 96093 ES - Rowland Elementary Facility | CARPENTRY | Floors | Region 6 | 18/06/2019 | 7/12/2019 |
| 96206 ES - Rowland Elementary Facility | CARPENTRY | Floors | Region 6 | 19/06/2019 | 7/12/2019 |
| 96354 ES - Rowland Elementary Facility | PLUMBING | | Region 6 | 20/06/2019 | |
| 97975 ES - Rowland Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 2/7/2019 | 7/9/2019 |
| 98465 ES - Rowland Elementary Facility | HVAC | | Region 6 | 10/7/2019 | |
| 98712 ES - Rowland Elementary Facility | HVAC | Room Too Hot | Region 6 | 15/07/2019 | |
| 64036 ES - Snapfinger Elementary Facility | HOUSEKEEPING | Miscellaneous | Region 6 | 15/08/2018 | |
| 74236 ES - Snapfinger Elementary Facility | ELECTRICAL | | Region 6 | 1/11/2018 | 11/1/2018 |
| 74557 ES - Snapfinger Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 6 | 6/11/2018 | 11/7/2018 |
| 80832 ES - Snapfinger Elementary Facility | CARPENTRY | Freezer / Cooler | Region 6 | 24/01/2019 | |
| 82066 ES - Snapfinger Elementary Facility | WAREHOUSE | Deliver Material | Region 6 | 1/2/2019 | |
| 83277 ES - Snapfinger Elementary Facility | ROOF | Roof Leak | Region 6 | 21/02/2019 | |
| 83635 ES - Snapfinger Elementary Facility | EQUIPMENT REPAIR | Miscellaneous | Region 6 | 26/02/2019 | |
| 85853 ES - Snapfinger Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 15/03/2019 | |
| 88416 ES - Snapfinger Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 3/4/2019 | |
| 88684 ES - Snapfinger Elementary Facility | HAZARDOUS | | Region 6 | 9/4/2019 | |
| 88745 ES - Snapfinger Elementary Facility | PLUMBING | Broken Equipment | Region 6 | 9/4/2019 | |
| 88799 ES - Snapfinger Elementary Facility | GROUNDS | | Region 6 | 9/4/2019 | |
| | | | | | |

| 90061 ES - Snapfinger Elementary Facility | ENERGY MANAGEMENT | | Region 6 | 22/04/2019 | |
|---|-----------------------------|---------------------------|----------|------------|-----------|
| 93499 ES - Snapfinger Elementary Facility | CARPENTRY | Floors | Region 6 | 23/05/2019 | |
| 93567 ES - Snapfinger Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 24/05/2019 | |
| 95227 ES - Snapfinger Elementary Facility | PLUMBING | Toilet Overflowing | Region 6 | 4/6/2019 | 6/9/2019 |
| 95234 ES - Snapfinger Elementary Facility | CARPENTRY | Doors | Region 6 | 4/6/2019 | |
| 96081 ES - Snapfinger Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 6 | 18/06/2019 | |
| 96673 ES - Snapfinger Elementary Facility | EQUIPMENT REPAIR | Broken Equipment | Region 6 | 26/06/2019 | 7/12/2019 |
| 96698 ES - Snapfinger Elementary Facility | CARPENTRY | Ceilings | Region 6 | 26/06/2019 | 7/1/2019 |
| 98215 ES - Snapfinger Elementary Facility | PLUMBING | | Region 6 | 8/7/2019 | |
| 98297 ES - Snapfinger Elementary Facility | PLUMBING | Miscellaneous | Region 6 | 9/7/2019 | |
| 98347 ES - Snapfinger Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 9/7/2019 | |
| 98359 ES - Snapfinger Elementary Facility | GROUNDS | | Region 6 | 9/7/2019 | |
| 98384 ES - Snapfinger Elementary Facility | ELECTRICAL | | Region 6 | 9/7/2019 | |
| 98398 ES - Snapfinger Elementary Facility | ELECTRICAL | | Region 6 | 10/7/2019 | |
| 98687 ES - Snapfinger Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 15/07/2019 | |
| 98699 ES - Snapfinger Elementary Facility | ELECTRICAL | Lights Out | Region 6 | 15/07/2019 | |
| 98700 ES - Snapfinger Elementary Facility | CARPENTRY | Miscellaneous | Region 6 | 15/07/2019 | |
| 86907 ES - Toney Elementary Facility | HVAC | | Region 6 | 25/03/2019 | |
| 88389 ES - Toney Elementary Facility | HAZARDOUS | | Region 6 | 2/4/2019 | 4/2/2019 |
| 89160 ES - Toney Elementary Facility | CARPENTRY | Decking | Region 6 | 12/4/2019 | |
| 89344 ES - Toney Elementary Facility | ROOF | Roof Leak | Region 6 | 15/04/2019 | |
| 90288 ES - Toney Elementary Facility | WAREHOUSE | Supplies Needed | Region 6 | 25/04/2019 | |
| 92812 ES - Toney Elementary Facility | HVAC | Water Leak | Region 6 | 14/05/2019 | |
| 93027 ES - Toney Elementary Facility | PLUMBING | Water Leak | Region 6 | 19/05/2019 | |
| 93390 ES - Toney Elementary Facility | PLUMBING | Broken Equipment | Region 6 | 22/05/2019 | |
| 93393 ES - Toney Elementary Facility | GLAZING | Broken Equipment | Region 6 | 22/05/2019 | |
| 93842 ES - Toney Elementary Facility | GLAZING | Broken Window | Region 6 | 29/05/2019 | 6/3/2019 |
| 93843 ES - Toney Elementary Facility | GLAZING | Broken Window | Region 6 | 29/05/2019 | 6/3/2019 |
| 93845 ES - Toney Elementary Facility | GLAZING | Broken Window | Region 6 | 29/05/2019 | 6/3/2019 |
| 95355 ES - Toney Elementary Facility | ELECTRICAL | Lights Out | Region 6 | 5/6/2019 | 6/10/2019 |
| 95741 ES - Toney Elementary Facility | CARPENTRY | Floors | Region 6 | 11/6/2019 | 7/12/2019 |
| 95830 ES - Toney Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 13/06/2019 | |
| 95846 ES - Toney Elementary Facility | ROOF | Standing Water | Region 6 | 13/06/2019 | |
| 96581 ES - Toney Elementary Facility | HVAC | Water Leak | Region 6 | 25/06/2019 | |
| 96599 ES - Toney Elementary Facility | MASON/CONCRETE | Structure | Region 6 | 25/06/2019 | 7/12/2019 |
| 98039 ES - Toney Elementary Facility | CARPENTRY | Broken Equipment | Region 6 | 3/7/2019 | 7/8/2019 |
| 98201 ES - Toney Elementary Facility | HVAC | Water Leak | Region 6 | 8/7/2019 | |
| 98662 ES - Toney Elementary Facility | PAINTING / PRESSURE WASHING | | Region 6 | 15/07/2019 | |
| 98751 ES - Toney Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 6 | 15/07/2019 | |
| 42342 ES - Wadsworth Magnet Facility | ROOF | | Region 6 | 29/01/2018 | |
| | | | | | |

| 80020 ES - Wadsworth Magnet Facility | GLAZING | Broken Window | Region 6 | 16/01/2019 | |
|--------------------------------------|-----------------------------|------------------|----------|------------|-----------|
| 82574 ES - Wadsworth Magnet Facility | HVAC | Roof Leak | Region 6 | 8/2/2019 | |
| 82784 ES - Wadsworth Magnet Facility | GLAZING | Broken Window | Region 6 | 12/2/2019 | |
| 85240 ES - Wadsworth Magnet Facility | PAINTING / PRESSURE WASHING | Paint | Region 6 | 7/3/2019 | |
| 86026 ES - Wadsworth Magnet Facility | PLUMBING | | Region 6 | 19/03/2019 | |
| 89133 ES - Wadsworth Magnet Facility | CARPENTRY | Structure | Region 6 | 12/4/2019 | |
| 89766 ES - Wadsworth Magnet Facility | ROOF | Roof Leak | Region 6 | 19/04/2019 | |
| 92697 ES - Wadsworth Magnet Facility | ROOF | Roof Leak | Region 6 | 13/05/2019 | |
| 92983 ES - Wadsworth Magnet Facility | HVAC | Room Too Hot | Region 6 | 17/05/2019 | |
| 93181 ES - Wadsworth Magnet Facility | HVAC | Room Too Hot | Region 6 | 20/05/2019 | |
| 93957 ES - Wadsworth Magnet Facility | ROOF | Paint | Region 6 | 30/05/2019 | 6/4/2019 |
| 96338 ES - Wadsworth Magnet Facility | HVAC | Room Too Hot | Region 6 | 20/06/2019 | |
| 96751 ES - Wadsworth Magnet Facility | PLUMBING | Miscellaneous | Region 6 | 27/06/2019 | 7/2/2019 |
| 98483 ES - Wadsworth Magnet Facility | PLUMBING | | Region 6 | 11/7/2019 | |
| 98749 ES - Wadsworth Magnet Facility | CARPENTRY | Doors | Region 6 | 15/07/2019 | |
| 98750 ES - Wadsworth Magnet Facility | CARPENTRY | Decking | Region 6 | 15/07/2019 | |
| 32046 HS - Columbia High Facility | ROOF | - | Region 6 | 20/10/2017 | 11/3/2017 |
| 76527 HS - Columbia High Facility | EQUIPMENT REPAIR | Broken Equipment | Region 6 | 3/12/2018 | 12/4/2018 |
| 82310 HS - Columbia High Facility | CARPENTRY | Doors | Region 6 | 5/2/2019 | |
| 86911 HS - Columbia High Facility | HVAC | | Region 6 | 25/03/2019 | |
| 90438 HS - Columbia High Facility | GLAZING | Broken Window | Region 6 | 26/04/2019 | 5/1/2019 |
| 92385 HS - Columbia High Facility | HVAC | Miscellaneous | Region 6 | 9/5/2019 | |
| 92426 HS - Columbia High Facility | CARPENTRY | Floors | Region 6 | 9/5/2019 | |
| 92427 HS - Columbia High Facility | CARPENTRY | Structure | Region 6 | 9/5/2019 | |
| 92482 HS - Columbia High Facility | HVAC | Room Too Hot | Region 6 | 10/5/2019 | |
| 92806 HS - Columbia High Facility | PLUMBING | Standing Water | Region 6 | 14/05/2019 | |
| 93171 HS - Columbia High Facility | KITCHEN EQUIPMENT | Doors | Region 6 | 20/05/2019 | |
| 95178 HS - Columbia High Facility | PLUMBING | | Region 6 | 3/6/2019 | 6/8/2019 |
| 95382 HS - Columbia High Facility | HVAC | Room Too Hot | Region 6 | 6/6/2019 | |
| 95389 HS - Columbia High Facility | PLUMBING | Miscellaneous | Region 6 | 6/6/2019 | |
| 95391 HS - Columbia High Facility | PLUMBING | Miscellaneous | Region 6 | 6/6/2019 | |
| 95392 HS - Columbia High Facility | PLUMBING | Miscellaneous | Region 6 | 6/6/2019 | |
| 95393 HS - Columbia High Facility | ROOF | Roof Leak | Region 6 | 6/6/2019 | |
| 95400 HS - Columbia High Facility | ROOF | Roof Leak | Region 6 | 6/6/2019 | |
| 95402 HS - Columbia High Facility | HVAC | Miscellaneous | Region 6 | 6/6/2019 | 6/11/2019 |
| 95405 HS - Columbia High Facility | CARPENTRY | Doors | Region 6 | 6/6/2019 | 6/11/2019 |
| 95406 HS - Columbia High Facility | ROOF | Roof Leak | Region 6 | 6/6/2019 | 6/11/2019 |
| 96245 HS - Columbia High Facility | CARPENTRY | Doors | Region 6 | 19/06/2019 | |
| 98189 HS - Columbia High Facility | HVAC | Room Too Hot | Region 6 | 8/7/2019 | |
| 98276 HS - Columbia High Facility | GROUNDS | Miscellaneous | Region 6 | 8/7/2019 | |
| | | | | | |

| 98277 HS - Columbia High Facility | CARPENTRY | Supplies Needed | Region 6 | 8/7/2019 | |
|--|-------------------|--------------------|----------|------------|----------|
| 98438 HS - Columbia High Facility | CARPENTRY | Room Too Hot | Region 6 | 10/7/2019 | |
| 82903 HS - Dekalb High Facility of Technology, South Cam | PEST CONTROL | Pest | Region 6 | 13/02/2019 | |
| 86914 HS - Dekalb High Facility of Technology, South Cam | HVAC | | Region 6 | 25/03/2019 | |
| 90493 HS - Dekalb High Facility of Technology, South Cam | PLUMBING | Water Leak | Region 6 | 26/04/2019 | 5/1/2019 |
| 91914 HS - Dekalb High Facility of Technology, South Cam | PLUMBING | | Region 6 | 2/5/2019 | 5/7/2019 |
| 93724 HS - Dekalb High Facility of Technology, South Cam | GLAZING | Broken Window | Region 6 | 28/05/2019 | 6/2/2019 |
| 93851 HS - Dekalb High Facility of Technology, South Cam | PLUMBING | Toilet Overflowing | Region 6 | 29/05/2019 | 6/3/2019 |
| 93856 HS - Dekalb High Facility of Technology, South Cam | CARPENTRY | Miscellaneous | Region 6 | 29/05/2019 | |
| 93880 HS - Dekalb High Facility of Technology, South Cam | CARPENTRY | Miscellaneous | Region 6 | 29/05/2019 | |
| 95414 HS - Dekalb High Facility of Technology, South Cam | CARPENTRY | Miscellaneous | Region 6 | 6/6/2019 | |
| 96009 HS - Dekalb High Facility of Technology, South Cam | WAREHOUSE | Move Items | Region 6 | 17/06/2019 | |
| 96181 HS - Dekalb High Facility of Technology, South Cam | CARPENTRY | | Region 6 | 19/06/2019 | |
| 75570 HS - Elizabeth Andrews High Facility | PLUMBING | | Region 6 | 16/11/2018 | |
| 95822 HS - Elizabeth Andrews High Facility | PLUMBING | | Region 6 | 13/06/2019 | |
| 98763 HS - Elizabeth Andrews High Facility | HVAC | Room Too Hot | Region 6 | 15/07/2019 | |
| 98764 HS - Elizabeth Andrews High Facility | HVAC | Room Too Hot | Region 6 | 15/07/2019 | |
| 98765 HS - Elizabeth Andrews High Facility | HVAC | Room Too Hot | Region 6 | 15/07/2019 | |
| 98768 HS - Elizabeth Andrews High Facility | ROOF | Water Leak | Region 6 | 15/07/2019 | |
| 98769 HS - Elizabeth Andrews High Facility | ROOF | Roof Leak | Region 6 | 15/07/2019 | |
| 98771 HS - Elizabeth Andrews High Facility | ROOF | Water Leak | Region 6 | 15/07/2019 | |
| 98815 HS - Elizabeth Andrews High Facility | | Water Leak | Region 6 | 16/07/2019 | |
| 51517 HS - Towers High School Facility | GLAZING | | Region 6 | 27/04/2018 | |
| 62216 HS - Towers High School Facility | ROOF | Roof Leak | Region 6 | 2/8/2018 | 8/3/2018 |
| 74219 HS - Towers High School Facility | CARPENTRY | Doors | Region 6 | 1/11/2018 | |
| 74226 HS - Towers High School Facility | CARPENTRY | Doors | Region 6 | 1/11/2018 | |
| 75717 HS - Towers High School Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 6 | 26/11/2018 | |
| 77326 HS - Towers High School Facility | CARPENTRY | Structure | Region 6 | 11/12/2018 | |
| 82507 HS - Towers High School Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 6 | 7/2/2019 | 2/8/2019 |
| 82515 HS - Towers High School Facility | GLAZING | Broken Window | Region 6 | 7/2/2019 | 2/8/2019 |
| 82518 HS - Towers High School Facility | GLAZING | Broken Window | Region 6 | 7/2/2019 | 2/8/2019 |
| 89377 HS - Towers High School Facility | ROOF | Roof Leak | Region 6 | 15/04/2019 | |
| 89764 HS - Towers High School Facility | ROOF | Roof Leak | Region 6 | 19/04/2019 | |
| 89791 HS - Towers High School Facility | GROUNDS | Broken Plug | Region 6 | 19/04/2019 | |
| 90633 HS - Towers High School Facility | HVAC | Room Too Hot | Region 6 | 29/04/2019 | 5/4/2019 |
| 92350 HS - Towers High School Facility | HVAC | Room Too Hot | Region 6 | 8/5/2019 | |
| 92919 HS - Towers High School Facility | HVAC | Room Too Hot | Region 6 | 16/05/2019 | |
| 94092 HS - Towers High School Facility | PLUMBING | Standing Water | Region 6 | 31/05/2019 | |
| 96209 HS - Towers High School Facility | DELIVERY | Compactor / Trash | Region 6 | 19/06/2019 | |
| 98496 HS - Towers High School Facility | PLUMBING | Water Leak | Region 6 | 11/7/2019 | |
| | | | | | |

| 98510 HS - Towers High School Facility | CARPENTRY | Floors | Region 6 | 11/7/2019 | |
|--|-----------------------------|--------------------|----------|------------|-----------|
| 50828 MS - Columbia Middle Facility | GLAZING | | Region 6 | 18/04/2018 | |
| 60514 MS - Columbia Middle Facility | CARPENTRY | | Region 6 | 26/07/2018 | |
| 62379 MS - Columbia Middle Facility | ROOF | | Region 6 | 3/8/2018 | |
| 63011 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 7/8/2018 | |
| 63364 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 9/8/2018 | |
| 72015 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 17/10/2018 | |
| 72763 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 26/10/2018 | |
| 72765 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 26/10/2018 | |
| 76999 MS - Columbia Middle Facility | PLUMBING | Broken Equipment | Region 6 | 7/12/2018 | |
| 77338 MS - Columbia Middle Facility | CARPENTRY | Doors | Region 6 | 11/12/2018 | |
| 79527 MS - Columbia Middle Facility | GLAZING | Broken Window | Region 6 | 9/1/2019 | 1/10/2019 |
| 83750 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 27/02/2019 | |
| 83753 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 27/02/2019 | |
| 84753 MS - Columbia Middle Facility | WAREHOUSE | Lights Out | Region 6 | 4/3/2019 | 3/5/2019 |
| 86909 MS - Columbia Middle Facility | HVAC | - | Region 6 | 25/03/2019 | |
| 88738 MS - Columbia Middle Facility | KITCHEN EQUIPMENT | | Region 6 | 9/4/2019 | |
| 89821 MS - Columbia Middle Facility | ROOF | Roof Leak | Region 6 | 19/04/2019 | |
| 90040 MS - Columbia Middle Facility | CARPENTRY | Floors | Region 6 | 22/04/2019 | |
| 92110 MS - Columbia Middle Facility | HVAC | Room Too Hot | Region 6 | 6/5/2019 | 5/11/2019 |
| 93915 MS - Columbia Middle Facility | CARPENTRY | Window/Door/Mirror | Region 6 | 30/05/2019 | 6/4/2019 |
| 95138 MS - Columbia Middle Facility | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 3/6/2019 | 6/8/2019 |
| 98445 MS - Columbia Middle Facility | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 10/7/2019 | |
| 98809 MS - Columbia Middle Facility | HVAC | Room Too Hot | Region 6 | 16/07/2019 | |
| 51155 MS - Dekalb International Student Center | CARPENTRY | | Region 6 | 23/04/2018 | |
| 74770 MS - Dekalb International Student Center | GLAZING | Broken Window | Region 6 | 8/11/2018 | |
| 79102 MS - Dekalb International Student Center | ROOF | Roof Leak | Region 6 | 7/1/2019 | |
| 82114 MS - Dekalb International Student Center | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 1/2/2019 | |
| 82386 MS - Dekalb International Student Center | WAREHOUSE | Supplies Needed | Region 6 | 6/2/2019 | |
| 82870 MS - Dekalb International Student Center | ROOF | Ceilings | Region 6 | 12/2/2019 | |
| 85024 MS - Dekalb International Student Center | PLUMBING | Broken Equipment | Region 6 | 6/3/2019 | |
| 88379 MS - Dekalb International Student Center | CARPENTRY | Miscellaneous | Region 6 | 1/4/2019 | |
| 89003 MS - Dekalb International Student Center | PAINTING / PRESSURE WASHING | Paint | Region 6 | 11/4/2019 | |
| 89034 MS - Dekalb International Student Center | CARPENTRY | Miscellaneous | Region 6 | 11/4/2019 | |
| 89754 MS - Dekalb International Student Center | ROOF | Roof Leak | Region 6 | 19/04/2019 | |
| 89757 MS - Dekalb International Student Center | CARPENTRY | Broken Equipment | Region 6 | 19/04/2019 | |
| 89996 MS - Dekalb International Student Center | CARPENTRY | Miscellaneous | Region 6 | 22/04/2019 | |
| 89998 MS - Dekalb International Student Center | CARPENTRY | Broken Equipment | Region 6 | 22/04/2019 | |
| 92777 MS - Dekalb International Student Center | CARPENTRY | Doors | Region 6 | 14/05/2019 | |
| 92778 MS - Dekalb International Student Center | CARPENTRY | Floors | Region 6 | 14/05/2019 | |
| | | | | | |

| 93142 MS - Dekalb International Student Center | GROUNDS | | Region 6 | 20/05/2019 | |
|--|-------------------|-------------------|----------|------------|-----------|
| 93887 MS - Dekalb International Student Center | ROOF | Roof Leak | Region 6 | 29/05/2019 | |
| 94085 MS - Dekalb International Student Center | CARPENTRY | Floors | Region 6 | 31/05/2019 | 6/5/2019 |
| 95139 MS - Dekalb International Student Center | CARPENTRY | Floors | Region 6 | 3/6/2019 | |
| 95792 MS - Dekalb International Student Center | CARPENTRY | Doors | Region 6 | 12/6/2019 | |
| 95793 MS - Dekalb International Student Center | GROUNDS | Miscellaneous | Region 6 | 12/6/2019 | |
| 95855 MS - Dekalb International Student Center | GROUNDS | Structure | Region 6 | 13/06/2019 | |
| 96325 MS - Dekalb International Student Center | WASTE MANAGEMENT | Compactor / Trash | Region 6 | 20/06/2019 | |
| 96488 MS - Dekalb International Student Center | DELIVERY | Supplies Needed | Region 6 | 24/06/2019 | |
| 96491 MS - Dekalb International Student Center | CARPENTRY | Doors | Region 6 | 24/06/2019 | |
| 96750 MS - Dekalb International Student Center | PLUMBING | | Region 6 | 27/06/2019 | |
| 97991 MS - Dekalb International Student Center | FIRE SAFETY | Fire Alarm | Region 6 | 3/7/2019 | 7/8/2019 |
| 98323 MS - Dekalb International Student Center | ELECTRICAL | Broken Plug | Region 6 | 9/7/2019 | |
| 98350 MS - Dekalb International Student Center | CARPENTRY | Supplies Needed | Region 6 | 9/7/2019 | |
| 98685 MS - Dekalb International Student Center | FIRE SAFETY | Fire Alarm | Region 6 | 15/07/2019 | |
| 57646 MS - Mary McLeod Bethune Middle Facility | GLAZING | | Region 6 | 18/06/2018 | |
| 57649 MS - Mary McLeod Bethune Middle Facility | CARPENTRY | | Region 6 | 18/06/2018 | |
| 64959 MS - Mary McLeod Bethune Middle Facility | GLAZING | Broken Window | Region 6 | 23/08/2018 | |
| 71466 MS - Mary McLeod Bethune Middle Facility | ROOF | Roof Leak | Region 6 | 10/10/2018 | |
| 71602 MS - Mary McLeod Bethune Middle Facility | ROOF | Roof Leak | Region 6 | 11/10/2018 | |
| 72808 MS - Mary McLeod Bethune Middle Facility | ROOF | Roof Leak | Region 6 | 29/10/2018 | |
| 74783 MS - Mary McLeod Bethune Middle Facility | GLAZING | Broken Window | Region 6 | 8/11/2018 | |
| 77370 MS - Mary McLeod Bethune Middle Facility | CARPENTRY | Ceilings | Region 6 | 12/12/2018 | |
| 79031 MS - Mary McLeod Bethune Middle Facility | CARPENTRY | Ceilings | Region 6 | 4/1/2019 | |
| 79323 MS - Mary McLeod Bethune Middle Facility | WAREHOUSE | | Region 6 | 8/1/2019 | |
| 86910 MS - Mary McLeod Bethune Middle Facility | HVAC | | Region 6 | 25/03/2019 | |
| 88739 MS - Mary McLeod Bethune Middle Facility | KITCHEN EQUIPMENT | | Region 6 | 9/4/2019 | |
| 89987 MS - Mary McLeod Bethune Middle Facility | CARPENTRY | Doors | Region 6 | 22/04/2019 | |
| 89990 MS - Mary McLeod Bethune Middle Facility | ROOF | Roof Leak | Region 6 | 22/04/2019 | |
| 92422 MS - Mary McLeod Bethune Middle Facility | HVAC | Room Too Hot | Region 6 | 9/5/2019 | |
| 93218 MS - Mary McLeod Bethune Middle Facility | HVAC | Room Too Hot | Region 6 | 20/05/2019 | |
| 93410 MS - Mary McLeod Bethune Middle Facility | HVAC | Room Too Hot | Region 6 | 22/05/2019 | |
| 93413 MS - Mary McLeod Bethune Middle Facility | CARPENTRY | Locks / Keys | Region 6 | 22/05/2019 | |
| 93460 MS - Mary McLeod Bethune Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 6 | 23/05/2019 | |
| 95371 MS - Mary McLeod Bethune Middle Facility | ROOF | Roof Leak | Region 6 | 6/6/2019 | 6/11/2019 |
| 96055 MS - Mary McLeod Bethune Middle Facility | PLUMBING | Faucet Dripping | Region 6 | 17/06/2019 | |
| 96108 MS - Mary McLeod Bethune Middle Facility | HVAC | Room Too Hot | Region 6 | 18/06/2019 | |
| 96257 MS - Mary McLeod Bethune Middle Facility | ELECTRICAL | | Region 6 | 19/06/2019 | |
| 98242 MS - Mary McLeod Bethune Middle Facility | CARPENTRY | Floors | Region 6 | 8/7/2019 | |
| 90619 AC - Ronald E McNair | HVAC | Room Too Hot | Region 7 | 29/04/2019 | 5/4/2019 |
| | | | | | |

| 93238 AC - Ronald E McNair | HVAC | Water Leak | Region 7 | 20/05/2019 | |
|--|-----------------------------|-------------------|----------|------------|-----------|
| 95111 AC - Ronald E McNair | INSPECTION | Miscellaneous | Region 7 | 3/6/2019 | 6/3/2019 |
| 95712 AC - Ronald E McNair | HOUSEKEEPING | Miscellaneous | Region 7 | 11/6/2019 | |
| 98011 AC - Ronald E McNair | PLUMBING | Clogged Drain | Region 7 | 3/7/2019 | |
| 98182 AC - Ronald E McNair | PLUMBING | Miscellaneous | Region 7 | 8/7/2019 | |
| 98819 AC - Ronald E McNair | | Locks / Keys | Region 7 | 16/07/2019 | |
| 98395 AF - Avondale Stadium | ELECTRICAL | , , . | Region 7 | 10/7/2019 | |
| 98396 AF - Avondale Stadium | ELECTRICAL | | Region 7 | 10/7/2019 | |
| 98469 AF - William Buck Godfrey Stadium | GROUNDS | | Region 7 | 10/7/2019 | |
| 67988 EO - Early Learning Center/Former Terry Mill | PAINTING / PRESSURE WASHING | Pressure Washing | Region 7 | 6/9/2018 | |
| 79960 EO - Early Learning Center/Former Terry Mill | ROOF | Water Leak | Region 7 | 15/01/2019 | |
| 87251 EO - Early Learning Center/Former Terry Mill | KITCHEN EQUIPMENT | Freezer / Cooler | Region 7 | 28/03/2019 | |
| 89104 EO - Early Learning Center/Former Terry Mill | KITCHEN EQUIPMENT | Freezer / Cooler | Region 7 | 12/4/2019 | |
| 92770 EO - Early Learning Center/Former Terry Mill | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 14/05/2019 | |
| 96025 EO - Early Learning Center/Former Terry Mill | KITCHEN EQUIPMENT | , , | Region 7 | 17/06/2019 | |
| 96149 EO - Early Learning Center/Former Terry Mill | ELECTRICAL | Lights Out | Region 7 | 18/06/2019 | |
| 96150 EO - Early Learning Center/Former Terry Mill | CARPENTRY | Doors | Region 7 | 18/06/2019 | |
| 96557 EO - Early Learning Center/Former Terry Mill | CARPENTRY | Doors | Region 7 | 24/06/2019 | |
| 88696 ES - Barak H. Obama Elementary Magnet School of Te | ROOF | Roof Leak | Region 7 | 9/4/2019 | |
| 89181 ES - Barak H. Obama Elementary Magnet School of Te | KITCHEN EQUIPMENT | Freezer / Cooler | Region 7 | 12/4/2019 | |
| 89752 ES - Barak H. Obama Elementary Magnet School of Te | ROOF | Water Leak | Region 7 | 19/04/2019 | |
| 90100 ES - Barak H. Obama Elementary Magnet School of Te | ROOF | Roof Leak | Region 7 | 23/04/2019 | |
| 90103 ES - Barak H. Obama Elementary Magnet School of Te | ROOF | Roof Leak | Region 7 | 23/04/2019 | |
| 98322 ES - Barak H. Obama Elementary Magnet School of Te | ROOF | Roof Leak | Region 7 | 9/7/2019 | |
| 98464 ES - Barak H. Obama Elementary Magnet School of Te | PLUMBING | Water Leak | Region 7 | 10/7/2019 | |
| 74428 ES - Cedar Grove Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 7 | 5/11/2018 | 1/10/2019 |
| 80139 ES - Cedar Grove Elementary Facility | ELECTRICAL | Broken Equipment | Region 7 | 17/01/2019 | |
| 95158 ES - Cedar Grove Elementary Facility | CARPENTRY | Miscellaneous | Region 7 | 3/6/2019 | 6/8/2019 |
| 96505 ES - Cedar Grove Elementary Facility | CARPENTRY | Floors | Region 7 | 24/06/2019 | |
| 86084 ES - DeKalb Elem. School Of Arts | GROUNDS | Miscellaneous | Region 7 | 19/03/2019 | |
| 86884 ES - DeKalb Elem. School Of Arts | ROOF | Roof Leak | Region 7 | 25/03/2019 | |
| 92719 ES - DeKalb Elem. School Of Arts | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 13/05/2019 | |
| 93165 ES - DeKalb Elem. School Of Arts | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 20/05/2019 | |
| 93473 ES - DeKalb Elem. School Of Arts | KITCHEN EQUIPMENT | Steamer / Warmer | Region 7 | 23/05/2019 | |
| 93474 ES - DeKalb Elem. School Of Arts | KITCHEN EQUIPMENT | Stove / Oven | Region 7 | 23/05/2019 | |
| 93488 ES - DeKalb Elem. School Of Arts | KITCHEN EQUIPMENT | Miscellaneous | Region 7 | 23/05/2019 | |
| 93721 ES - DeKalb Elem. School Of Arts | CARPENTRY | Doors | Region 7 | 28/05/2019 | |
| 93940 ES - DeKalb Elem. School Of Arts | ELECTRONICS | Broken Equipment | Region 7 | 30/05/2019 | 6/4/2019 |
| 96737 ES - DeKalb Elem. School Of Arts | FIRE SAFETY | Fire Alarm | Region 7 | 27/06/2019 | 7/5/2019 |
| 98346 ES - DeKalb Elem. School Of Arts | PLUMBING | | Region 7 | 9/7/2019 | |
| | | | | | |

| 98375 ES - DeKalb Elem. School Of Arts | HVAC | Room Too Hot | Region 7 | 9/7/2019 | |
|--|-----------------------------|-------------------|----------|------------|-----------|
| 98418 ES - DeKalb Elem. School Of Arts | PAINTING / PRESSURE WASHING | Paint | Region 7 | 10/7/2019 | |
| 98420 ES - DeKalb Elem. School Of Arts | EQUIPMENT REPAIR | Broken Equipment | Region 7 | 10/7/2019 | |
| 70839 ES - Flat Shoals Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 7 | 2/10/2018 | |
| 71724 ES - Flat Shoals Elementary Facility | GLAZING | Broken Window | Region 7 | 12/10/2018 | |
| 88988 ES - Flat Shoals Elementary Facility | HOUSEKEEPING | Supplies Needed | Region 7 | 11/4/2019 | |
| 90472 ES - Flat Shoals Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 26/04/2019 | 5/1/2019 |
| 90664 ES - Flat Shoals Elementary Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 7 | 29/04/2019 | |
| 90703 ES - Flat Shoals Elementary Facility | HVAC | Room Too Hot | Region 7 | 30/04/2019 | 5/5/2019 |
| 91923 ES - Flat Shoals Elementary Facility | CARPENTRY | | Region 7 | 2/5/2019 | 5/7/2019 |
| 92881 ES - Flat Shoals Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 15/05/2019 | |
| 92892 ES - Flat Shoals Elementary Facility | HVAC | Room Too Hot | Region 7 | 15/05/2019 | |
| 93833 ES - Flat Shoals Elementary Facility | CARPENTRY | Miscellaneous | Region 7 | 29/05/2019 | |
| 93835 ES - Flat Shoals Elementary Facility | CARPENTRY | Miscellaneous | Region 7 | 29/05/2019 | 6/3/2019 |
| 93920 ES - Flat Shoals Elementary Facility | HVAC | Room Too Hot | Region 7 | 30/05/2019 | 6/7/2019 |
| 93922 ES - Flat Shoals Elementary Facility | FIRE SAFETY | Doors | Region 7 | 30/05/2019 | 6/4/2019 |
| 96227 ES - Flat Shoals Elementary Facility | CARPENTRY | Floors | Region 7 | 19/06/2019 | |
| 96620 ES - Flat Shoals Elementary Facility | CARPENTRY | Decking | Region 7 | 25/06/2019 | |
| 96621 ES - Flat Shoals Elementary Facility | CARPENTRY | Ceilings | Region 7 | 25/06/2019 | 7/12/2019 |
| 97898 ES - Flat Shoals Elementary Facility | CARPENTRY | Ceilings | Region 7 | 1/7/2019 | 7/6/2019 |
| 98001 ES - Flat Shoals Elementary Facility | FIRE SAFETY | Alarm Systems | Region 7 | 3/7/2019 | 7/8/2019 |
| 98401 ES - Flat Shoals Elementary Facility | ROOF | Roof Leak | Region 7 | 10/7/2019 | |
| 98499 ES - Flat Shoals Elementary Facility | GROUNDS | Broken Plug | Region 7 | 11/7/2019 | |
| 98791 ES - Flat Shoals Elementary Facility | ELECTRICAL | | Region 7 | 16/07/2019 | |
| 98807 ES - Flat Shoals Elementary Facility | ELECTRICAL | No Power | Region 7 | 16/07/2019 | |
| 98808 ES - Flat Shoals Elementary Facility | GROUNDS | Miscellaneous | Region 7 | 16/07/2019 | |
| 68177 ES - Kelley Lake Elementary Facility | PLUMBING | | Region 7 | 10/9/2018 | |
| 94084 ES - Kelley Lake Elementary Facility | CARPENTRY | Miscellaneous | Region 7 | 31/05/2019 | |
| 96256 ES - Kelley Lake Elementary Facility | CARPENTRY | Floors | Region 7 | 19/06/2019 | |
| 96259 ES - Kelley Lake Elementary Facility | CARPENTRY | Floors | Region 7 | 19/06/2019 | |
| 96282 ES - Kelley Lake Elementary Facility | CARPENTRY | Floors | Region 7 | 19/06/2019 | 7/12/2019 |
| 97865 ES - Kelley Lake Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 1/7/2019 | 7/6/2019 |
| 98324 ES - Kelley Lake Elementary Facility | ELECTRICAL | Lights Out | Region 7 | 9/7/2019 | |
| 98348 ES - Kelley Lake Elementary Facility | LOCKSMITH | Locks / Keys | Region 7 | 9/7/2019 | |
| 98349 ES - Kelley Lake Elementary Facility | ELECTRICAL | No Power | Region 7 | 9/7/2019 | |
| 98379 ES - Kelley Lake Elementary Facility | ELECTRICAL | | Region 7 | 9/7/2019 | |
| 98424 ES - Kelley Lake Elementary Facility | HVAC | Water Leak | Region 7 | 10/7/2019 | |
| 98425 ES - Kelley Lake Elementary Facility | HVAC | Room Too Hot | Region 7 | 10/7/2019 | |
| 98426 ES - Kelley Lake Elementary Facility | PAINTING / PRESSURE WASHING | Paint | Region 7 | 10/7/2019 | |
| 98427 ES - Kelley Lake Elementary Facility | CARPENTRY | Miscellaneous | Region 7 | 10/7/2019 | |
| | | | | | |

| 00420 FG Kalla Lala Flavorator Facility | CARRENTOV | National Harmonia | 5 | 40/7/2040 | |
|---|-----------------------------|-------------------|----------|----------------|------------|
| 98429 ES - Kelley Lake Elementary Facility | CARPENTRY | Miscellaneous | Region 7 | 10/7/2019 | |
| 98511 ES - Kelley Lake Elementary Facility | HVAC | Water Leak | Region 7 | 11/7/2019 | |
| 98852 ES - Kelley Lake Elementary Facility | PEST CONTROL | Pest | Region 7 | 16/07/2019 | |
| 75304 ES - Narvie Harris Elementary Facility | ROOF | Roof Leak | Region 7 | 14/11/2018 | |
| 93334 ES - Narvie Harris Elementary Facility | GLAZING | Broken Equipment | Region 7 | 21/05/2019 | |
| 97859 ES - Narvie Harris Elementary Facility | WASTE MANAGEMENT | Compactor / Trash | Region 7 | 1/7/2019 | 7/6/2019 |
| 98729 ES - Narvie Harris Elementary Facility | HVAC | Room Too Hot | Region 7 | 15/07/2019 | |
| 98849 ES - Narvie Harris Elementary Facility | PLUMBING | Miscellaneous | Region 7 | 16/07/2019 | |
| 56588 ES - Oakview Elementary Facility | ROOF | | Region 7 | 1/6/2018 | |
| 60075 ES - Oakview Elementary Facility | ROOF | | Region 7 | 19/07/2018 | |
| 63190 ES - Oakview Elementary Facility | ROOF | Ceilings | Region 7 | 8/8/2018 | |
| 63202 ES - Oakview Elementary Facility | ROOF | Roof Leak | Region 7 | 8/8/2018 | |
| 69812 ES - Oakview Elementary Facility | ROOF | Water Leak | Region 7 | 28/09/2018 | |
| 84768 ES - Oakview Elementary Facility | ROOF | Roof Leak | Region 7 | 4/3/2019 | |
| 87102 ES - Oakview Elementary Facility | ROOF | Roof Leak | Region 7 | 26/03/2019 | |
| 92164 ES - Oakview Elementary Facility | FIRE SAFETY | | Region 7 | 6/5/2019 | 5/11/2019 |
| 86878 ES - Robert Shaw Theme Facility | CARPENTRY | | Region 7 | 25/03/2019 | |
| 92836 ES - Robert Shaw Theme Facility | CARPENTRY | Freezer / Cooler | Region 7 | 15/05/2019 | |
| 95411 ES - Robert Shaw Theme Facility | PAINTING / PRESSURE WASHING | Paint | Region 7 | 6/6/2019 | |
| 98691 ES - Robert Shaw Theme Facility | PAINTING / PRESSURE WASHING | | Region 7 | 15/07/2019 | |
| 75075 HS - Avondale High DSA | ROOF | Roof Leak | Region 7 | 12/11/2018 | |
| 89748 HS - Avondale High DSA | ROOF | Roof Leak | Region 7 | 19/04/2019 | |
| 89776 HS - Avondale High DSA | ROOF | Roof Leak | Region 7 | 19/04/2019 | |
| 93938 HS - Avondale High DSA | GROUNDS | Miscellaneous | Region 7 | 30/05/2019 | |
| 95288 HS - Avondale High DSA | HVAC | Room Too Hot | Region 7 | 5/6/2019 | 6/10/2019 |
| 95666 HS - Avondale High DSA | ELECTRICAL | | Region 7 | 11/6/2019 | |
| 95772 HS - Avondale High DSA | HVAC | | Region 7 | 12/6/2019 | |
| 95982 HS - Avondale High DSA | HVAC | Room Too Hot | Region 7 | 17/06/2019 | |
| 96117 HS - Avondale High DSA | GROUNDS | Paint | Region 7 | 18/06/2019 | |
| 96473 HS - Avondale High DSA | HVAC | | Region 7 | 24/06/2019 | |
| 97993 HS - Avondale High DSA | FIRE SAFETY | Fire Alarm | Region 7 | 3/7/2019 | 7/8/2019 |
| 62167 HS - Cedar Grove High Facility | CARPENTRY | Miscellaneous | Region 7 | 1/8/2018 | 8/2/2018 |
| 62309 HS - Cedar Grove High Facility | ROOF | | Region 7 | 2/8/2018 | |
| 75494 HS - Cedar Grove High Facility | ROOF | Roof Leak | Region 7 | 16/11/2018 | |
| 77564 HS - Cedar Grove High Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 7 | 14/12/2018 | |
| 85046 HS - Cedar Grove High Facility | PLUMBING | Water Leak | Region 7 | 6/3/2019 | 3/7/2019 |
| 85637 HS - Cedar Grove High Facility | ELECTRICAL | Miscellaneous | Region 7 | 13/03/2019 | |
| 89438 HS - Cedar Grove High Facility | KITCHEN EQUIPMENT | Miscellaneous | Region 7 | 16/04/2019 | |
| 95999 HS - Cedar Grove High Facility | PEST CONTROL | Pest | Region 7 | 17/06/2019 | |
| 97879 HS - Cedar Grove High Facility | CARPENTRY | Miscellaneous | Region 7 | 1/7/2019 | 7/6/2019 |
| | | | | _, , , _ 0 _ 0 | ., -, =0=0 |

| 98740 HS - Cedar Grove High Facility | FIRE SAFETY | Fire Alarm | Region 7 | 15/07/2019 | |
|--|-----------------------------|----------------------|----------|------------|-----------|
| 98774 HS - Cedar Grove High Facility | PLUMBING | Miscellaneous | Region 7 | 15/07/2019 | |
| 60502 HS - McNair High Facility | ROOF | | Region 7 | 26/07/2018 | |
| 60590 HS - McNair High Facility | PAINTING / PRESSURE WASHING | Pressure Washing | Region 7 | 26/07/2018 | |
| 71527 HS - McNair High Facility | ROOF | Roof Leak | Region 7 | 11/10/2018 | |
| 74987 HS - McNair High Facility | ROOF | Water Leak | Region 7 | 12/11/2018 | |
| 77987 HS - McNair High Facility | CARPENTRY | Miscellaneous | Region 7 | 21/12/2018 | |
| 78032 HS - McNair High Facility | PLUMBING | Standing Water | Region 7 | 30/12/2018 | |
| 83453 HS - McNair High Facility | CARPENTRY | Doors | Region 7 | 22/02/2019 | |
| 83476 HS - McNair High Facility | CARPENTRY | Miscellaneous | Region 7 | 22/02/2019 | |
| 85962 HS - McNair High Facility | WAREHOUSE | | Region 7 | 18/03/2019 | |
| 92127 HS - McNair High Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 7 | 6/5/2019 | 5/11/2019 |
| 93869 HS - McNair High Facility | CARPENTRY | Floors | Region 7 | 29/05/2019 | |
| 93932 HS - McNair High Facility | CARPENTRY | Locks / Keys | Region 7 | 30/05/2019 | |
| 95795 HS - McNair High Facility | GLAZING | Broken Window | Region 7 | 12/6/2019 | |
| 95796 HS - McNair High Facility | KITCHEN EQUIPMENT | Pressure Washing | Region 7 | 12/6/2019 | |
| 96064 HS - McNair High Facility | CARPENTRY | Floors | Region 7 | 17/06/2019 | |
| 96065 HS - McNair High Facility | CARPENTRY | Doors | Region 7 | 17/06/2019 | |
| 96548 HS - McNair High Facility | CARPENTRY | Miscellaneous | Region 7 | 24/06/2019 | 7/12/2019 |
| 96549 HS - McNair High Facility | CARPENTRY | Floors | Region 7 | 24/06/2019 | 7/12/2019 |
| 96584 HS - McNair High Facility | PLUMBING | Faucet Dripping | Region 7 | 25/06/2019 | |
| 96585 HS - McNair High Facility | ELECTRICAL | Lights Out | Region 7 | 25/06/2019 | 7/12/2019 |
| 98230 HS - McNair High Facility | CARPENTRY | Doors | Region 7 | 8/7/2019 | |
| 98331 HS - McNair High Facility | CARPENTRY | Miscellaneous | Region 7 | 9/7/2019 | |
| 98360 HS - McNair High Facility | CARPENTRY | Ceilings | Region 7 | 9/7/2019 | |
| 98416 HS - McNair High Facility | CARPENTRY | Doors | Region 7 | 10/7/2019 | |
| 98417 HS - McNair High Facility | LOCKSMITH | Locks / Keys | Region 7 | 10/7/2019 | |
| 98484 HS - McNair High Facility | ROOF | Roof Leak | Region 7 | 11/7/2019 | |
| 98505 HS - McNair High Facility | CARPENTRY | Miscellaneous | Region 7 | 11/7/2019 | |
| 59896 MS - Cedar Grove Middle Facility | PLUMBING | Water Leak | Region 7 | 18/07/2018 | |
| 73132 MS - Cedar Grove Middle Facility | GLAZING | Miscellaneous | Region 7 | 31/10/2018 | |
| 76610 MS - Cedar Grove Middle Facility | ELECTRICAL | Miscellaneous | Region 7 | 4/12/2018 | |
| 85016 MS - Cedar Grove Middle Facility | CARPENTRY | Miscellaneous | Region 7 | 6/3/2019 | |
| 85117 MS - Cedar Grove Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 7 | 7/3/2019 | |
| 85657 MS - Cedar Grove Middle Facility | CARPENTRY | Ceilings | Region 7 | 13/03/2019 | |
| 86423 MS - Cedar Grove Middle Facility | KITCHEN EQUIPMENT | Freezer / Cooler | Region 7 | 22/03/2019 | |
| 90427 MS - Cedar Grove Middle Facility | HVAC | | Region 7 | 26/04/2019 | 5/1/2019 |
| 90784 MS - Cedar Grove Middle Facility | HVAC | | Region 7 | 30/04/2019 | 5/5/2019 |
| 91845 MS - Cedar Grove Middle Facility | HVAC | | Region 7 | 2/5/2019 | 5/7/2019 |
| 92465 MS - Cedar Grove Middle Facility | ELECTRONICS | Clocks | Region 7 | 10/5/2019 | |
| | | | | | |

| 92510 MS - Cedar Grove Middle Facility | MECHANICAL EQUIPMENT | Miscellaneous | Region 7 | 10/5/2019 | |
|--|----------------------|------------------|----------|------------|-----------|
| 92718 MS - Cedar Grove Middle Facility | FIRE SAFETY | Fire Alarm | Region 7 | 13/05/2019 | |
| 93246 MS - Cedar Grove Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 7 | 21/05/2019 | |
| 93528 MS - Cedar Grove Middle Facility | KITCHEN EQUIPMENT | Broken Equipment | Region 7 | 24/05/2019 | |
| 95992 MS - Cedar Grove Middle Facility | FIRE SAFETY | | Region 7 | 17/06/2019 | |
| 96269 MS - Cedar Grove Middle Facility | EQUIPMENT REPAIR | Broken Equipment | Region 7 | 19/06/2019 | |
| 96279 MS - Cedar Grove Middle Facility | PLUMBING | Water Leak | Region 7 | 19/06/2019 | 7/12/2019 |
| 98065 MS - Cedar Grove Middle Facility | CARPENTRY | Miscellaneous | Region 7 | 5/7/2019 | 7/10/2019 |
| 98850 MS - McNair Middle Facility | | Miscellaneous | Region 7 | 16/07/2019 | |
| M-57964 MS - McNair Middle Facility | GLAZING | | Region 7 | 21/06/2018 | |
| 70762 CO - DeKalb County Schools System Wide | FIRE SAFETY | | | 1/10/2018 | |
| 98688 | GROUNDS | | | 15/07/2019 | |